



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No.F6/DFS/MS/School/SZ/2025/107

Dated: 14/02/2025

To

The Principal,  
M/s Hill View Public School,  
337/1, Master Colony, Tughlakabad Village,  
New Delhi-44.

**Sub:-** Regarding issuance of Fire Safety Certificate in respect of M/s Hill View Public School located at 337/1, Master Colony, Tughlakabad Village, New Delhi-44.

Sir,

With reference to letter bearing email dated 26.10.2024 on the subject cited above, it is informed that the said building was earlier comprised of Ground + 01 upper floor. The premises was re-inspected by Assistant Divisional Officer (M. Road) from this department on 11.02.2025 in the presence of Mr. Sunil (Owner) and it was observed that the building is comprised of Two blocks: Ground (School) + 1 upper floor (Care taker residence), Ground + 2 upper floors (School at all floors). This may be treated as case of addition/alternation. During the inspection following shortcoming were observed:-

1. School is not accessible to fire engine.
2. Corridor having 1.50 meters width has not been provided in G+2 block.
3. Staircase of 1.50 meters width has not been provided in G+2 block.
4. First aid hose reels has not been provided.
5. Fire pump having capacity 450 LPM with 40 m head has not been provided.
6. Terrace water tank of 10,000 liters (Exclusively for firefighting) has not been provided.
7. Exit signages has not been provided.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)

Director

Delhi Fire Service

11/2/25. e

**Copy to:-**

The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.