Vimpul CD

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

Dated: 310312025

Director

No. F6/DFS/MS/GH/SZ/2025/ 151-

FIRE SAFETY CERTIFICATE

Certified that Hotel Good Luck, located at A-103, Road No-4, Mahipalpur Extn, New Delhi-110037, in a building comprised of Basement (Hall), Ground (Reception & Officer), 1st Floor (Office), 2nd Floor (09 Guest Rooms), 3rd Floor (09 Guest rooms), (Total 18 Guest Rooms), owned/occupied by Hotel Good Luck, was issued FSC vide letter no. F6/DFS/MS/GH/2022/SZ/57 dated 25/01/2022. The building/premises was re-inspected by the officer concerned of this department on 10/03/2025 in the presence of Sh. Ishawar Singh and found that the said guest house building found in good working condition & that the premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential" Sub Division A-1 Group-A, (Guest House with 18 Guest rooms only), validity upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

Issued on 31032025 at New Delhi by.

Copy to:-

1. The Commissioner, MCD, Civic Centre, New Delhi. To ensure the occupancy as Detailed above. ID No. 2025021001671 dated 25/02/2025.

2. The Joint C.P. (Lic.), Police Station, Defence Colony, 1st floor, New Delhi. Email Id:(addlcp.lic-dl@nic.in)

3. The owner/occupier The Corner Point, located at 8210A, Multani Dhanda, Paharganj, New Delhi- 110055.

Conditions for the Validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the risk and responsibility of managements.
- 3. Any deviation, with regards to construction shall be verified by the concerned building sanctioning agencies.
- 4. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 6. All comments / directions of licensing department shall always be permitted and followed.
- 7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.
- 9. Basement shall be used as incidental storage of guest house items.



	As II	NSPECTION REPOR	<u>RT</u>				
1.	Name & address of the building	Hotel Good Luck, locate at A-103, Road No-4, Mahipalp					
		Extn, New Delhi- 11	0037.				
2.	Type of Occupancy	Residential, Sub Division A-1 (Guest House)					
3.	Type of Case	Renewal					
4.	Details of previous NOC	F6/DFS/MS/GH/2022	2/SZ/57 dated 25/01/2022				
5.	Fire Safety directives letter No	Nil					
6.	Date of inspection	10/03/2025					
7.	Name of the Inspecting Officers	Sarabjeet Singh ADO	(MN)				
8.	Name and designation of officers	Sh. Ishawar Singh					
	from the building side	which only					
9.	Year of Construction	2005 (As per MHA P	Portal)				
10.	Applicant's letter No.		o.2025021001671 dated 2	5/02/2025			
The	Guest house building comprise						
(inci	idental storage related to guest ho	use items). Ground F	floor (Reception & Offic	cer), 1st Floo			
(Off	ice), 2 nd Floor (09 Guest Rooms), 3 ^r	d Floor (09 Guest root	ms), (Total 18 Guest Roo	ms).			
S.	Minimum Standards on fire	Required as per	Provided at site	Remarks			
No.	prevention and fire safety U/R 33	Rule 35(6) of DFS	pogli i pi Piti i	MR/NMR			
		Rule 2010					
1	Access to building	A STATE OF ASSESSED TO STATE OF THE STATE OF					
	Road width	Required	06 mtr	MR			
	Gate width	Required	Accessable from road	MR.			
	Width of internal road	NA NA	NA	NA			
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	Required	02 nos.	MR			
	Basements	Required	02 nos.	MR			
	b. Width of staircases		Account of the second				
	Upper Floors	1.25 m each	1.25 m & 1.06 m	MR old case			
	Basements	1.25 m each	1.60 m & 1.25 m (iron)	NA			
	c. Protection of exits	4					
	Fire check door	Required	Provided	MR			
	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrac	e Two	Provided	MR			
	e. Width of Corridor	1.25 m	Provided	MR			
	f. Door Size	01 mtr	1.8 mtr (Final exit)	MR			
3	Compartmentation.						
	Fire check door	NA	NA	NA			
	 Sealing of electrical shafts 	Required	Provided	MR			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
1	Smoke Management System.						
	Basements	Required	Exhaust fan Provided	MR			
	 Upper floors 	Required	Natural ventilation	MR			
5	Fire Extinguishers						
	Total numbers	10 nos.	14 Provided	MR			
	• Types	CO ₂ , ABC type	Provided	MR			
	TOleine	ISI marked	Provided	MR			
	IS marking			7			
6	First-Aid Hose Reels.	1					
6	First-Aid Hose Reels. Total numbers on each floor	01	Provided	MR			
6	First-Aid Hose Reels.	01 30 mtr 5 mm	Provided Provided Provided	MR MR			

8 9 10	Automatic fire detection and alarmin Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer Number of hydrants per floor	Required (CO) Required NA Required Required Required NA Required NA NA NA NA	Provided NA Provided Provided Provided Provided NA Provided NA NA NA	MR NA MR NA MR NA NA NA
9	Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	Required NA Required Required NA Required NA Required NA NA	NA Provided Provided NA Provided NA	NA MR MR MR NA
9	Location of Repeater Panel Alternate source of power Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	NA Required Required NA Required NA Required NA NA	Provided Provided NA Provided NA	MR MR MR NA
9 10	Alternate source of power Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	Required Required NA Required NA NA NA	Provided NA Provided NA NA	MR MR NA MR NA
9 10	Hooters' Location MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	Required Required NA Required NA NA NA	Provided NA Provided NA	MR NA MR NA
9 10	MOEFA Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	NA Required NA NA	NA Provided NA	NA MR NA
9 10	Public Address System. Automatic Sprinkler System. Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	Required NA NA	Provided NA	MR NA
	Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	NA NA	NA	NA
	Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	NA NA	NA	NA
11	Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	NA NA	NA	
11	Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer	NA	(20.18) Mr.	
11	Internal Hydrants • Size of riser/down-comer		NA	1111
11	Size of riser/down-comer			
		RIA .	(<u>1</u> 2.12.10.	
	Number of hydrants per floor	NA NA	NA	NA
- 1		NA NA	NA	NA
	Hose Box	NA	NA	NA
12	Yard Hydrants.			
	Total number of hydrants	NA	NA	NA
	Hose Box	NA	NA	NA
13	Pumping Arrangements.			
	Ground Level			
	Discharge of main Pump	NA	NA	NA
	Head of Main pump	NA	NA	NA
	Number of main pumps	NA	NA	NA
	Jockey Pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump out put	- NA	NA	NA
- 1	> Standby Pump Head	NA	NA	NA
	> Auto Starting/ Manual stopping	NA	NA	NA
	➢ Pump House Access	NA	NA	NA
	Terrace level			
	Discharge of pump	900 LPM	Provided	MR
	➤ Head of the pump	35 m	Provided	MR
	➤ Power Supply	Required	Provided	MR
41	➤ Auto Starting of pump	Required	Provided	MR
4 (Captive Water Storage for fire fighting	3		
	Underground tank capacity	NA	NA	NA
4	> Draw-off connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	> Access to tank	NA	NA	NA
	Overhead Tank capacity	10,000 ltrs	Provided	MR
5 E	Exit Signage.	Required	Provided	MR
P	rovision of Lifts.		W 4. 1	87 85
	Pressurization of Lift Shaft	Required	Provided	MR
	Pressurization of Lift lobby	NA	NA	NA
	Communication In lift Car	Required	Provided	MR
		Required	Provided	MR
	Fireman's Grounding Switch Lift Signage	Required	Provided	MR

17	Standby power supply	517				
11		Required	Provided (DG Set)	MR		
18						
	> Total Area	NA	NA	NA		
	> Location	NA	NA	NA		
19	Fire Control Room					
	Detector System Panel	NA	NA NA	NA		
	Flow Switch Panel	NA	NA	NA		
	PA System Panel	NA	NA	NA		
	Battery backup	NA	NA	NA		
	Building Floor Plans	NA	NA	NA		
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA *	NA		

The fire protection systems provided in the building were checked & found functional at the time of inspection. Earlier all the shortcomings issued by this department have been complied by the management of Guest House.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010 is recommended.

93 ADD MN

It. clarify regarding shortcomings Leves 24/1/16.

AND Southfeet

All shortleng's daked 24/1/25 hours been completed now. gres ub method pls. 1

[3/2/215]