

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F.6/DFS/MS/School/NDZ/2025/ 191

Dated: 04 / 04 /2025

To

The Principal,
Jai Bharat School,
Chawri Bazar, Delhi-110006.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o Jai Bharat School, Chawri Bazar, Delhi -110006.

Sir,

This has reference to letter no. nil dated 04.03.2025 received in this department through outdoor diary no. 14063 dated 04.03.2025 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 01.04.2025 and observed that the shortcomings intimated vide letter no. F6/DFS/MS/School/2014/368 dated 13.02.2014 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

End: as above

Yours faithfully,

Atul Garg)
Director

Delhi Fire Service

Tel: 011-23414000

Copy to:-

The Directorate of Education, Municipal Corporation of Delhi, Dr. SPM Civic Center, New Delhi.

dis

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110001

Ph - 23412025 Email - dcfondz.dlfire@nlc.in

No. F6/0fs/ms/school/ 214/368

Dated: 13/02/14

To.

The Principal,

Jai Bharat School, Chawri Bazar, Delhi-1 10006.

Sub: - Regarding issue of "Fire Safety Certificate" from fire safety point of view in r/o Jai Bharat School, Chawri Bazar, Delhi-110006.

Madam,

Please refer to your letter No. Nil dated 06.01.2014 on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the school on 6.2.2014 to verify the fire safety arrangements in accordance with the circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education. At the time of inspection Mrs. Leena Sharma (Principal) was present.

It was observed that the school building comprises of ground plus two upper floors and school is running on first and second floors. Ground floor is commercial. Fire fighting systems such as fire extinguishers and fire buckets were found provided and following shortcoming was observed.

- 1. An additional staircase not less than 75 cm width is required as the width of the existing single staircase is less than 1.5 meters.
- 2. A hose reel of 30 meters length fitted with 5mm shut-off nozzle on each floor connected with a pump of 450 LPM capacity (40 meters head) on terrace with 10000 liters overhead tank exclusively for firefighting not provided.
 - 3. Exit signs not provided at all exits and escape routes at appropriate locations.

In view of above, the fire safety certificate cannot be issued at this stage.

Yours faithfully

(Rajesh Panwar)

Dy.Chief Fire Officer

Copy to:-

The Director of Education, NorthDelhi Municipal Corporation, Dr. SPM Civic Centre, JLN Marg, N.D