



75
जन्मदायी
अमृत महोत्सव

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001**

No. F6/DFS/MS/GH/WZ/2025/ 39

Dated: 22/01/2025

To,

The Joint Commissioner of Police,
Licensing Unit, 1st floor, Police Station,
Defence Colony, New Delhi.
adlcp.lic-dl@nic.in

Sub: - Inspection report in respect of J.P Inn, Located at Shop No. 5, Street 2, East Patel Nagar, New Delhi- 110008.

Sir,

Please refer to online application through MHA portal vide I.D. No. 2021061613937 dated 25/12/2024 on the subject cited above. In this connection, it is to inform you that the said building was re-inspected by the officer concerned of this department on 17/01/2025 in presence of Sh. Arpit Jain to check the shortcomings already issued by this department vide letter no. F6/DFS/MS/GH/SZ/2023/234 dated 31/05/2023 & F6/DFS/MS/SZ/2024/701 dated 25/11/2024.

The Status of the Shortcomings are as under.

S. no.	Shortcomings	Status
1.	Hose reel hose found nonfunctional.	Rectified
2.	CO (carbon monoxide) detectors found removed.	Not Rectified
3.	P A system found removed.	Not Rectified
4.	Terrace pump of 450 lpm capacity found nonfunctional.	Rectified
5.	Exit signage found removed at some places.	Not Rectified

In addition to above shortcomings, MOEFA is provided but not functional.

In view of above Shortcomings the application for renewal of Fire safety Certificate is rejected. The occupancy of the Building/ premises in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/occupier. The licensing issuing authority/statutorily authority is requested that premises should not be allowed to run till it provide all necessary fire arrangements. Further, the applicant is directed to comply the above shortcomings under intimation to this department for further consideration in this matter.

Yours Faithfully

(Ajul Garg)
Director

Copy To: -

1. The Owner/Occupier J.P Inn, Shop No. 5, Street 2, East Patel Nagar, New Delhi- 110008.

21/1/2025