## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

0001 Dated: 12 04 2015

No. F.6/DFS/MS/Restaurant/WZ/2025/ 127

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Jubilant Food Works Ltd. Dominos Pizza, Shop No.13 & 14, Ground Floor, Plot No.1 B-5, situated at D Mall, Sector-10, Rohini, Delhi-110085, comprised of Three Tiered Basement, Ground + five upper floors but Dominos Pizza restaurant is running at in a mall Shop No.13 & 14 ground floor only has already been issued FSC by this department vide letter No. F.6/DFS/MS//Restaurant/WZ/2022/21 dated 01.02.2022. The premises was reinspected by the officer concerned of this department on 04.04.2025 in the presence of Mrs. Sabreena (Manager) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy Group D "Assembly" (Eating House) for Shop No.13 & 14, ground floor only with effect from 19 04 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 12 04 2025 at New Delhi by

(Atul Garg) DIRECTOR h; 011-23414000

## Copy to:

MCD Portal ID-2025031703784 dated 17.03.2025.

2. The Dy. Health Officer, North MCD, Sec-5, Rohini Zone, Delhi-110085.

3. Mrs. Sabreena (Manager), M/s Jubilant Food Works Ltd. Dominos Pizza, Shop No.13 & 14, Ground Floor, Plot No.1 B-5, situated at D Mall, Sector-10, Rohini, Delhi-110085.

## Conditions for validity of Fire Safety Certificate;

- All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form "K" is available on

http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit fire/FIRE/Home/Forms



INSPECTION REPORT

1. Name & address of the building: M/s Jubilant Food Works Ltd. Dominos Pizza, Shop No.13 & 14,

Ground Floor, Plot No.1 B-5, situated at D Mall, Sector-10, Rohini,

Delhi-110085.

2. Type of Occupancy : Assembly

3. Type of Case : Renewal (Ground floor Shop No.13 & 14)

4. Details of Previous NOC : F.6/DFS/MS//Restaurant/WZ/2022/21 dated 01.02.2022

5. Fire Safety directives letter No : NBC Part-IV 6. Date of inspection : 04.04.2025

7. Name of Inspecting Officer : Mr. Suman Kumar (ADO)

8. Name and designation of officers

		designation of officers building side : Mrs. Sabreen	a (Managara)		1		
			a (Manager)				
			eation no.2025031703784 da	ated 17.03.202	<		
. No.	Minimu	m Standards on fire prevention safety U/R 33	UBBL/NBC Requirement	Provided	Remarks MR/NMR		
	Access to building(Twin District Centre, D Mall, Sector-10, Rohini issued FSC vide letter						
		DFS/MS/2024/WZ/724 dated 10.12.20					
	Road width		Accessible	Accessib	le MR		
	Gate width		Accessible	Accessib	le MR		
	<ul> <li>Width of internal road</li> </ul>		NA	NA	NA		
2.	Number, Width, Type & Arrangement of [Provided & Maintained by Mall management]						
		ber of staircases					
	•	Upper Floors	Restaurant within mall	As Above	MR		
	•	Basements	Restaurant within mall	As Above	MR		
	b. Wid	th of staircases		-			
	•	Upper Floor	Restaurant within mall	As Above	MR		
	>.	Basements	Restaurant within mall	As Above	MR		
	c. Prote	ction of exits		2	100		
	Fire	check door	Restaurant within mall	As Above	MR		
	•	Pressurization	Restaurant within mall	As Above	MR		
	1 3723 0 3 3 3	of continuous staircases to terrace	Restaurant within mall	As Above	MR		
	13.452	dth of Corridor	Restaurant within mall	As Above	MR		
	f. Do	or Size	1.5m	Provided	MR		
3.	Comp	artmentation	OCENTACE CO.				
<u>"-</u>	•	Fire check door	Restaurant within mall	As Above	MR		
		Sealing of electrical shafts	Restaurant within mall	As Above	MR		
	•	Fire Rating of shaft door	Restaurant within mall	As Above	MR		
	•	Water Curtain	Restaurant within mall	As Above	MR		
		Fire Dampers	Restaurant within mall	As Above	MR		
1.	Smoke Management System [Provided & Maintained by Mall management]						
••	Short	Basements	Restaurant within mall		ve MR		
		Upper floors	Restaurant within mall	- II	ve MR		
5.	Fire Extinguishers						
		Total numbers	03nos.	provid	ed MR		
	•	Types	ABC/CO2	ABC-0	O3 MR		
	•	IS marking	ISI marked	Yes	MR		
6.	First-Aid Hose Reels						
CONTRACT	•	Total numbers on each floor	01nos.	As Abo			
	•	Length of hose reel hose	30mm	As Abo	A. (1) (1)		
	1 1	Nozzle diameter	5m	As Abo	ove MR		

	a landian and alarming system	em [Provided & Maintained	by Mail managemen	11			
<b>!</b>	Automatic fire detection and alarming syste		As Above	MR			
	<ul><li>Type of detectors</li><li>Location of Main Panel</li></ul>	Restaurant within mall	As Above	MR			
	Location of Repeater Panel	Restaurant within mall	As Above	MR			
	Alternate source of power	Restaurant within mall	As Above	MR			
	Hooters' Location	Restaurant within mall	As Above	MR			
	120	Required	Provided	MR			
3.	MOEFA	Restaurant within mall	As Above	MR			
).	Public Address System  (Descrided & Maintained by Mall management)						
10.		Restaurant within mall	As Above	MR			
	Basement	Restaurant within mall	As Above	MR			
	Ground & Upper Floors  Section of the Continuous C	Restaurant within mall	As Above	MR			
	Sprinkler above false ceiling						
11.	Internal Hydrants [Provided & Maintained b	100mm	As Above	MR			
	Size of riser/down-comer	One(near to Restaurant)	As Above	MR			
	Number of hydrants per floor	One(near to Restaurant)	As Above	MR			
	Hose Box			•			
12.	Yard Hydrants [Provided & Maintained by ]	Restaurant within mall	As Above	MR			
	Total number of hydrants	Restaurant within mall	As Above	MR			
	Hose Box	Kestaurant within man					
13.	Pumping Arrangements [Provided & Maint	ained by Mail management		6			
14	Ground Level	Restaurant within mall	As Above	MR			
	Discharge of main Pump		As Above	MR			
	> Head of Main pump	Restaurant within mall	As Above	MR			
	Number of main pumps	Restaurant within mall	As Above	MR			
	Jockey Pump out put	Restaurant within mall	As Above	MR			
	Jockey pump head	Restaurant within mall	As Above	MR			
	Standby Pump out put	Restaurant within mall	As Above	MR			
	Standby Pump Head	Restaurant within mall	As Above	MR			
	Auto Starting/Manual Stopping	Restaurant within mall	WWW. 1100-1100-1100-1100-1100-1100-1100-110	10.00			
	> Pump House Access	Restaurant within mall	As Above	MR			
	Terrace level	NA	As Above	MR			
	Discharge of pump	NA NA	As Above	MR			
	> Head of the pump	Required	As Above	MR			
	> Power Supply		As Above	MR			
	Auto Starting of pump Required						
14.	Captive Water Storage for firefighting [Provided & Maintained by Mall management]  Restaurant within mall						
	Underground tank capacity	Restaurant within mall	As Above	MR			
	<ul><li>Draw-off connection</li><li>Fire service inlet</li></ul>	Restaurant within mall	As Above	MR			
	> Access to tank	Restaurant within mall	As Above	MR			
	Overhead Tank capacity	Restaurant within mall	As Above	MR			
			Provided	MR			
15.	Exit Signage.	Required	11011404	1744			
16.	Provision of Lifts. [Provided & Maintained by Mall management]						
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	Restaurant within mall	As Above	MR			
	<ul> <li>Pressurization of Lift lobby</li> </ul>	Restaurant within mall	As Above	MR			
	Communication In lift Car	Restaurant within mall	As Above	MR			
	Fireman's Grounding Switch	Restaurant within mall	As Above	MR			
	Lift Signage	Restaurant within mall	As Above	MR			
17.	Standby power supply	Required	As Above	MR			

(-	>	Total Area	NA	NA	NA		
	>	Location	NA	NA	NA		
19.	Fire Control Room [Provided & Maintained by Mall management]						
	•	Detector System Panel	Restaurant within mall	As Above	MR		
		Flow Switch Panel	Restaurant within mall	As Above	MR		
	•	PA System Panel	Restaurant within mall	As Above	MR		
		Battery backup	Restaurant within mall	As Above	MR		
	•	Building Floor Plans	Restaurant within mall	As Above	MR		
20.	J	Fire Protection System for tion of special Risks, if any:	NA	Kitchen suppression system & gas detector found installed	NA		

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS//Restaurant/WZ/2022/21 dated 01.02.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

4005/04/25

Signature of the Inspecting Officer
Name Suman Kumar
Designation ADO

1/3/2424.

10x/4/2005

8 41 2025

Dinesta My

Anulfu

12

Confinu-