

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/Buisness/2025/SZ/331

Dated: 09/07/2025

To,

Sh. Rajiv Vij (President),
 Jyoti Shikhar Building, Plot No. 8
 District Centre, Janakpuri, New Delhi- 58.

Sub:- Regarding renewal of FSC in r/o M/s Jyoti Shikhar Building at Plot No. 8, District Centre, Janak Puri, New Delhi- 110058

Sir,

This has reference to your letter No. Nil, dated 13.06.2025, on the subject cited above. In this connection this is to inform you that officer concerned of this department inspected the premises/building on dated 28.06.2025 to verify the fire safety arrangements in accordance with the rules. At the time of inspection Sh. Rajiv Vij (President), was present and it was observed that the building comprised of basement, ground floor, upper ground floor plus five upper floors, and have following shortcomings were observed:

1. Electric shaft found not sealed properly.
2. First aid hose reel provided but found not functional.
3. Automatic fire detection and alarming system found provided but not functional.
4. MOEFA found provided but not functional
5. Hydrant system provided but found not functional.
6. Underground pumps provided as per requirements but found not in working condition.
7. Overhead tank found in damage condition and it needs repair.
8. Inspection ladder for access to overhead tank found not provided at the time of inspection.
9. Exit Signages found removed at some places.

In view of above shortcomings, the application for renewal of Fire Safety Certificate is rejected. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter.

Yours faithfully,

(Atul Garg)
 Director
 Delhi Fire Service

Copy to: -

- 1 The Chairman, DDA, Vikas Sadan, INA, New Delhi- 110003.
- 2 The Executive Engineer (Bldg.), MCD, Civic Centre, Minto Road, New Delhi.