GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F.6/DFS/MS/2025/\093

Dated 1.4/.0.6/2025

To,

Mr. S.R Goyal (G.M. Finance), Kailash Building, 26, Kasturba Gandhi Marg, New Delhi-110001.

Sub:-Regarding renewal of FSC in r/o Kailash Building, 26, Kasturba Gandhi Marg, New Delhi-110001.

Sir,

This has reference to your letter no. nil dated 30/05/25, on the subject cited above. In this regard the site was inspected by the officers concerned of this department on 12/06/25 in presence of Mr. S.R Goyal and observed that the shortcoming issued earlier vide letter no. F6/DFS/MS/GH/2025/239 dated 26/05/25 have not been complied so far.

In view of above, the case is rejected with a request to comply the same for further consideration in the matter.

Yours faithfully

DIRECTOR Delhi Fire Service

Copy to:

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.

2. Sh. S.K. Goyal (G.M. Finance), Kailash Building, 26, Kasturba Gandhi Marg, New Delhi-110001.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI

HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No.F.6/DFS/MS/2025/ 2 39

Dated 26/05/2025

To,

Mr. Sadhu Ram Goyal (G.M. Finance), Kailash Building, 26, Kasturba Gandhi Marg, New Delhi-110001.

Sub:-Regarding renewal of FSC in r/o Kailash Building, 26, Kasturba Gandhi Marg, New Delhi-110001.

Sir.

This has reference to your letter no. nil dated 25.04.2025, on the subject cited above. In this regard the site was inspected by the officer concerned of this department on 15/05/2025 in the presence of Sh. Omprakash & Sh. Pitambar and the following shortcomings were observed:-

- 1. Fire check doors in basement found removed.
- 2. Door closers from fire check door found removed at some floor.
- 3. Smoke Management system in basement found nonfunctional.
- 4. Fire service inlet found non functional
- 5. Draw off connection found not approachable for fire tender.

In view of above shortcomings, the application for renewal of FSC is rejected. The occupancy in the building in absence of requisite fire safety arrangements shall be at risk and liability of owner /occupier. Further, statutory authority / building sanctioning authority may take necessary action as deemed fit. Yours faithful

Copy to:

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.

2. Sh. S.K. Goyal (G.M. Finance), Kailash Building, 26, Kasturba Gandhi Marg, New Delhi-110001.