

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OFDELHI **HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001**



No. F.6/DFS/MS/BNQT/2025/WZ/ 56

Dated: 07/11/2025

## FIRE SAFETY CERTIFICATE

Certified that M/s Lotus Banquet (A unit of P R S Events) located at Property No. 7259, Prem Nagar, Shakti Nagar, Delhi-110007, running at Ground & First Floor in a building comprised of ground and 02 upper floors, owned/occupied by M/s Lotus Banquet(A unit of P R S Events), was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/BNQT/2022/45 dated 10/08/2022. The premise was re-inspected by the concerned offices of this department on 25/10/2025 in the presence of Sh. Sagar Kumar(Owner) and found that said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premise/building is fit for occupancy class "Group D-3 Assembly" (Banquet Hall at Ground & First Floor only) with effect from 07/11/2025 for a period up to 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 07/11 /2025at New Delhi by

Dy. Chief Fire Officer (WZ) Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, 9th Floor, Dr. SPM Civic Centre, Minto Road, New Delhi-110002

(w.r.t. online application no. 2025101614249 dated 16/10/2025)

2. Sh. Sagar Kumar, M/s Lotus Banquet(A unit of P R S Events) located at Property No. 7259, Prem Nagar, Shakti Nagar, Delhi-110007

## Conditions for the validity of Fire Safety Certificate: -

1. Second floor shall not be used for any purpose by the owner/occupier without prior approval of this department, failing which FSC should be treated null & void.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

3. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire-fighting system.

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, prior to its expiry.

7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

1.	Name & address of the building	ON REPORT  Lotus Banquet (A Unit of P R S Events), Property No. 7259, Prem Nagar, Shakti Nagar, Delhi–110007 Assembly (Banquet Hall).			
2.	Type of Occupancy				
3.	Building Comprised of	Ground plus two upper floors but banquet hall is running at ground & first floor only.			
4.	Type of Case	Renewal			
5.	Details of previous NOC No.	F6/DFS/MS/BNQT/2022/45 Dt. 10/08/2022			
6.	Fire safety directives letter No.	Nil			
7.	Date of inspection	25/10/2025			
8.	Name of the Inspecting Officer	DO (NW) and ADO (JKP)			
9.	Name and designation of Officer from the building side	Sh. Sagar Kumar (Owner)			
10.	Year of Construction	1990			
11.	Applicant's letter No./Online Appn.	No 2025101614249 dated 16/10/2025			
S. No.	Minimum standards on fire prevention and fire safety U/R 33	Drovided at site   Ke		Remarks MR/NMR	
1.	Access of building			MR	
	Road width	6.0 mtr	9.0 mtr approx.	MR	
	Gate width	Required	Directly accessible	N/A	
	Width of internal road	N/A	N/A	IV/A	
-	Number, width, Type & Arrangement	s of exits			
2.	N. 1 Catainagas			1 MD	
	Number of staffcases     Upper floors	02 Nos	03 Nos	MR N/A	
	Basements	N/A	N/A	N/A	
	b. Width of staircases		0.15	MR	
1	Upper floors	2.0m & 1.5m	2m, 2m & 1.5m	N/A	
	Basements	N/A	N/A	] *"	
	c. Protection of exits	CEARWAY.	N/A	N/A	
	Fire check door	N/A	N/A	N/A	
	<ul> <li>Pressurization</li> </ul>	N/A 02 Nos	02 Nos	MR	
	d. No of continuous staircase to terrace	N/A	N/A	N/A	
	e. Width of Corridor	2.0m & 1.5m	GF= 2m, 2m, 1.5m &1.0	m MR	
	f. Door Size	2.0m & 1.3m   Gr 2m, 2m, 1.5m   FF= 2m, 2m & 1.5m			
3.	Compartmentation	Required	Provided	MR	
	• Fire check door	Required	Provided	MR	
	<ul><li>Sealing of electrical shafts</li><li>Fire Rating of shaft door</li></ul>	Required	Provided	MR	
1	Water Curtain	N/A	N/A	N/A	
	Fire Dampers	N/A	N/A	N/A	
4.	Smoke Managements System	n_ file	an in the second	- V	
-	Basement.	N/A	N/A	N/A	
	Upper floors	12 ACPH	Exhaust fans provided	MR.	
5	Fire Extinguishers	14,82 L	Alter actual sell,	1 1	
5.	Total numbers	16 Nos	Provided	MR	
5.		ABC/CO <sub>2</sub>	ABC-14&CO <sub>2</sub> -02	MR	
5.	<ul> <li>Types</li> </ul>		D 111	M	
5.	<ul><li>Types</li><li>ISI marking</li></ul>	ISI marked	Provided	IVIK	
		ISI marked	Provided	MIK	
6.	ISI marking	ISI marked 02 Nos	1 2 2 3	MR	
	ISI marking     First-Aid Hose Reels		02 Nos 30 mtr	MR	

( A

N-16

	Type of detector	N/A	N/A	1 NT/A
		*****	357.03	N/A
	Location of Main Panel	N/A	N/A	N/A
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System			
	Basements	N/A	N/A	N/A
	Upper Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			INI
	Size of riser/down- comer	100 mm	Provided	MR
	Number of hydrants per floor	02 Nos	Provided	1000
	Hose Box	02 Nos	Provided	MR
12.	Yard Hydrants		Tiovided	MR
	Total number of hydrants	N/A	27/1	
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements	IN/A	N/A	N/A
7	Ground Level			
	Discharge of main pump			-on
	Head of main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	> Jockey pump out put	N/A N/A	N/A	N/A
	▶ Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standoy I unito Head	N/A	N/A	N/A
	<ul> <li>Auto Staring/Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A N/A	N/A
	Terrace level	N/A	N/A	N/A
	Discharge of pump		IVA	N/A
	Head of the pump	900 LPM	900 LPM	100
	> Power supply	40 mtr	40 mtr	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water storage for firefighting	Required	Provided	MR
	Undergraved to threfighting		TTOVIDED	MR
	Underground tank capacity	N/A	N/A	1
	> Draw of connection	N/A	1207 (000000)	N/A
	The service inlet	N/A	N/A	N/A
	Access to tank  Overhead Table	N/A	N/A	N/A
15	Overhead Tank capacity     Exit signage	25,000 ltr	N/A	N/A
16.	Provision of lifts	Required	Provided	MR
	> Pressure	quircu	Provided	MR
	> Pressurization of Lift Shaft	N/A	All the second of	
	riessurization of life 1-11	N/A	N/A	N/A
	Communication in 1:0 a		N/A	N/A
	Fireman's Grounding C	N/A	N/A	N/A
17.		N/A	N/A	
18.	Standby power supply	N/A	N/A	N/A
· ·	Refuge area	Required	Provided	N/A
	> Total area	37/		MF
	> Location	N/A	N/A	
	D./h	N/A	N/A	N/A

N-17

19.	Fire Control Room			
	Detector system panel	N/A	N/A	N/A
	➤ Flow Switch Panel	N/A	N/A	N/A
	➤ PA System Panel	N/A	N/A	N/A
	➤ Battery backup	N/A	N/A	N/A
	➤ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/BNQT/2022/45 dated 10/08/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Ashok Kumar Jaiswal

Designation: DO (NW)

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (JKP)

Dy. CFO (WZ

35/10/25

Principal Director

New 3

T. please.

ADOKTHE

Sir, FT water

ntop for your bi

171112 July

Dycro(12)

2/11/25

located Cheif F. P. Wing