



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

ण्डादी वा अमृत महोत्सव

No.F6/DFS/MS/College/SZ/2025/56

Dated: 16 05 2025

To

The Acting Principal, Lady Shri Ram College for Women, University of Delhi, Lajpat Nagar, New Delhi-24.

Sub:- Regarding renewal of Fire Safety Certificate in r/o Lady Shri Ram College for Women, University of Delhi located at Lajpat Nagar, New Delhi-24.
Sir,

With reference to the letter bearing outdoor dairy no. 1408 dated 07.05.2025 on the subject cited above, it is informed that the said building was visited by Assistant Divisional Officer (M. Road) from this department on 13.05.2025 in the presence of Mr. Shailesh (Admin) and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/SZ/2020/3164 dated 24.12.2020 (Photocopy overleaf) has not been rectified till date.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Delbi Fire Service

Copy to:-

1. The Executive Engineer (Bldg.) HQ, MCD, Civic Centre, Minto Road, New Delhi.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI-HEADOUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/SZ/2020/ 3164

To

Sh. Sanjay Roy Chowdhary (Vice-Principal) Lady Sri Ram College for Women, Laipnt Nagar, New Delhi-110024

Sub.: Regarding Fire Safety Certificate in r/o Academic Block A-4, Lady Shree Ram Collage for Woman Later State of the Collage for the Collage for Woman Later State of the Collage for the Colla Collage for Women, Lajpat Nagar, New Delhi-110024

Sir.

This has reference to e-mail dated 24/09/2020 received in this department, on the subject cited above. In this connection, it is to inform you that the officers concerned of this department inspected the aforesaid building in presence of Mr. Nittin (Engineer) 23/11/2020 to check the compliance of fire safety arrangements from fire safety point of view and the following shortcomings were observed: -

- I. As per letter No. F.6/DFS/MS/BP/2010/2779 dated 23/09/2010 issued by this department, the building plans for A-4 block were approved consisting of Ground + 6 upper floors. Whereas, during inspection it was observed that only Ground + 3 upper
- 2. At present the building is built as G+3 upper floors (height 13.80 m) and as such 6m wide road all around the building is not required but if the management decided to built additional approved floors i.e G+6 upper floors then 6m wide road all around the building shall be required/provided.
- 3. One of the staircase found 1.2m wide against the required width of 1.5m
- 4. The required width of entry/exit in multipurpose hall is less than required width of 1.5m.
- 5. The electric shaft not sealed.
- 6. Smoke management system in multipurpose hall not provided.
- 7. The required MOEFA not found provided

In view of the above shortcomings, Fire Safety Certificate cannot be considered at this stage. In view of the above the shortcomings under intimation to this department for further action in the matter.

Copy to:

1. The Executive Engineer (Bldg.) HQ, SDMC, Civic Center, Minto Road, New Delhi