

cl/79

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/NDZ/Hosp/2025/ 159

Dated 15/04/2025

To,

The Assistant Engineer(E), HC-2,
PWD, HMED (Central),
Lok Nayak Hospital, New Delhi.

Sub:- Regarding renewal of fire safety certificate to the various blocks of LNJP hospital , New Delhi.

Sir,

This has reference to letter no. Fire/AE (E) /HC-II/PWD/2024-25/59 dated 04.03.2025, on the subject cited above. In this regard, it is to inform you that the various block of LNJP hospital were inspected by the officer concerned of this department on 25 & 26.03.2025 in the presence of Sh. Manish Kumar AE (E) & JE (E), PWD and the following shortcoming were observed.

A. Causality OPD & surgical block.

1. 06 meter road for fire tender movement all around the said block is not provided Clearly.
2. One staircase of surgical block found blocked by dumping of waste items/ materials, which may leads to obstacle/hurdle to evacuate of the occupants/patients of the surgical block at the time of emergency.
3. Exit signage's found inadequate, required to be provided at conspicuous places.
4. Hoses and branches found missing at some hydrant boxes.
5. Further, some floors of causality block is under renovation and fire fighting is disconnected.

B. BL Taneja Block:

1. MCP found non-functional.
2. Hoses and branches found missing at some hydrant boxes.

C. MRD Block

1. MCP found non-functional.
2. Smoke managements system in basement found non-functional.
3. Hoses and branches found missing at some hydrant boxes.
4. All electric wire hanging haphazardly required to lay properly.

D. New OT Block

1. PA system found non-functional.
2. Smoke management system found non-functional in basement.
3. Hoses and branches found missing at some hydrant boxes

E. Ortho Block:

1. 06 meter road all around the building for fire tender movement found encroached with parking, shed and tree branches.
2. Detection system found non-functional.
3. MCP found non-functional.
4. PA system found non functional
5. Diesel engine is not in auto mode provision.
6. Hoses and branches found missing at some hydrant boxes
7. It was informed during inspection that ground and 7th floor are being renovated.

F. New Special Ward :

1. PA found non-functional.

2. Door closer found removed from some fire check doors.
3. Hoses and branches found missing at some hydrant boxes

In view of above shortcomings, the renewal of Fire Safety Certificate cannot be considered till compliance of above said shortcomings. .

Yours Faithfully,


(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. The Medical Superintendent, LNJP hospital, New Delhi.
2. The Superintendent Engineer (SE), Electrical health & Maintenance, MSO building, Second floor, IP Estate, ITO, New Delhi.
3. The Assistant (Engineer (E)-II, Health Maintenance Electrical Division (Central), PWD (NCTD), Lok Nayak hospital, New Delhi.