



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/EH/2025/SZ/388

Dated: 21 / 11 /2025

## FIRE SAFETY CERTIFICATE

Certified that M/s McDonalds Family Restaurant (Unit of Connaught Plaza Restaurants Pvt. Ltd) located at Shop No. 34, 102-B, 109 & 110, Ground & 1st Floor in MLCP DLF South Square Mall, Sarojini Nagar, New Delhi–110023, running at Ground & 1st Floor of the building, comprised of Basement, Ground + 08 upper floor, was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/EH/SZ/2022/284 dated 11/10/2022. Now, the premise was re-inspected by the officer concerned of this department on 07/11/2025 in the presence of Mr. Amit (Store Manager) and found that said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and that the said premise is fit for occupancy class "Assembly Group D" (Restaurant at Ground & 1st Floor only) with effect from 21/11/2025 for a period up to 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 21 / 11 /2025 at New Delhi by

(A.K. Malik)

Dy. Chief Fire Officer (SZ)

Delhi Fire Service

## Copy to: -

 The Commissioner, MCD, 9<sup>th</sup> Floor, Civic Centre, Minto Road, New Delhi–110002 (w.r.t. Online application No. 2025102914463 dated 29/10/2025)

 Sh. Rajeev Goel, M/s McDonalds Family Restaurant (Unit of Connaught Plaza Restaurants Pvt. Ltd), Shop No. 34, 120-B, 109 & 110, Ground & 1st Floor in MLCP DLF South Square Mall, Sarojini Nagar, New Delhi-110023

## Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided there in shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, prior to its expiry.
- 6. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

1.	Name & address of the building				
	of the building	M/s McDonald's Family Restaurant (Unit			
		of Connaught Plaza Restaurants Pvt. Ltd) at Shop No. 34, 102-B, 109 & 110, Ground &			
		1st Floor MI C	02-B, 109 & 110, G	round &	
2		1 <sup>st</sup> Floor, MLCP DLF South Square Mall, Sarojini Nagar, New Delhi-110023			
2.	Type of Occupancy	Assembly, Group 'D'			
3.	Building Comprised of	B+G+08 Upper Floor (Restaurant is running			
1		at Ground & First Floor of the building).			
4.	Type of Case	Renewal			
5.	Details of previous NOC No.	F6/DFS/MS/EH/SZ/2022/284 Dt. 11/10/2022			
6.	Fire safety directives letter No.	F.6/DFS/MS/BP/2008/3507 Dt. 22/12/2008 & F6/DFS/MS/BP/2014/17 Dt. 17/01/2014 (Bldg.)			
7.	Date of inspection	07/11/2025			
8.	Name of the Inspecting Officer	ADO (JKP)			
9.	Name and designation of Officer	Mr. Amit (Store Manager)			
	from the building side				
10.	Year of Construction	2011			
11.	Applicant's letter No./Online Appn.	No. 2025102914463 dated 29/10/2025			
S.	Minimum standards on fire	Old NOC	Provided at site	Remarks	
No.	prevention and fire safety U/R 33	Requirement	4. 10.5	MR/NMR	
1.	Access of building (Bldg. FSC No. F.6/	DFS/MS/Mixed/	SZ/2024/131 dated	04/03/2024)	
	Road width	Restt. within	As above	MR	
	Gate width	MLCP DLF	As above	N/A	
1 3	Width of internal road	South Square	As above	N/A	
2.	Number, width, Type & Arrangements	s of exits	ndiv. marangal		
	a. Number of staircases	Provided & M	ded & Maintained by Building Mgmt.		
	Upper floors	02 Nos	03 Nos	MR	
	Basements	N/A	As above	N/A	
	b. Width of staircases	Provided & M	aintained by Build	ing Mgmt.	
	Upper floors	1.5 mtr	3nos of 1.5m eac		
	Basements	N/A	As above	N/A	
	c. Protection of exits	Provided & Maintained by Building			
	Fire check door	N/A	As above	MR	
	Pressurization	N/A	As above	N/A	
	d. No of continuous staircase to terrace	Required	03 Nos	MR	
	e. Width of Corridor	N/A	N/A	N/A	
	f. Door Size/Exits	1.5m & 2.0m	1.5m & 2.0m (2n		
3.	Compartmentation	- D P. R. W.	aintained by Build		
	Fire check door	Required			
	Sealing of electrical shafts	Required	Provided	MR	
	Fire Rating of shaft door	Required	Provided	MR	
	Water Curtain	N/A	Provided	MR	
	Fire Dampers	N/A	N/A N/A	N/A	
4.	Smoke Managements System	NAME OF TAXABLE PARTY O		N/A	
	Basement.	N/A	laintained by Build		
	Ground & upper floor		As above	N/A	
5.	Fire Extinguishers	Required	Provided	MR	
	Total numbers	06.37	hou awtraw's g		
	Types	06 Nos	06 Nos	MR	
	ISI marking	CO <sub>2</sub> / ABC	ABC type	MR	
6.	First-Aid Hose Reels	ISI marked	Provided	MR	
٥.		Provided & N	faintained by Build	ding Mam	
	Total numbers on each floor		02 Nos near Res		
	<ul> <li>Length of hose reel hose</li> </ul>	Hose-reel	30 mtr		
	<ul> <li>Nozzle diameter</li> </ul>		\$11 mate	MR	

8 N

N-16

7.	Automatic fire detection and alarming sy	ystem.		
	Type of detector	N/A	Heat/Smoke	N/A
	<ul> <li>Location of Main Panel</li> </ul>	N/A	Ground floor	N/A
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	Fire control room	N/A
1	Alternate source of power	N/A	Provided	N/A
_	Hooters' Location	N/A	Provided	N/A
8.	MOEFA	Required	Provided	MI
9.	Public Address System	N/A	Provided	N/A
10.	Automatic Sprinkler System	1.50.707.07.	faintained by Building	
	Basements	N/A	As above	N/A
	Ground & Upper Floor	N/A	Provided	
	• Sprinkler above false ocilia-	N/A	Provided	N/A
11.	Internal Hydrants	The second secon		N/A
	Size of riser/down-comer	N/A	faintained by Building	
	Number of hydrants per floor	2012000	As above	N/A
10	Hose Box	N/A	As above	N/A
12.	Yard Hydrants	N/A Provided & N	As above	N/A
	Total number of hydrants	N/A	faintained by Building	
	Hose Box	N/A N/A	As above	N/A
13.	Pumping Arrangements		As above	N/A
	Ground Level	Provided & Maintained by Building Mgm		
	Discharge of main nump	Common fire-	fighting pumps for ent	ire blo
	riead of main nump	N/A N/A	2850 LPM	N/A
	Number of main number	N/A	60 mtr	N/A
	Jockey pump out put	N/A	02 Nos 180 LPM	N/A
	> Jockey pump head > Standby Pump out put	N/A	60 mtr	N/A
	Standby Pump Head	N/A	2850 LPM	N/A N/A
	Auto Staring/Manual starning	N/A	60 mtr	N/A
	> Pump House Access	N/A N/A	Provided	N/A
	Terrace level		Provided	A
	Discharge of pump	450 LPM	Maintained by Building	
	Head of the pump	40 mtr	900 LPM	MR
	> Power supply	Required	40 mtr Provided	MR
1.4	Auto starting of pump	Required	Provided	MR
14.	Captive water storage for firefighting		water storage for entire	MR
	Underground tank capacity	N/A	1,50,000 ltrs	
	Draw of connection	N/A	As above	N/A
	Fire service inlet	N/A	As above	N/A
	Access to tank	Required	As above	N/A
	Overhead Tank capacity	20,000 ltrs	25,000 ltrs	MR
15	Exit signage	Required	Provided	MR MR
16.	Provision of lifts		Maintained by Building	Mom
	Pressurization of Lift Shaft	N/A	As above	N/A
	Pressurization of lift lobby	N/A	As above	N/A
	Communication in lift Car Fireman's Grounding Switch	N/A	As above	N/A
	<ul><li>Fireman's Grounding Switch</li><li>Lift Signage</li></ul>		As above	N/A
17.		N/A Paguinad	As above	N/A
		Required	Provided	MR
18.		NT/A	377	
	> Total area	N/A	N/A	N/A
1	> Location	N/A	N/A	N/A

Qp.

N-17

19.	Fire Control Room	Provided & Maintained by Building Mgmt.		
	Detector system panel	N/A	As above	N/A
	Flow Switch Panel	N/A	As above	N/A
	PA System Panel	N/A	As above	N/A
	Battery backup	N/A	As above	N/A
	Building Floor Plans	N/A	As above	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	Provided & Maintained by Building Mgmt.		MR

The fire protection systems provided in the building/premises were checked, tested at random and found functional at the time of inspection. The main building has been issued FSC vide letter No. F.6/DFS/MS/Mixed/SZ/2024/131 dated 04/03/2024 (copy attached).

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/EH/SZ/2022/284 dated 11/10/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer
Name: Santosh Kumar

Name: Santosh Kumar Designation: ADO (JKP)

Ravinder Singh

) (a)

Busilal Snow

wh.

Oto to Stan

4 1410

20(fD)

MIIM

and stone

P-J.D