

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



No. F6/DFS/MS/WZ/2025/ 309 To,

Dated: 01/05/2025

The Principal, M. C. Primary School, Kamruddin Nagar-1, Nangloi, Delhi-110041.

## Subj.:- Regarding issuance of Fire Safety Certificate in respect of M. C. Primary School, located at Kamruddin Nagar-1, Nangloi, Delhi-110041.

Please refer to your email dated 05/042025 on the subject cited above. In this connection, it Sir, is to inform you that the said school building was re-inspected by the officer concerned of this department on 21/04/2025 in the presence of Ms. Sharmilla (Incharge) to check the compliance of shortcomings issued by this department vide letter no. F.6/DFS/MS/School/2013/2025 dated

During the course of inspection, it has been observed that the school management has 16.08.2013. rectified some of the shortcomings, the status is under as:-

ractifi	ed some of the shortcomings, the status is under as.	<u>Status</u>
	Shortconnings	n diffied
<u>S. No.</u>	The width of the staircase in one $G + 1$ block is 1.15 m which is either to 1.50 m are one additional fire escape of	Not Rectified
•	The width of the staircase in one G + 1 block is 1.13 in the	
1.	The width of the staircase in one G + 1 block is 1.13 in the required to be increased up to 1.50 m are one additional fire escape of required to be provided	
	required to be increased up a provided	Rectified
	Width 0.75 in 18 19	Rectified
2.	No of Fire Extinguishers were madequate wired to be provided.	107 1
2.	of ABC/CO <sub>2</sub> type 2.5kg capacity each is required to be provided of 10,000 ltrs. First Aid Hose Reel at each floor and an Over Head Tank of 10,000 ltrs.	Not Rectified
	The Aid Hose Reel at each floor and an Over Head Talk of Toyota	
3.	First Ald Hose Reel at Dump of 450 lpm discharge not provided in G	
	First Aid Hose Reel at each floor and an Over Head Tank of Specific Capacity and a Fire Pump of 450 lpm discharge not provided in G + 2	D 4:God
	block building.	Not Rectified
	block building.  Exit signage required to be provided in G + 2 block building	a C tiGasta
4.	Exit signage required to be provided in	afety Certificate
1 1	t teamings the application for issues	

In view of the above shortcomings, the application for issuance of Fire safety Certificate cannot be granted at this stage & rejected. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action.

Yours faithfully

(Atul Garg)

Director

Copy to:-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054.