



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

c24

No. F6/DFS/MS/WZ/2025/ 691  
To,

Dated: 25 / 08 / 2025

The Principal,  
M.C. Primary Utkrisht Vidyalaya,  
AG- Block, Shalimar Bagh,  
Delhi- 110088.

**Sub: - Inspection report in r/o M.C. Primary Utkrisht Vidyalaya located at AG- Block, Shalimar Bagh, Delhi- 110088.**

Madam,

This is in reference to your e mail id dated 18/07/2025 on the subject cited above. In this connection, it is to inform you that the above said school building was re-inspected by the officer concerned of this department on 30/07/2025 in the presence of Smt. Archana Mishra (Principal) to verify the compliance of shortcomings communicated vide this department letter No. F6/DFS/MS/2013/School/1281 dated 03/05/2013 & letter no. F6/DFS/MS/WZ/2019/2578 dated 03/05/2019.

The status of shortcoming is as under:-

Sr. No	Shortcomings	Status
1.	Fire Extinguishers are not adequate.	Rectified
2.	Hose reels are not provided.	<b>Provided but nozzle found missing.</b>
3.	Fire pump of capacity 450 lpm not provided.	<b>Provided but not functional</b>
4.	Overhead tank of capacity 10,000 ltrs not provided.	Rectified
5.	Exit sign not provided.	<b>Not Rectified</b>
6.	Second staircase found blocked at 2 <sup>nd</sup> floor	Rectified

In addition to the above shortcomings electrical meter under the staircase has to be removed to a safer place or segregated by fire check door. In view of the above shortcomings, the request for **issuance of Fire Safety Certificate can't be considered at this stage & rejected**. You are advised to rectify the above mentioned shortcomings under intimation to this department for further necessary action in this regard.

Yours faithfully,

(Virendra Singh)  
Chief Fire Officer

Copy to:-

1. The Director, Directorate of Education, MCD, Civic Centre, Delhi.