OV

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F6/DFS/MS/School/WZ/2025/ 318

Dated: 02/05/2025

To.

The Principal/Incharge, Montfort School, Ashok Vihar, Phase-1, Delhi-110052.

Sub: Inspection report in r/o. Montfort School, located at Ashok Vihar, Phase-1, Delhi-110052.

Sir,

With reference to your letter No.MS/Dep/2024-25/205 dated 19/02/2025, on the subject cited above. In this connection, it is to inform you that the said premises was inspected by the officer concerned of this department on 29/03/2025, in the presence of Brother Joy Thomas (Principal) to see the functioning of the fire safety arrangements/equipment's provided in the building.

During inspection, it has been observed that the said school building is running at total 04 Blocks, comprised of Two Blocks=Ground + 03 Upper Floors each, 01 Block=Ground + 02 Upper Floors & All 03 Blocks are interconnected & 01 new block is Ground + 03 Upper Floors, was already issued FSC vide letter No. F6/DFS/MS/School/WZ/2022/511 dated 12/05/2022, Fire Safety Arrangements such as, Fire Extinguishers, First Aid Hose Reels, Terrace pump, etc. are provided. However, following shortcomings were observed: -

- First Aid Hose Reels are provided but not functional.
- 2. Terrace fire pump of 450 LPM & 180 LPM is provided but not functional.
- 3. Exit Signage are found removed.

In view of above shortcomings, the application for renewal Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Atul Garg)

Director

Copy To:-

1. The Directorate of Education Old Secretariat Delhi – 110054.