## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2025/ 606

Dated: - 31/07/2025

To,

The Manager, New Ring Midways Public School, E-109-113, Nanhey Park, Hastsal, New Delhi-110059.

Sub:- Regarding renewal of "Fire Safety Certificate" from fire safety point of view in r/o New Ring Midways Public School at E-109-113, Nanhey Park, Uttam Nagar, New Delhi-59.

Sir,

Please refer to your letter No. MISC/NRMPS/AR/2024 dated 23.06.2025, on the subject cited above. In this connection it is to inform you that the above said school building have been inspected by the officer concerned of this department, in presence of Mr. Mahesh Solanki (Manager) on dated 11.07.2025, to check the status of the shortcomings already pointed out by this department vide letter No. F.6/DFS/MS/School/2023/SZ/123 dated 20.03.2023. During the course of inspection, it was observed that the shortcomings are not fully complied.

In view of the above, renewal of 'Fire Safety Certificate' cannot be granted at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter and running school in absence of requisite fire safety arrangements shall be at the risk & liability of the school management.

Yours faithfully

Virendra Singh Chief Fire Officer Delhi Fire Service

Copy for information:-

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2023/SZ / 12-3

Dated: 20/03/2023

To,

The Manager, New Ring Midways Public School at E-109, Nanhey Park,, Uttam Nagar, New Delhi-110059.

Sub: - Regarding issuance of Fire Safety Certificate in r/o New Ring Midways Public School at E-109, Nanhey Park, Uttam Nagar, New Delhi-110059.

Sir,

Please refer to your letter No. MISC./NRPMS/AR/2022 Dated- 15/02/2023 on the subject cited above. In this regard, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 06/03/2023 to see the compliance of the requisite fire safety measures. Sh. Mahesh (Manager) was present and it was observed that the school building is comprised of Two Blocks Old block having ground plus two upper floors & New Block having ground plus three upper floors and have following shortcomings.

- 1. Both staircases of 1.5 m wide shall be provided in New block.
- First aid Hose reel provided in old block but not functional & in New block First aid hose reel is not provided.
- 3. Fire pump having 450 lpm output at 40 m head provided in old block but not functional & in New block Fire pump 450 lpm not provided.
- 4. Overhead tank capacity 10,000 ltrs not provided in New block.
- 5. Exit Signage's provided but not sufficient.

In view of above, the school building cannot be considered for grant of fire safety certificate at this stage Therefore you are suggested to rectify the above said shortcomings under the intimation to this department for further course of action.

Yours Faithful)

Director

Delhi Fire Service

Copy:-