


GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F.6/DFS/MS/School/2025/WZ/ 562

Dated: 02 107/2025

To,

The Principal, New St. Michael Academy, F-242, Rishi Nagar, Shakur Basti, Delhi-110034.

Sub: - Regarding issuance of Fire Safety Certificate in r/o New St. Michael Academy located at F-242, Rishi Nagar, Shakur Basti, Delhi- 110034.

Sir,

This has reference to your letter no. nil received through outdoor diary number 1889 dated 20/05/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 26.06.2025 to see the compliance of shortcomings communicated vide letter no. F6/DFS/MS/WZ/2019/6319 dated 24/10/2019. Sh. Himanshu Garg was present at the time of inspection. During the course of inspection it was observed that shortcomings communicated via above mentioned letter were not rectified yet.

In view of the above, the application for issuance of Fire Safety Certificate is not considered at this stage & rejected. You are advised to rectify the above-mentioned shortcomings under

intimation to this department.

Yours Faithfull

Pirector Ph. 011-23414000

De N 46

Copy to:-

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-54.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No.F6/DFS/MS/WZ/2019/

To

The Principal, New ST. Michael Academy, F-242, Rishi Nagar, Rani Bagh, Delhi- 110034

Sub: - Inspection report in respect of New ST. Michael Academy located at F- 242, Rishi Nagar, Rani Bagh, Delhi- 110034

Dated: 24/10/2019

Sir,

Please refer to your Letter no. FS/2019-20/01 dated 13/09/2019 on the subject noted above. In this connection, it is informed that the said school premises have been inspected by the officer concerned of this department on 09-10-2019 in the presence of Smt. Charu Chugh.

The following shortcoming was observed during the time of inspection:-

- 1. Only one staircase of 86cm is provided against two staircase of 1.5m clear width.
- 2. The width of the corridor less than requirement 1.5m clear width
- 3. Width of class room door is less than requirement 1.2m clear width.
- 4. Hose Reel Hose of 30 mtrs length at each floor not provided.
- 5. Public address system are not provided...
- 6. Fire Pump of 450 lpm with 40m head is not provided
- 7. Overhead water tank of 10000 ltrs capacity is not provided
- 8. Exist signage are not provided.

You are requested to comply the above mentioned shortcomings under intimation to this department for further necessary action.

Yours faithfully

Chief Fire

Delhi Fire Serv

Copy to; - Director of Education, Old Secretariat, Delhi-110054