

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/School/NDZ/2025/ 328

Dated: 21 11 2025

To

The Principal, MCD Primary School (Co-Ed) Kalyanpuri, 05- Block, Delhi-94.

Sub:- Regarding issuance of Fire Safety Certificate in r/o MCD Primary School (Co-Ed), located at Kalyanpuri, 05- Block, Delhi-94.

Sir,

This has reference to the email dated 26.09.2025 on the subject cited above, it is informed that the said school was visited by officer concerned of this department on 11.11.2025 in the presence of Mrs. Sangeeta (Principal) and it was observed that the shortcomings already communicated by this department vide letter no. F6/DFS/MS/School/NDZ/2025/229 dated 17.04.2025 (Photocopy overleaf) has not been rectified till date.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Dr. S.K. Tomar)

Dy. Chief Fire Officer (NDZ)

Delhi Fire Service

Copy to:-

1. The Directorate of Education, MCD, 419, Udyog Sadan, Patparganj Industrial Area, Delhi92.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

्राजारी_म अपूर्वा महोत्रा

No. F6/DFS/MS/School/NDZ/2025/229

Dated: 17/04/2025

Τo.

The Principal, Nigam Pratibha Vidyalaya (Co-ed) Kalyanpuri 05 Block, Delhi - 110094,

Subject: - Regarding grant of Fire Safety Certificate in r/o Nigam Pratibha Vidyalaya (Co-ed) located at Kalyanpuri 05 Block, Delhi – 110094.

Sir,

This has a reference to your Outdoor Diary No. 14604 dated 18/03/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 07/04/2025 in the presence of Mr. Satish Kumar Bhati (Principal) and observed that building comprised of ground plus two upper floors.

Following shortcomings were observed during time of inspection:

- 1. First-Aid-Hose Reel not provided.
- 2. Terrace level fire pump capacity of 450 LPM not provided.
- 3. Overhead tank of capacity 10,000 litters not provided.
- 4. Exit & floors Signage's not provided at strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG) DIRECTOR

OCDELHI FIRE SERVICE

Copy to:-

 The Director of Education, East Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi - 110092.