

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/WZ/2025/ SCH / 30/ To, Dated: 08/07/2025

The Principal, Nigam Prathibha Vidyalaya, Nangloi, Main-I, Delhi-110041.

Subj.:- Regarding issuance of Fire Safety Certificate in respect of Nigam Prathibha Vidyalaya, located at Nangloi, Main-I, Delhi-110041.

Sir,

Please refer to your email dated 06/06/2025 on the subject cited above. In this connection, it is to inform you that the above said school building was inspected by the officer concerned of this department on 02/07/2025 in the presence of Ms. Seema Vats (Incharge) to check the compliance of shortcomings issued by this department vide letter no. F6/DFS/MS/2014/School/917 dated 22/04/2014 (copy enclosed).

During inspection, it have been observed that the shortcomings issued by this department vide above said letter has not been rectified yet.

In view of the above, the application for issuance of fire safety certificate cannot be considered at this stage & rejected. You are advised to rectify the above mentioned shortcomings under intimation to this department for taking further necessary action in the matter.

Delhi Fire Service

Yourd faithfully

Copy to :-

1. The Director, Directorate of Education, GNCT of Delhi, Old Secretariat Delhi – 110054

(-13

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE **NEW DELHI-110001**

No. F6/DFS/MS/2014/School/ 9/7

Dated 2 2 /0 4 /2014

To

The Principal, Nigam Prathibha Vidyalaya, Nangloi Main-1, Delhi-110041.

Sub:- Regarding issuance of NOC/FSC from Fire Safety Point of view in respect of Nigam Prathibha Vidyalaya, Nangloi Main-1, New Delhi-110041 (ID-1556385).

Sir,

Please refer to your letter No. Nil dated 04.02.2014 on the subject cited above, in this connection the premises was visited by the officer of this department and observed that the premises have three blocks, Ground Floor, (G+1) & G+2 having plot area 4800yard2 with covered area 2400yard2, Ground Floor is abandoned. Only (G+1) block & (G+2) block are being used as class rooms.

During the course of inspection it was observed that the both blocks are having two staircases in each. Fire Safety arrangements such as Fire Extinguisher are found provided.

However following shortcomings were observed during the time of inspection in G+2 Floor:-

- 1. Hose Reel Hose not provided in block consisting of Ground +2 Upper Floors.
- 2. Over Head Tank of 10,000ltrs. Capacity not provided.
- 3. Fire Pump of 450Lit / Mnt. Capacity not provided.

4. Exit Signages not provided.

5. There are two exits of 1.20mtr. in hall at First Floor against required width of 1.50mtr. Ill Education rivollar design of the

The School premises is not meeting the requirement of Fire & Safety guidelines issued by the Directorate of Education circular dated 01.03.2011.

In view of above, Fire Safety Certificate from Fire & Safety point of view cannot be considered at this stage.

You are requested to approach this department after compliance of above quoted shortcoming.

Yours faithfully,

(VIPIN KENTALY Dy. Chief Fire Officer, Ph: 011-23842505

Copy to:-

1. Dy. Director of Education, North Delhi Municipal Committee, Civic Center, J.L. Nehru Marg, New Delhi -110002.