

0/21

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No. F6/DFS/MS/School/2025/ 301

Dated: 30/04/2025

To

Mrs. Sweta Chaudhary, (Incharge),
Nigam Pratibha Vidhyalya,
Shadi Kham Pur, New Delhi-08.

Sub: Regarding issuance of FSC in r/o Nigam Pratibha Vidhyalya, Shadi Kham Pur, New Delhi-08.

Sir,

This has reference to your letter no. nil dated 20/03/25 & DFS diary no.14803 dated 21.03.2025, on the subject cited above. In this regard, it is to inform you that the matter was examined and observed that this department has already issue shortcomings vide letter no.F6/DFS/MS/2013/school/2613 dated 29/11/2013, wherein you have been informed that 06 meter road is not available for fire tender movement. Hence, the case cannot be considered for issuance of fire safety certificate till compliance of all the shortcomings issued vide aforesaid letter.

Therefore you are request to submit the point compliance of aforesaid letter for further consideration in the matter.

Encl. As above.

Yours faithfully

(Atul Garg)
DIRECTOR

Delhi Fire Service

Copy to:-

The Director of Education, Govt. of NCT of Delhi, Old Sectt. Delhi - 54.

DEPUTY CHIEF MINISTER

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001
Ph. 011-26189168

Dated: 29/11/13

The Principal,
M.C. Primary Adarsh School,
Shadi Kham Pur, New Delhi-08.

Sub: - Regarding grant of Fire Safety Certificate in r/o M.C. Primary Adarsh School, Shadi Kham Pur, New Delhi-110008.

Madam,

Please refer to your letter No. Nil dated 19.10.13 on the subject cited above. In this connection, it is to inform you that the re-inspection of above said school building has been carried out by officer concerned of this department on 25.11.2013 to see the compliance of the requisite Fire Safety measures. Smt. Mona Mahajan (Incharge) was also present.

During the course of inspection it was observed that the school building comprised of ground floor plus two upper floors. The upper floors are served by a single staircase having width 150 cms. The building is not approachable to the Fire Fighting vehicles and the building does not meet the required norms in the light of Delhi Fire Service Act 2007, and Rule 2010, provisions contained in NBC of India (part-IV) due to the following shortcomings: -

1. First Aid Hose Reels are not provided in the school building.
2. Fire Pump of 450 LPM discharge with 30-m head is not provided.
3. Overhead water storage tank of 10000 ltr cap. is not provided.
4. Three Co2 type Fire Extinguishers of 4.5 kg/2.2 kg cap. each and two D.C.P type Fire Extinguishers of 05 kg cap. each or two WCO2 type Fire Extinguishers of 09 ltr cap. each are not provided in the school building.
5. The width of street is 4.50 mtrs instead of 06 mtr.

You are advised to rectify the above mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully

Dy. Chief Fire Officer
Delhi Fire Service