GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/School/NDZ/2025/ 455

Dated: 26/05/2025

To

The Principal, North DMC Co-Education School, 357, Gali Garhiya, Bazar Matia Mahal, Jama Masjid, Delhi - 110006.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o North DMC Co-Education School, 357, Gali Garhiya, Bazar Matia Mahal, Jama Masjid, Delhi - 110006.

Sir,

This has reference to your letter outdoor diary No. 698 dated 17.04.2025 on the subject cited above. In this connection, it is to inform you that the above mentioned premise was visited by the officer concerned of this department on dated 19.05.2025 and observed that the shortcomings intimated vide letter no.F6/DFS/MS/2012/School/4644 dated 14/12/2012 (copy enclosed) have not been complied yet.

In view of above shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management.

Yours faithfully,

Encl: As above.

Director ol

Delli Fire Service

Tel: 011-23414

Copy to:-

The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO: F6/0FS/MS/2012/8Chool/4644

Dated: - 14 | 12 1/2

To,

The Principal,
M. C. Primary School,
Matia Mahal New, Jama Masjid, Delhi

Sub: - <u>Inspection report in r/o M. C. Primary School, Matia Mahal New, Jama Masjid, Delhi from fire safety & means of escape point of view.</u>

Sir,

With reference to your letter No nil dated 19/09/2012 on the above cited subject, this is to inform you that the aforesaid school building have been inspected by the officer concerned of this department in presence of the Principal on 17-10-2012 to verify the fire safety arrangements as per the directives of Education Department vide Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011.

During inspection, it was observed that the said school building is comprised of ground plus one upper floor and located on approx. 30 mts away from motorable road. One staircases of 1.08 mts found provided in the building. Two ABC type fire extinguishers, exit signs, electric siren and 08 sand buckets found provided in the building. The following shortcomings were observed:-

a. The school building is not approachable to the fire engines.

b. One additional staircase of minimum width 0.75 mts is required

In view of the above shortcomings, 'Fire Safety Certificate' cannot be considered at this stage.

Yours faithfully

Dy Chief Fire Officer Delhi Fire Service

Copy to :-

The Director of Education, MCD (North), Kashmere Gate, Nigam Bhawan, Delhi

90 8