## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/N Hostel/NDZ/2025/ 329

Dated: 09/07/2025

The Medical Superintendent, Kasturba Hospital, Dariya Ganj, New Delhi -110002.

Sub:- Regarding renewal of Fire Safety Certificate in r/o Nursing Hostel at Kasturba Hospital Darya Ganj, New Delhi - 110002.

Sir,

This has reference to email dated 13.06.2025 & outdoor diary No. 2804 dated 17.06.2025 on the subject cited above. In this connection, it is to inform you that the building/ premises was visited by the officer concerned of this department on 20.06.2025 in the presence of Mr. Rahul (Elect. Staff) and it was observed that the building is comprised of partially basement + ground + 08 upper floors. During inspection following shortcomings were observed, in addition to those previously identified.

- 1. Approach to the building was found completely blocked by car parking.
- 2. Channel gate shall not be allowed in the staircases.
- 3. Door closure of fire check doors found removed.
- 4. Vertical and horizontal electrical openings should be sealed.
- 5. Exhaust fans for ventilation were not provided in the basement.

First aid hose reel provided but non functional.

- 7. Automatic detection alarm system/ Manual call points was found non functional. This arrangement shall also be extended to the left out areas.
- 8. Manually operated electrical fire alarm system provided but non functional.

9. PA system provided but non functional.

- 10. Automatic sprinkler system provided in basement but not functional.
- 11. Internal hydrant was not functional and landing valves have removed from some hydrants. Delivery hoses and branches were not placed in hose cabinet.
- 12. Internal hydrant system was not provided on terrace.
- 13. Fire pumps at ground level and at terrace level found not functional.
- 14. Exit signages & lift signages are not adequately provided.
- 15. HT & LT panels were not protected with gas based suppression system.
- 16. LPG cylinders found installed at 6<sup>th</sup> floor & same shall be shifted at ground floor.
- 17. Overhead cables/ tree branches and other obstructions shall be removed near the entry gate.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the hospital management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

Delhi/Fire Service

Tel:-011-23414000

Copy to:-

1. The Executive Engineer (Electrical). Underground Car parking, Asaf Ali Road, New Delhi.