

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/GH/2025/ 1045

Dated 12/06₂₀₂₅

To,

Dr. Kartik K Raman, Senior medical Officer Link Officer, Fire and safety, LHMC & Smt. S.K Hospital, New Delhi.

Sub:- Regarding issuance of FSC in r/o Oncology Block at Lady Harding Medical College and Associated Smt. Scheta Kriplani Hospital Panchkuian Marg, New Delhi.

Sir,

This has reference to your letter no. LHMC/ACH /2025/17 dated 23.05.2025, on the subject cited above. In this regard, it is to inform you that the site was visited by officers concerned of this department on dated 04.06.2025 in presence of Sh. Neeraj Kumar Aggarwal JE(CPWD) and observed that the point no. 2 & 4 of the shortcomings issued vide letter no.F6/DFS/MS/2024/356 dated 24/06/2024(copy enclosed) have still not been complied.

In view of above, FSC can't be renewed till the compliance of all the shortcomings issued vide aforesaid letter.

Encl: As above.

Yours faithfully,

(Aful Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.

2. AE, Elec., CPWD, Lady Harding Medical College & Associated Hospital, New Delhi.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2024/ 356

Dated 1.1.05/2024

To,

The Director, Lady Harding Medical College & Associated Hospital, New Delhi.

Sub: Regarding fire clearance of Oncology block at Lady Harding Medical College and associated Hospital, at Shaheed Bhagat Singh Marg, New Delhi.

Sir,

This has reference to your mail id <directorlhmc@gmail.com> dated 27.05.2024, on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 13/06/24 in the presence of Sh. Ranjeet (JE) and the following shortcomings were observed.

- 1. Detector found non functional at some offices.
- Electrical shaft are not sealed at floor level.
- 3. PA system found non functional.
- 4. Pressurization of lift lobby & shaft found non functional.

In view of above shortcomings, the application for issuance of FSC is rejected. The occupancy in the building without requite fire safety arrangement shall be at risk and liability of owner /occupier of the building. The statuary /licensing authority may take necessary action as deemed fit.

Yours faithful

DIRECTOR

Delhi Fire Service

Copy to:

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.

2. AE. CPWD, Lady Harding Hospital, New Delhi.