



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आज़ादी का
अमृत महोत्सव

No. F6/DFS/MS/Industrial/NDZ/2025/ 980

Dated: 09/06/2025

To,

Mr. Anil Jain
Plot no. 377, Patparganj Industrial Area,
Delhi – 110092.

Subject: - Regarding Fire NOC in r/o M/s Plot no. 377, Patparganj Industrial Area, Delhi – 110092.


Sir,

Please refer to your email dated 02/05/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 27/05/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/NDZ/2022/153 dated 17/01/2022 (copy overleaf).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: as above


(VIRENDRA SINGH)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to: -

1. The Executive Engineer (Bldg.) HQ, MCD Udyog Sadan, Plot No. 419, FIE, Patparganj, Delhi - 110092.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F.6/DFS/MS/NDZ/2022/ 153

Dated: 17.01.2022

To

Sh. Anil Kumar Sharma,
Plot No. 377, FIE,
Patparganj Industrial area, Delhi-92.

Subject:- Regarding renewal of Fire Safety Certificate in r/o Plot No. 377, FIE, Patparganj Industrial area, Delhi-92.

Sir,

This has reference to your email dated 20/12/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 28/12/2021 in the presence of Mr. Anil Kumar Sharma and the following shortcomings were observed :-

1. Pump of capacity 950 LPM & 450 LPM is provided against required capacity of 2280 LPM & 180 LPM.
2. Staircase of 1.50 M is not provided in basement and encroached at upper floor.
3. Fire check doors not provided.
4. In basement Smoke management system is not provided.
5. Lift Signage not provided.

Hence, renewal of Fire Safety Certificate can not be considered at this stage.

Yours faithfully,



(Dr. S. K. Tomar)
Dy. Chief Fire Officer
Delhi Fire Service

ok
mw