

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/Industrial/SZ/2025/1164

Dated: 01 07

To

The Authorized Signatory, Plot No. E-1/B-1, Mohan Co-Operative Industrial Area/Estate, Mathura Road, New Delhi.

Sub: - Regarding renewal of Fire Safety Certificate in r/o Plot No. E-1/B-1, Mohan Co-Operative Industrial Area/Estate, Mathura Road, New Delhi.

Sir,

With reference to the letter bearing outdoor diary no. 1120 dated 29.04.2025 on the subject cited above, it is informed that the said building was visited by officer concerned of this department on 27.06.2025 in the presence of Sh. Lokesh Chauhan (Caretaker/Supervisor) and it vide letter building to the shortcomings issued that the observed F6/DFS/MS/Industrial/SZ/2025/128 dated 27.03.2025 (Photocopy overleaf) has not been completely rectified till date. Hence renewal of Fire Safety Certificate cannot be considered at this stage.

In view of above shortcomings, the application renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable

necessary action as deemed fit.

Yours faithfull

(Atul Garg) Director

Delhi Fire Service

Copy to:-

1. The Commissioner, MCD, Dr. S.P.M. Civic Centre, Minto Road, New Delhi-110002.

2. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

No. F6 /DFS/MS/Industrial/SZ/2025/ 12-8

Dated: 9.7

To.

The Owner/Occupier/Manager, Plot No. E-1/B-1, Mohan Co-Operative Industrial Area/Estate, Mathura Road, New Delhi.

Regarding renewal of Fire Safety Certificate in r/o Building located at Plot No. E-1/B-1, Mohan Co-Operative Industrial Area/Estate, Mathura Road, New Delhi.

Sir,

With reference to the letter bearing outdoor diary no. 14266 dated 10.03.2025 on the subject cited above, it is informed that the said building was inspected by officer concerned of this department on 19.03.2025 in the presence of Mr. Narender Singh (Caretaker/Supervisor) and following shortcomings were observed:

- 1. Fire Check Door (FCD's) found removed.
- 2. Automatic Fire Detection and Alarming System (ADAS) found non function.
- 3. Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.
- 4. All water based systems like Hose reels Internal & Yard Hydrants, Sprinklers, Fire Pumps are non functional.
- Diesel pump found removed.
- 6. Power cables running in the FHC must be removed and relocated in electrical shaft.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Copy to:-.

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi-24.