



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

C-16
सत्यमेव जयते
सत्यमेव जयते

No.F.6/DFS/MS/School/2025/NDZ/ 721

Dated: 10/09/25

To,

The Manager,
P.M. Public School,
89, Gobind Pura, Delhi-110051

Subject:-Regarding renewal of Fire Certificate in r/o P.M. Public School located at 89, Gobind Pura, Delhi-110051.

Sir,

This is in reference to your email Id. prishafilms01@gmail.com dated 13/08/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has visited the school on 25/08/2025 in presence of Manager and observed that the shortcomings as communicated earlier vide letter No. F.6/DFS/MS/School/2025/NDZ/245 dated 17/04/2025 (copy enclosed) have not been complied yet.

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Encl:- As above

Yours faithfully,


(VIRENDRA SINGH)
CHIEF FIRE OFFICER
o/c E.

Copy to:-

The Dy. Director of Education
D-Block, Anand Vihar, Delhi-110053



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

C-10 C-15 C-11



No. F.6/DFS/MS/School/2025/NDZ/ 245

Dated 17/04/2025

To,

The Manager,
P.M. Public School at 89, Gobind Park, Delhi-110051.

Sub:- Regarding Issuance of Fire Safety Certificate r/o P.M. Public School at 89, Gobind Park, Delhi-110051.

Sir,

With reference to your letter no. nil dated 03/03/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection on dated 03/04/2025 of the above mentioned School from fire safety point of view in presence of the Mr. Subhash Madan, Manager of the school. The building comprised of ground plus two upper floors. Following shortcomings were observed during the time of inspection.

1. An additional staircase of minimum width 0.75 meter not provided.
2. First Aid hose reels found removed at first and second floor.
3. Terrace pump 240 lpm head 40 meters found removed.
4. An Overhead tank capacity 1,500 liters provided against the requirement of 2,500 liters.
5. Exit Signage found removed.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to rectify the above mentioned shortcomings under intimation to this office for further course of action.

Yours faithfully

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to:-

The Dy. Director of Education
D-Block, Anand Vihar, Delhi-110053

o/c