

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI Dated: 2//05/2025 **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**



No: F.6/DFS/MS/2025/WZ/ 232

To,

The Sub Divisional Engineer, Provincial Sub Division No. 1, P.W.D. B&R, Haryana Bhawan,

New Delhi- 110001.

Sub: - Regarding renewal of Fire Safety Certificate in r/o PWD Housing Complex located at Shalimar Bagh, Delhi.

Sir,

This has reference to your letter no. 366 dated 01/04/2025 received through outdoor diary no. 546 dated 15/04/2025 on the subject cited above. In this connection, it is to inform you that the inspection of above said residential building has been carried out by officer concerned of this department on 15.05.2025 to see the compliance of the requisite fire safety measures. Sh. Deepak (Supervisor) was present at the time of inspection.

During the course of inspection it was observed that the building comprised of 05 Blocks (03- Blocks = Stilt + 8 upper floors each) & (02 Blocks = Stilt + 6 upper floors each). Your request for renewal of FSC is rejected as the following shortcomings were observed:-

- 1. First aid hose reels found provided but not functional.
- MOEFA found provided but not functional.
- 3. P.A system found removed.
- 4. Internal hydrants and yard hydrant found provided but not functional.
- 5. Terrace level pump found provided but not functional.
- 6. Exit signage's found removed at some places.
- 7. Building floor plans found removed.

You are advised to rectify the above-mentioned shortcoming for taking further action as necessary for renewal of Fire Safety Certificate.

Yours Faithfully