
C/488



NEW DELHI- 110001

No.F.6/DFS/MS/HTL/2025/31

Dated: 05/12/2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s Radisson Blu Hotel (A unit of Divine Infracon Pvt. Ltd.) (New Block) located Plot No. 4, Sector- 13, Dwarka City Centre, New Delhi- 110075, owned/occupied by M/s Radisson Blu Hotel (A unit of Divine Infracon Pvt. Ltd.), comprised of 3<sup>rd</sup> Basement, 2<sup>nd</sup> Basement, 1<sup>st</sup> Basement (lower ground), ground plus 01 upper floor, was issued FSC vide Letter No. F6//MS/DFS/MS/SZ/2022/504 dated 10.11.2022. The premises was re-inspected by the officer concerned of this department on dated 18.11.2025 in the presence of Sh. Subhash (Manager), and found that the building management constructed one more floor (2<sup>nd</sup> floor) and building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy mixed class "Mercantile & Assembly" (for 3<sup>rd</sup> Basement, 2<sup>nd</sup> Basement, 1<sup>st</sup> Basement (lower ground), ground plus 02 upper floors) w.e.f. of 12 1202 for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 05 12 2025 at New Delhi.

Oy. Chief Fire Officer

South Zone

## Copy to: -

1 The Assistant Engineer (Bldg.), MCD, Najafgarh Zone, Main Zonal Building, 1<sup>st</sup> Floor, Dhansa Stand, Najafgarh, New Delh- 110043.

2 The Manager, M/s Radisson Blu Hotel (A unit of Divine Infracon Pvt. Ltd.) (New Block) located Plot No. 4, Sector- 13, Dwarka City Centre, New Delhi- 110075.

## Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the BBL/UBBL.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

M[59

	ins	SPECTION REPORT				
-	Name & address of the building	Radisson Blu Hotel (	A unit of Divine Infracon I	Pvt. Ltd \ (N)		
1		Block) at Plot No. 04	Radisson Blu Hotel (A unit of Divine Infracon Pvt. Ltd.) (New Block) at Plot No. 04, Sec. 13, Dwarka City Centre, New Delh			
1	Type of Occupancy	Mixed (Mercantile &	: Assembly)	Delin		
1	2 Building Comprised of	03 Basement, ground	plus 02 upper floors			
	K	Addition/Alteration/	New Case			
4.	Type of Case		F6//DFS/MS/SZ/2022/HTL/35 dated 20.01.2022 (for 03 basement.			
5.	Details of previous NOC No.	ground plus 01 upper fi	oor)	n 03 basement.		
	Fire Safety directives Letter No.		0/200 dated 24.05.2019			
6.	Data of inspection	18.11.2025				
7.	Name of the Inspecting Officer	R.K. Yadav, ADO (D	OWK)			
8.	Name and designation of Officer	Sh. Subhash (Manage				
9.		on, outliness (viamege				
	from the building side	2021				
10.	Year of Construction	EE(B)/NGZ/25/D-1/8	142 dated 08 10 2025			
11.	Applicant's letter No.	EE(B)/NGZ/23/D-1/6	42 dated 08.10.2023			
Sr. No.	tion and fine safety II/D 22	Old NOC Requirements	Provided at site	Remark MR/NM		
1.	Access of building					
	Road width	20 mtr	Provided	MR		
	Gate width	06 mtr	Provided	MR		
	Width of internal road	06 mtr	Provided	MR		
			(6)			
2.	Number, width, Type & Arrangem	ients of exits				
	a. Number of staircases	02 No's	Provided	MR		
	Upper floors	02 No's	Provided	MR		
	Basements     Width of staircases	02 110 3	Tiovided	IVIIC		
		2.0 m each	Provided	MR		
	<ul><li>Upper floors</li><li>Basements</li></ul>	2.0 m each	Provided	MR		
	c. Protection of exits	2.0 in cach	Tiovided	- Inc		
	Fire check door	Required	Provided	MR		
	Pressurization	Required	Provided	MR		
	d. No of continuous staircase to terrace	02 No's	Provided	MR		
	e. Width of Corridor	2.0 m	Provided	MR		
	f. Door Size	1.50 m	Provided	MR		
	Compartmentation		NOTE TO THE	10016023		
	Fire check door	Required	Provided	MR		
	Sealing of electrical shafts	Required	Sealed	MR		
	Fire Rating of shaft door	02 hours	Provided	MR		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	Required	Provided	MR		
4.	Smoke Managements System			an openin		
	Basement.	Required	Provided	MR		
- 1	<ul> <li>Upper floors</li> </ul>	Required	Provided	MR		
_	Fire Extinguishers					
	70.1	50 Nos.	Provided	MR		
	<ul> <li>Total numbers</li> </ul>	To September 7 (September 2)				
		ABC &CO <sub>2</sub>	Provided	MR		
		ABC &CO <sub>2</sub> ISI marked	Provided	MR		
	<ul><li>Types</li><li>ISI marking</li></ul>		1975-1976-1976-1976-1976-1976-1976-1976-1976			
	<ul> <li>Types</li> <li>ISI marking</li> </ul> First-Aid Hose Reels	ISI marked	Provided	MR		
	<ul><li>Types</li><li>ISI marking</li></ul>		1975-1976-1976-1976-1976-1976-1976-1976-1976			

Es

-						
7.	Automatic fire detection and alarming  Type of detector  Location	Jan		MR		
	• T.	- Leo		MR		
	Type of detector  Location	g system.	Provided	MR		
	- duon of M.	Smoke/Heat	Provided	MR		
	Location of Repeater Panel  Alternate source of	Required	Provided	MR		
0	Hone Hone	Required	Provided	MR		
8.	Hooters' Location  MOEFA	Required	Corridor			
9.		Required Required	Provided	MR		
0.	Public Address System		Provided			
υ.	Automatic Sprinkler System	Required	Plovide			
	Basements			MR		
	• Upper Floor	Required	Provided	MR		
	• Sprinkler above 6.1	Required	Provided	MR		
1.	Sprinkler above false ceiling     Internal Hydrants	Required	Provided			
	• Size of :	·		MR		
	Size of riser/down- comer	150 mm	Provided	MR		
	Number of hydrants per floor     Hose Box	02 nos.	Provided	MR		
2.		Required	Provided			
	Yard Hydrants					
	Total number of hydrants	Required	Provided	MR		
3.	Hose Box	Required	Provided	MR		
	Pumping Arrangements	required				
	Ground Level					
	<ul> <li>Discharge of main pump</li> </ul>	2850 LPM	Provided	M/R		
	<ul> <li>Head of main pump</li> </ul>	120 mtrs.	Provided	M/R		
	Number of main pumps	Two	Provided	M/R		
	Jockey pump out put	220 LPM	Provided	M/R		
	Jockey pump head	90 mtrs.	Provided	M/R		
	Standby Pump out put	2850 LPM	Provided	M/R		
	Standby Pump Head	90 mtrs.	Provided	M/R		
	➤ Auto Staring/Manual stopping	Required	Provided	M/R		
	Pump House Access	Required	Provided	M/R		
	Terrace level					
	Discharge of pump	900 LPM	9000 LPM	M/R		
	Head of the pump	40 m	40 m.	M/R		
- 1		Required	Provided	M/R		
1	Power supply	Required	Provided	M/R		
	<ul> <li>Auto starting of pump</li> </ul>			N/A		
	Captive water storage for firefighting	1904				
	Underground tank capacity	2,00,000 ltr	Provided	MR		
	<ul> <li>Draw of connection</li> </ul>	Required	Provided	MR		
	Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	20,000 ltrs	Provided	MR		
	Overneau rank capacity	Required	Provided			
	Exit signage	Required	Tiovided	MR		
+	Provision of lifts					
+	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of lift lobby	Required	Provided	MR		
	Communication in lift Car	Required	Provided	MR		
	Communication in the Car	Required	Provided	MR		
	Fireman's Grounding Switch	Required	Provided	MR		
İ	<ul> <li>Lift Signage</li> </ul>	Required	DG Set	MR		
		D - antro		IVIR		

Refuge Area			
Total area	N/A	N/A	N/A
Location	N/A	N/A	N/A
Fire Control Room			
Fire Courton panel	Required	Provided	MR
Detector system panel	Required	Provided	MR
Flow Switch Panel	Required	Provided	MR
PA System Panel	Required	Provided	MR
Battery backup Building Floor Plans	Required	Provided	MR
Special Fire Protection Systems for Protection of Special Risks, if any;  The fire protection systems provide	Required	CO <sub>2</sub> Flooding System provided in HT & LT Panel	MR

at the time of inspection.

Delhi Fire Service Rule 2010.

RAJINDER

Note: - Earlier, Radisson Blu Hotel building was issued FSC by this department vide letter

Keeping in view the compliance of the minimum standards on fire prevention and fire safety

Signature of the Inspec

Name: - R.K. Yadav

Designation: - ADO (DWK)

No. F6//DFS/MS/SZ/2022/HTL/35 dated 20.01.2022 (for 03 basements, ground plus 01 upper

required under the rules it is recommended to grant Fire Safety Certificate under Rule 35 of the

floor). but now Hotel management constructed one additional floor (2<sup>nd</sup> floor).