

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADOUAD TO NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE

No. F.6/DFS/MS/GH/2025/SZ/413 NEW DELHI-110001 Dated: ..!]../.v.6/2025

FIRE SAFETY CERTIFICATE

Certified that the Lodging house in the Name & Style of M/s ROCKLAND INN located at B- 207, Chittranjan Park, New Delhi 110019 comprised of Basement, Ground plus Three ways a Rishi Kumar plus Three upper floors having total 21 Guest room owned/occupied Mr. Rishi Kumar Srivastave was a Srivastava was issued been issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/GH/2022/SZ/25 dated 14/01/2022. The premise was re-inspected by the officer and of Mr. Aditva the officer concerned of this department on 04/06/2025 in the presence of Mr. Aditya Bhandari and the fire Bhandari and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (Guest House running at Ground plus three upper floors with 21 Guest Rooms only) and validity upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

DELMI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic. Branch), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MCD Portal ID 2025042907472 dated 14/05/2025)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of BBL-/NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

"The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."





| | INSPECTIO | N DEPOS | | | | |
|--------|---|---|------------------------|------------------|--|--|
| 1 | bar of a le | ON REPORT M/s Rockland Inn located at B-207, Chittranjan Park, New Delhi-110010 | | | | |
| 2 | Type of Occupancy | Park, New Delhi-110019 | | | | |
| 3 | Building Comprised of | Residential, "Group-A" (Guest II | | | | |
| 4 | Type of Case | Suscincia, Ground + 03 upper 4 | | | | |
| 5 | Details of Previous NOC | Rollewal | | | | |
| 6 | Fire Safety Directives Letter No | F6/DFS/MS/GH/2022/SZ/25 dated 14/01/2022 | | | | |
| 7 | Date of Inspection | Nil Nil 2022/SZ/25 dated 14/01/2022 | | | | |
| 8 | Name of the Install | 04/06/2025 | | | | |
| 9 | Name of the Inspecting Officers | Sh. Rajesh Kumar ADO (BCP) | | | | |
| | Name & Designation of Officers from the building side | Mr. Aditya Bhandari | | | | |
| 10 | Year of construction | 1995 Total- 21 Guest Room | | | | |
| 11 | Applicant letter No. | MCD Portal ID 2025042907472 dated 14/05/2025 | | | | |
| S. No. | Minimum standards on Fire Prevention and Fire Safety U/R 33 | Old NOC requirements | Provided at Site | Remarks | | |
| 1 | Access to Building. | | | MR/NMR | | |
| | Road width Gate width | Required | Accessible | MR (old case) | | |
| | Width of internal road | -NA- | -NA- | -NA- | | |
| | | -NA- | -NA- | -NA- | | |
| 2 | Number, width, type & arrangement of exits. | | BIN I DELLIGIE . | | | |
| | a) Number of Staircase | | | | | |
| | > Upper floors. | Required | 02 Nos | MR | | |
| | ➢ Basement floor. | Required | 02 Nos | MR | | |
| | b) Width of Staircase | | | | | |
| | ➤ Upper floors | 1.25 mtr | 1.0 m & 0.90 m | MR (old case) | | |
| | > Basement floor | 1.25 mtr | 1.0 m & 0.90 m | MR (old case) | | |
| 1-6- | c) Protection of exits | 174 | NA | -NA- | | |
| | ➤ Fire check door | -NA- | -NA- | -NA- | | |
| 9705 | > Pressurization | -NA- | -NA- | MR | | |
| - | d) No. of continuous staircase to terrace | One | 02 No -NA- | -NA- | | |
| 1.8 | e) Width of corridor | -NA- | 1 m | MR | | |
| dine. | f) Door size | lm | SELLAN LABOUR NAMED IN | F-51 | | |
| 3 | Compartmentation. | -NA- | -NA- | -NA- | | |
| | Fire check door. Fire check door. Fire check door. | -NA- | -NA- | -NA- | | |
| | Sealing of electrical shafts. Sealing of electrical shafts. Sealing of electrical shafts. | -NA- | -NA- | -NA- | | |
| | Fire rating of shaft door. Water curtain | -NA- | -NA- | -NA- | | |
| | Water curtain Fire dampers. | -NA- | -NA- | -NA- | | |
| 1170 | - A supplementary | As per clause 7.31 of UBBL 2016 Respect for provided MR | | | | |
| 4 | Basement | 30 ACPH | Exhaust fan provided | | | |
| 10 | Upper floors | 12 ACPH | Exhaust fan provided | MK | | |
| 5 | Fire Extinguishers. | 11 Nos | Provided | MR | | |
| Fry | Total numbers | ABC / CO2 | ABC & CO2 | MR | | |
| K. | Types ISI Marking | ISI marked | Provided | MR | | |
| - | First Aid Hose Reels. | | Provided | MR | | |
| - | Total numbers on each floor. | One | 1 - 2 - 1 - 1 | MI | | |
| | Length of hose-reel hose. | 30 mtr | Provided | MI | | |
| | Nozzle Diameter | 5 mm | Provided | IVI | | |

m35

14.17

| 7 | |
|-----|---------------------------|
| SIL | 3 |
| अमृ | ते _{का} त मही |

| 7 | Automatic fire detection & alarming system. | As per clause 7.31 of UBBL 2016 | | - 6 | |
|----|---|---------------------------------|-----------------------|-------|--|
| | Type of detectors | Co.MO Det. | Provided | | |
| | Location of Main Panel | Required | Provided | MR | |
| | Location of Repeater Panel | -NA- | -NA- | MR | |
| | Alternate source of power | Required | Provided | -NA- | |
| | Hooter's location | Required | Provided | MR | |
| 8 | MOEFA | Required | | MR | |
| 9 | Public Address System | Required | Provided | MR | |
| 10 | Automatic Sprinkler System | | Provided | MR | |
| 10 | Basement | Required | D | | |
| | Upper floors. | -NA- | Provided -NA- | MR | |
| | Sprinkler above false ceiling | -NA- | | -NA- | |
| 11 | Internal Hydrants. | | -NA- | -NA- | |
| | Size of Riser/Down-comer | 150 mm | D | | |
| | Number of Hydrant per floor | 01 No | Provided | MR | |
| | Hose box. | 01 No | Provided | MR | |
| 12 | Yard Hydrants. | 01110 | Provided | MR | |
| | Total number of hydrants. | -NA- | | 150 | |
| | Hose box. | -NA- | -NA- | -NA- | |
| 13 | Pumping arrangements. | -INA- | -NA- | -NA- | |
| | Ground Level | | at trint milk seessle | 1111 | |
| | Discharge of main pump. | as Maryon very | | | |
| | Head of main pump. | -NA- | -NA- | -NA- | |
| | Number of main pumps. | -NA- | -NA- | -NA- | |
| | > Jockey Pump output. | -NA- | -NA- | -NA- | |
| | Jockey Pump head. | -NA- | -NA- | -NA- | |
| | Standby Pump output | -NA- | -NA- | -NA- | |
| | Standby Pump head | -NA- | -NA- | -NA- | |
| | Auto Starting/Manual Stopping | -NA- | -NA- | -NA- | |
| | Pump house access. | -NA- | -NA- | -NA- | |
| | Terrace Level | -NA- | -NA- | -NA- | |
| | Discharge of pump. | 450 1 72 5 | Caling y | - 112 | |
| | ➤ Head of pump. | 450 LPM | Provided | MR | |
| | ➤ Power supply. | 35 m | Provided | MR | |
| | ➤ Auto starting of pump. | Required | Provided | MR | |
| 14 | Captive water storage for fire fighting. | Required | Provided | MR | |
| | Underground tank capacity. | - D : - | | | |
| | Draw-off connection. | Required | 27,000 ltrs | MR | |
| | Fire Service Inlet. | -NA- | -NA- | -NA- | |
| | Access to tank. | Required | Provided | MR | |
| | Overhead tank capacity. | -NA- | -NA- | -NA- | |
| 15 | Exit Signage. | 25,000 Ltr | 25,000 Ltr | MR | |
| 16 | Provision of Lifts. | Required | Provided | | |
| | | | TOVIGEU | MR | |
| | 1 1033ulization of lift shaft | -NA- | -NA- | NT. | |
| | Pressurization of lift lobby. | -NA- | -NA- | -NA- | |
| 4 | • Communication in lift car. | -NA- | -NA- | -NA- | |
| | • Fireman's switch. | -NA- | -NA- | -NA- | |
| 7 | • Lift signage. | -NA- | -NA- | -NA- | |
| 8 | Standby Power Supply | Required | WALL DAY YOU | -NA- | |
| | Refuge Area | quirou | Provided | MR | |
| | Total area | -NA- | NTA | | |
| | • Location | | -NA- | -NA- | |
| 9 | Fire Control Room. | -NA- | -NA- | -NA- | |



Detector system panel. -NA-Flow switch panel. -NA--NA--NA-PA system panel. -NA--NA--NA--NA-Battery backup. -NA--NA-Building floor plan. -NA--NA--NA-Special Fire Protection System for the Protection of special Risk, if any. -NA--NA-

Note: - Fire Check Door not required as owner/occupied has applied in CAF MCD Portal number of beds is less than 10 at each floor.

The fire protection system provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/GH/2022/SZ/25 dated 14/01/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: - Rajesh Kumar Designation: - ADO/BCP

DO (SD)

fmeler 6/6/ps

GD | | | mg/ 9 6/ 2025

Director

letter is

stoce of

portal

Mil6

Dire vor My

Wooded

18/1/25