

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/WZ/2025/ 77

Dated: 04 03 2025

### FIRE SAFETY CERTIFICATE

Certified that the M/s Rio Rave Restaurant (A Unit of HPM Foods Pvt. Ltd) located at Shop No. A-6, 7, 8, 11 Ground floor, Vikas Surya Shopping Mall, Plot no. 18, Manglam Place, District Centre, Sec-3, Rohini, Delhi-85 (FSC issued to the entire mall in the name of Vikas Surya Shopping Mall Plot no. 18, Manglam Place, District Centre, Sec-3, Rohini, Delhi-85), which is comprised of Basement + Ground + 05 upper floors owned by Vikas Surya Shopping Mall & occupied by Rio Rave Restaurant (A Unit of HPM Foods Pvt. Ltd) has complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concerned of Delhi Fire Service on 21.02.2025 in the presence of Mr. Gurpreet (Mall Manager) & Mrs. Komal (Manager) and that the building/premises is fit for occupancy class Group 'D' (Assembly) and valid upto 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on 04 03 2025 at New Delhi by

Director

Delhi Fire Service

Reference: etl.mcdonline application no. 2025021401881 & 2025020401450. Copy to:

The Commissioner MCD, 9<sup>th</sup> Floor, Shyama Prashad Mukherjee Civic Centre, Delhi – 110002.
 To ensure the occupancy of the building as per the issued FSC.

## Conditions for the validity of Fire Safety Certificate

- 1. This Fire Safety Certificate is valid for restaurant at Ground floor only.
- 2. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 4. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 5. The trained fire fighting staff should be available round the clock.
- 6. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
  7. This fire safety certificate may not be treated in any second in the concerned building sanctioning authority.
- 7. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 10. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.

### 1. N-3

#### INSPECTION REPORT

1.	Name	e and address of the building:	M/s Rio Rave Restaurant (A Unit of HPM Food Pvt. Ltd) located at Shop No. A-6, 7, 8, 11, Groun floor, Vikas Surya Shopping Mall, Plot no. 1 Manglam Place, District Centre, Sec-3, Rohin Delhi-85 (FSC issued to the entire mall in the name Vikas Surya Shopping Mall Plot no. 18, Manglam Place District Centre, Sec-3, Rohini, Delhi-85).			
2.	Type	of occupancy		nbly" (Restaurant)		
_		ing comprised of				
	Julia	ing comprised of	Basement + Ground + 05 upper floors.  (The said Restaurant running at Ground floor building)		floor of the	
4.	Type	of case:	New Case		CONT. N.	
10000		ls of previous FSC	Nil	who I write A	Title T	
		afety directives no.	UBBL/NBC- 20	16 per 1911	100	
200		of inspection:	21.02.2025		il K	
		of the inspecting officer:	Rajesh Kumar Sl	hukla, ADO (M. Road)	11.8	
		and designation of the officer	Mr. Gurpreet (M	all Manager) &		
		the building side:	Mrs. Komal (Ma	nager)	event L.	
	200	of construction:	2023-24		21001.0	
~~	M. S. Marin	ence letter no.:	etl.mcdonline application no. 2025021401881 & 2025020401450			
S. No		nimum standard of Fire evention and Fire Safety U/R	Requirements UBBL/NBC- 2016	Provide at site	Remarks MR/NMR	
1	Ac	cess to Building:	THE RESERVE OF THE PARTY OF THE		MR	
	A	Road width	6.0 mtrs	Provided	NA	
	В	Gate width	NA	NA	NA NA	
	C	Width of internal roads	NA	NA	NA	
2	Nu	mber, Width, Type & Arrang	ement of Exits:	Small Committee	10	
	A	No. of Staircase:	Restaur	ant at Ground floor o		
		a) Upper floor	NA	NA	NA	
	200	b) Basements	NA	NA	NA	
	В	Width of the Staircase:	ant at Ground floor o			
	В	a) Upper floors	NA	NA	NA	
	550	b) Basement	NA	NA le sul torre	NA	
	C	Protection of Exits	magnatic fine ru-4			
	-	a) fire check door	NA	NA	NA	
	1	b) pressurization	NA	NA -	NA	
	_	No. of continuous staircase	NA	NA	NA	
	D	to terrace		Acres to be substitution		
		Width of the corridor	NA	NA	NA	
	F	Door Size	Required	03 nos. of exist - 2 nos. x 1.65 m & 1no. x 1.09 m	MR	
3	Cor	npartmentation:	W. I	nazan Rosa		
3	A	Fire check doors	NA	NA	NA	
	B	Sealing of horizontal & vertical opening	NA	NA	NA	
	C	Fire rating of shaft doors	NA	NA	NA	
	D	Water curtain	NA	NA	NA	
	E	Fire dampers	NA	NA	NA	
2		oke Management System:		The same		
4	-	Basements	NA	NA	NA	
	A		Required	Provided	MR	
1	B	Restaurant area	Roquirou	equired 110vides in pairing.		
5	4	Extinguishers:	06.55	06 nos.	MR	
	A .	Total numbers	06 nos.	OO HOS.	IATIC	
	A	STORY AND VINCENSIAN STORY	150	ADC	MD	
	B	Types	ABC ISI marked	ABC ISI marked	MR MR	

HIL

		J	
_	1		
7			

5	Fi		& maintained by	building manager	ment)		
	A	Total no. at each floor	1 no.	Provided near	MR		
1.415	D	7 241 41		exits 30 m	MR		
store.	B	Length of hose reel	30 m		MR		
	C	Nozzle diameter	5 mm	5 mm	The second second		
7	Automatic Fire Detection and Alarm System (ADAS): (Provided & maintained by building management)						
	A	Type of detectors	NA	Smoke/heat	NA		
	B	Location of main panel	NA	Provided	NA		
	C	Location of repeater panel	NA	NA	NA		
39/0	D	Alternate power source	NA	NA	NA		
	E	Hooter's location	NA	Provided	NA		
8		OEFA:	Required	Provided	MR		
9		iblic Address System:	NA	NA	NA NA		
10	_			by building mana	NA NA		
	A	Basement	NA	NA .	NA NA		
	B	Ground floor	NA	Provided			
	C	Sprinklers above false ceiling	NA	NA	NA		
11				building managem	MR		
_	A	Size of down comer	100 mm	Provided	MR		
	B	No. of hydrants per floor	01 no.	Provided	MR		
	C	Hose box	01 no.		- CONTRACTOR - CON		
12	_		& maintained by NA	building managem Provided	NA NA		
100	A	Total no. of hydrants	NA NA	Provided	NA NA		
13	В	Hose box Imping Arrangements: (Common fire		provided & mainta			
-	A	a) Discharge & head of main pump	Required	2850 LPM & 60 m	MR		
		b) Number of main pump	Required	02 nos.	MR		
		c) Discharge & head of jockey pump	Required	180 LPM & 60 m	MR		
		d) Discharge & head of standby pump	Required	2850 LPM & 60 m	MR		
	-	NA 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1 A 1	Required	Provided	MR		
	_	e) Auto starting/ manual stopping	And the second of the second o				
_	B Terrace Level (Common fire fighting system provided & mainta building management)						
£	d	a) Discharge of terrace pump	450 LPM	Better system provided	MR		
	A P	b) Head of terrace pump	NA	NA	NA		
		c) Alternate power supply	NA	NA	NA		
	-	d) Auto starting of pump	NA	NA	NA		
14	Captive Water Storage for Fire Fighting: (Common fire tank provided & maintained by building management)						
-	A	Underground tank capacity	NA NA	2,00,000 ltrs	NA		
	B	Draw off connection	NA	Provided	NA		
-		Fire service inlet	NA	Provided	NA		
	C	Access to tank	NA	Provided	NA		
-	E	West States and Control	20,000 ltrs	20,000 ltrs	MR		
_	D	Overhead tank capacity	Required	Provided	MR		
		it Signage:	Market State Control of the Control	INC. CO. CO.			
-		The state of the s	& maintained b	NA NA	NA		
UI.	A	Pressurization of lift shaft	NA NA	NA NA	NA		
1		Pressurization of lift lobby Communication in lift car	NA NA	NA NA	NA		
	~	Communication in the car			NA		
	-	Eiroman switch	NA	INA	11177		
	C D E	Fireman switch Lift signage	NA NA	NA NA	NA		

M/s Rio Rave (A Unit of HPM Foods Pvt. Ltd) located at Shop No. A-6, 7, 8, 11 Ground floor, Manglam Place, Sec-3, Rohini Delhi-85.

M/s Rio Rave (A Unit of HPM Foods Pvt. Ltd) located at Shop No. A-6, 7, 8, 11 Ground floor, Manglam Place, Sec-3, Rohini Delhi-85.

18	Refuge Area:				
	A	location	NA	NA	NA
	В	Total area	NA	NA	NA
19	Fire Control Room: (Provided & maintained by building management)				
	A	Fire detection system panel	NA	Provided	NA
	В	Flow switch panel	NA	Provided	NA
	_		NA	Provided	NA
	C	P a system panel	1 T. O. O. C.	Provided	NA
	D	Battery backup	NA	Provided	NA
	E	Building floor plan	NA		
20	Special Fire Protection for special risk if any				
	A	Special Fire Protection system for Protection of Special Risk, if any:	NA	NA	NA

# LEGENDS:-Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Not Provided (NP) Provide But Not Functional (PNF).

Note:- During the course of inspection it was observed that the Restaurant running at Ground floor of existing building of Vikas Surya Shopping Mall Plot no. 18, Manglam Place, District Centre, Sec-3, Rohini, Delhi-85) which has been already issued the FSC by this department vide letter no. F.6/DFS/MS/2022/WZ/536 dated 29.11.2022 (Copy placed on file).

placed on file).

The fixed fire installation has been provided & maintained by the building management which is common to the entire building. The installed fire system is of higher capacity and category then required for the individual restaurant and same was

found functional at the time of inspection.

If agreed to the note above & in view of the substantial compliance of the minimum standards on fire prevention and fire safety measures as required under the Rules, it is recommended to grant Fire Safety Certificate under Rules 35 of Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Rajesh Kumar Shukla Designation ADO (M.Road)

DO DAN Oa boare

Deneter My N

PJP is fut up pla

03/3/25

·

Uplanded 04/03/28 A