GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

No. F.6/DFS/MS/School/2025/SZ 1328

Dated: 20/11/2025

FIRE SAFETY CERTIFICATE

Certified that the Rishikul International School located at Sector- 04, Dwarka, New Delhi110075, is comprised of ground floor plus two upper floors, was issued Fire Safety Certificate by this
department vide letter No. F.6/DFS/MS/SZ/2022/School/490 dated 09.05.2022 (for the name of Tiny
Tulips School). The school building was re- inspected by the officer concerned of this department on
dated 07.11.2025 in the presence of Sh. Naresh, and found that the school building have complied the
fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service
Rules, 2010 and that the building/premises (ground plus two upper floors) is fit for occupancy class
"Educational Building" w.e.f. 2011 2025 for a period of three years in accordance with Rule 36
unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the
conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 20/11/2025 at New Delhi by.

(A.K. Malik)
Dy. Chief Fire Officer
South Zone

Copy to: -

- 1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.
- 2. The Principal, Rishikul International School at Sector- 04, Dwarka, New Delhi- 110075.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

1. Name & address of the building

2. Building comprised of

3. Type of Occupancy

4. Details of Previous NOC

5. Fire Safety directives letter No

6. Date of inspection

7. Name of Inspecting Officer

8. Name and designation of officers From the building side

9. Year of Construction

11. Applicant's letter No.

INSPECTION REPORT

Rishikul International School, Sec. 4, Dwarka, New Delhi- 75.

Ground plus two upper floors.

Renewal

F.6/DFS/MS/SZ/2022/School/490 dated 09.05.2022

N/A

:

07.11.2025

A.D.O. R.K. Yadav

Sh. Naresh

2005 & 2015 (second floor)

Sr. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per FSC dated 09.05.2022	Provided at site	Remarks MR/NMR			
ι.	Access to building						
	 Road width Gate width Width of internal road 	Accessible 06 m 4.5 m N/A	12 m Provided N/A	M/R MR N/A			
2.	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases						
	Upper Floors	02 No	02 No's	M/R			
	Basements	N/A	N/A	N/A			
	b. Width of staircases		and the second	NO H			
	Upper Floor	1.50 m & 0.75 m	Provided	MR, old case			
	Basements	N/A	N/A	N/A			
	c. Protection of exits		N//	N/A			
	Fire check door	N/A	N/A	AMAMASS			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	5	Talled a man day	M/R			
	terrace	02 nos. 1.50 m	02 nos. 1.80 m	M/R M/R			
	e. Width of Corridor		DOMESTIC RESERVE	SS SYNTAGES			
	f. Door Size	1.0 m	0.85	M/R, old case			
3.	Compartmentation		The second				
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4.	Smoke Management System						
	Basements	N/A	N/A	N/A			
	Upper floors	Required	Natural ventilation	M/R			
5.	Fire Extinguishers						
	Total numbers	15 Nos.	Provided	M/R			
	• Types	ABC/CO ₂ type	Provided	M/R			
	IS marking	ISI marked	Provided	M/R			
j.	First-Aid Hose Reels						
	Total numbers on each floor	01 no.	Provided	NA/D			
	Length of hose reel hose	30 M	Provided	M/R M/R			
	Nozzle diameter	5 mm	Provided	M/R M/R			
7.	Automatic fire detection and alarming syste		Tovided	IVI/ K			

011/11/19

		10 mg 20 mg				
	Type of detectors	N/A	N/A	N/A		
1	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	· N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
D	MOEFA .	N/A	N/A	N/A		
3.		N/A	N/A	N/A		
9.	Public Address System	e sudanesse				
10.	Automatic Sprinkler System	N/A	N/A	NI/A		
	Basement	N/A N/A	N/A	N/A N/A		
	Ground Floor Ground Floor false ceiling	N/A	N/A	N/A		
	Sprinkler above false ceiling					
11.	Internal Hydrants	and the second of the second	erex este electron			
	Size of riser/down-comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
12.	Yard Hydrants	m LP				
	Total number of hydrants	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	➤ Discharge of main Pump	N/A	N/A	N/A		
	Head of Main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey Pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	> Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	➤ Auto Starting/Manual Stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level					
	> Discharge of pump	450 LPM	450 LPM	MR		
	➤ Head of the pump	40 mtr	40 mtr	MR		
	➤ Power Supply	Required	Provided	MR		
	 Auto Starting of pump 	Required	Provided	MR		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	N/A	N/A	N/A		
	> Draw-off connection	N/A	N/A N/A	N/A		
	Fire service inlet	N/A		N/A N/A		
	Access to tank	N/A N/A	N/A			
	Overhead Tank capacity	10,000 ltrs	N/A Provided	N/A MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts,					
	No Lift					
	Pressurization of Lift Shaft Pressurization of Lift lobby	N/A	N/A	- N/A		
- 11	Communication In lift Car	N/A	N/A	N/A		
	- Communication in lift Car	N/A	N/A	N/A		
	The second secon			The state of the s		
	Fireman's Grounding Switch	N/A	N/A	N/A		
7.	The second secon	N/A N/A	N/A N/A	N/A N/A		

Total Area	N/A	N/A	N/A		
> Location	N/A	N/A	N/A		
Fire Control Room					
Detector System Panel	N/A	N/A	N/A		
Flow Switch Panel	N/A	· N/A	N/A		
PA System Panel	N/A	N/A	N/A		
Battery backup	N/A	N/A	N/A		
Building Floor Plans	N/A	N/A	N/A		
Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - Earlier, the school building was issued FSC by this department vide letter No. F.6/DF\$/MS/SZ/2022/School/490 dated 09.05.2022 for the name of Tiny Tulips School. But now the school management change the name of the school from Tiny Tulips School to Rishikul International School.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the Fire Safety Certificate issued vide letter No. F.6/DF\$/MS/SZ/2022/School/490 dated 09.05.2022, is recommended to be renewed under rule 37, of the Delhi Fire Service Rules, 2010.

Signature of the Inspecting

Name: - R.K. Yadav

Designation: - ADO (DWK)

NDER ATWAL

MALIK

PPO