

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI <u>HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001</u>



No F 6/DFS/MS/2025/School/WZ/ 858

Dated: 03/07/2025

FIRE SAFETY CERTIFICATE

Certified that the Rockfield Public School (Junior Wing) located at Sector-3, Rohini, Delhi-85, comprised of Ground and first floor owned/occupied by Rockfield Public School (Junior Wing) was vide granted **FSC** this department by F.6/DFS/MS/2022/School/WZ/613 dated 03.06.2022. The premises was re-inspected by the officer concerned of this department on 19.06.2025 in the presence of Mr. Anil Kumar Sharma (Assistant Director) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from 63/07/2025 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on 63 07 2025 at New Delhi

DIRECTOR Ph; 011\23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi - 54.

 The Principal, Rockfield Public School (Junior Wing) located at Sector-3, Rohini, Delhi-85.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building: Rockfield Public School (Junior Wing) located at Sector-3, Rohini,

Delhi-85.

2. Type of Occupancy : Educational

3. Comprised of building : Ground + 1 floor & 2nd floor T/Structure 4. Type of Case : Renewal (Ground + 1 floor only)

5. Details of Previous NOC : F.6/DFS/MS/2022/School/WZ/613 dated 03.06.2022. 6. Fire Safety directives letter No : Director of Education Circular dated 01.03.2011

7. Date of inspection : 19.06.2025.

8. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)

9. Name and designation of officers

From the building side : Mr. Anil Kumar Sharma (Assistant Director)

10. Year of Construction : 1996

S. No.		num Standards on fire prevention re safety U/R 33	Director of Education Circular dated 01.03.2011	Provided at site	Remarks MR/NMR		
1.	Acces	s to building					
1	•	Road width	Accessible	Accessible	MR		
	•	Gate width	Accessible	4.5m	MR		
	•	Width of internal road	-NA-	-NA-	-NA-		
2.	Numl	er, Width, Type & Arrangement of	Exits				
		mber of staircases			1		
	•	Upper Floors	02nos.	03nos.	MR		
		Basements	-NA-	-NA-	-NA-		
	b Wi	dth of staircases	1 2	<			
	•	Upper Floor	1.5m	1.5m iron SC & 1.10m x 2	MR		
	•	Basements					
	c Pro	tection of exits	-NA-	-NA-	-NA-		
	180,001,000,000	check door	-NA-	-NA-	-NA-		
		Pressurization	-NA-	-NA-	-NA-		
	d N	o. of continuous staircases to terrace	-NA-	-NA-	-NA-		
	11. CONT. C. 17.	idth of Corridor	-NA-	-NA-	-NA-		
	15 G (747 - 2500)	oor Size	1.0m	1.0m	MR		
3.	CANADA GALAN	artmentation					
).		Fire check door	-NA-	-NA-	-NA-		
	•	Sealing of electrical shafts	-NA-	-NA-	- Cananari		
		Fire Rating of shaft door	350,000,000	**************************************	-NA-		
		Water Curtain	-NA-	-NA-	-NA-		
	3	Fire Dampers	-NA-	-NA-	-NA-		
			-NA-	-NA-	-NA-		
4.	Smoke Management System						
	•	Basements	-NA-	-NA-	-NA-		
	•	Upper floors	12 a/c per hour	Natural ventilated	MR		
•	Fire Extinguishers						
	•	Total numbers	06nos.	08nos.	MR		
	•	Types	ABC/CO2	ABC-8	MR		
		IS marking	ISI marked	Yes	MR		
	First-	Aid Hose Reels	T 274				
	•	Total numbers on each floor	-NA-	01nos.	-NA-		
	•	Length of hose reel hose	-NA-	30m	-NA-		
	•	Nozzle diameter	-NA-	5mm	-NA-		
	Autom	natic fire detection and alarming syste	-NA-				
	1.0	Type of detectors	-11/4-	-NA-	-NA-		

	Location of Main Panel	-NA-	-NA-	-NA-				
	 Location of Repeater Panel 	-NA-	-NA-	-NA-				
	 Alternate source of power 	-NA-	-NA-	-NA-				
	 Hooters' Location 	-NA-	-NA-	-NA-				
6	MOEFA	-NA-	-NA-	-NA-				
	Public Address System	-NA-	-NA-	-NA-				
0.	Automatic Sprinkler System							
11	Basement	-NA-	-NA-	-NA-				
	Ground & Upper Floors	-NA-	-NA-	-NA-				
3	Sprinkler above false ceiling	-NA-	-NA-	-NA-				
1	Internal Hydrants							
	Size of riser/down-comer	-NA-	-NA-	-NA-				
	Number of hydrants per floor	-NA-	-NA-	-NA-				
	Hose Box	-NA-	-NA-	-NA-				
12.	Yard Hydrants							
	Total number of hydrants	-NA-	-NA-	-NA-				
10	Hose Box	-NA-	-NA-	-NA-				
13.	Pumping Arrangements							
	Ground Level	H						
	Discharge of main Pump	-NA-	-NA-	-NA-				
	➤ Head of Main pump	-NA-	-NA-	-NA-				
à:	Number of main pumps	-NA-	-NA-	-NA-				
	Jockey Pump out put	-NA-	-NA-	-NA-				
	Jockey pump head	-NA-	-NA-	-NA-				
	Standby Pump out put	-NA-	-NA-	-NA-				
	Standby Pump Head	-NA-	-NA-	-NA-				
	➤ Auto Starting/Manual Stopping	-NA-	-NA-	-NA-				
	> Pump House Access	-NA-	-NA-	-8159069				
	Terrace level	-NA-	-NA-	-NA-				
	Discharge of pump	NIA	4501					
	➤ Head of the pump	-NA-	450lpm	-NA-				
	> Power Supply	-NA-	40m Provided	-NA-				
	➤ Auto Starting of pump	-NA-	Provided	-NA-				
		-14/A-	Flovided	-IN/A-				
14.	Captive Water Storage for fire fighting							
	Underground tank capacity	-NA-	-NA-	-NA-				
	Draw-off connection	-NA-	-NA-	-NA-				
	➤ Fire service inlet	-NA-	-NA-	-NA-				
	> Access to tank	-NA-	-NA-	-NA-				
	Overhead Tank capacity	-NA-	5,000ltr	-NA-				
15.	Exit Signage.	-NA-	-NA-	-NA-				
16.	Provision of Lifts.		'					
		-NA-	-NA-	-NA-				
	Pressurization of Lift Shaft Pressurization of Lift labburgers	-NA-	-NA-	-NA-				
	 Pressurization of Lift lobby Communication In lift Car 	-NA-	-NA-	-NA-				
	A CONTRACTOR OF THE CONTRACTOR		-NA-	-NA-				
	Fireman's Grounding Switch Lift Signage	-NA-	-NA-	-NA-				
	Lift Signage	-NA-		-NA-				
17.	Standby power supply	-NA-	-NA-	-IVA-				
18.	Refuge Area.							
	> Total Area	-NA-	-NA-	-NA-				
	> Location	-NA-	-NA-	-NA-				
19.	Fire Control Room							
19.	Detector System Panel	-NA-	-NA-	-NA-				
	Detector by stering and	-NA-	-NA-	-INA				

ON/

	Flow Switch Panel			
	PA System Panel	-NA-	-NA-	-NA-
	Battery backup	-NA-	-NA-	-NA-
	Building Floor Plans	-NA-	-NA-	-NA-
20.	Special Fire Protection System for	274		
	Protection of special Risks, if any:	-NA-	-NA-	-NA-
	Accordingly 41 C			

Accordingly, the fire protection systems provided in the building were tested/ checked

randomly and found in working condition at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures required stipulated in Director of Education Circular, the FSC issued vide letter no. F.6/DFS/MS/2022/School/WZ/613 dated 03.06.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

24/6/2

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Rohini)

DO (NW) MIR

Dycforpz

DCF0/161-0110

Dated 26/06/21

30 61 Aan

Deneta

Moth

FT lette to fort up for kind pound and sights

Director of M

W/1 27-125