

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6/DFS/MS/2025/School/WZ/ 859

Dated: 03 67/2025

FIRE SAFETY CERTIFICATE

Certified that the Rockfield Public School, Sector-16, Rohini, Delhi-89, comprised of Ground + 03 upper floors owned/occupied by Rockfield Public School was granted FSC by this department vide letter No. F.6/DFS/MS/2022/School/WZ/619 dated 07.06.2022. The premises was re-inspected by the officer concerned of this department on 19.06.2025 in the presence of Mrs. Alka Shri Vastava and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from

mentioned below:

Issued on 03/07/2025 at New Delhi

(Athl/Garg) DIRECTOR Ph; 011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi - 54.

2. The Principal, Rockfield Public School, Sector-16, Rohini, Delhi-89.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms



INSPECTION REPORT

1. Name & address of the building: Rockfield Public School, Sector-16, Rohini, Delhi-89.

2. Type of Occupancy : Educational

: Renewal (Ground + 03 upper floors) 3. Type of Case

: F.6/DFS/MS/2022/School/WZ/619 dated 07.06.2022 4. Details of Previous NOC : Director of Education Circular dated 01.03.2011 5. Fire Safety directives letter No

: 19.06.2025 6. Date of inspection

: A.K.Sharma ADO(Rohini) 7. Name of Inspecting Officer

8. Name and designation of officers

: Mrs. Alka Shri vastava From the building side

S. No.	11ppineum o 101101	Director of Education Circular dated 01.03.2011	Provided at site	Remarks MR/NMR
1.	Access to building		Accessible	MR
4.	Road width	Accessible	4.5m	MR
	• Gate width	Accessible	-NA-	-NA-
	• Width of internal road	-NA-	AW.	
2.	Number, Width, Type & Arrangement of l	Exits		
	a. Number of staircases	01nos.	02nos.	MR
	• Upper Floors		-NA-	-NA-
	Basements	-NA-	• 11.5	
	b. Width of staircases	1.5m	1.6m & 1.45m	MR
	Upper Floor	1.5m	-NA-	-NA-
	Basements	-NA-	-IVA-	
	c. Protection of exits		-NA-	-NA-
	Fire check door	-NA-	-NA-	-NA-
	Pressurization	-NA-	-NA-	-NA-
	c timuous staircases to terrace	-NA-	2.45m	MR
	Tri 1.1 Comidor	1.5m	1m	MR
	g.'	1m	1111	
			1 1 V 1 V 1 V 1 V 1 V 1 V 1 V 1 V 1 V 1	NIA
3.	Compartmentation	-NA-	-NA-	-NA-
	Fire check door Sealing of electrical shafts	-NA-	-NA-	-NA-
	Deting of shaft door	-NA-	-NA-	-NA-
	TTI tou Custoin	-NA-	-NA-	-NA-
	Water Curtain Fire Dampers	-NA-	-NA-	-NA-
4.	Smoke Management System	-NA-	-NA-	-NA-
"	Basements	12 a/c per hour	Natural ventilated	MR
	Upper floors	12 a/c per nour		
5.	Fire Extinguishers	08nos.	12nos.	MR
	Total numbers	ABC/CO2	ABC-12	MR
	Types		Yes	MR
	IS marking	ISI marked	168	IVIK
5.	First-Aid Hose Reels	01nos.	Provided	MR
	Total numbers on each floor	30mm	Provided	MR
	Length of hose reel hose	5m	Provided	MR
	Nozzle diameter	11/20/09/00/01/	Flovided	IVIK
	Automatic fire detection and alarming system	-NA-	-NA-	-NA-
	Type of detectors Chair Bonel			
	Location of Main Panel Constant Panel	-NA-	-NA-	-NA-
	 Location of Repeater Panel 	-NA-	-NA-	-NA-

	V/	1	
1	"	1	6
	ı	_	

	C	-NA-	-NA-	-NA-
	Alternate source of power	-NA-	-NA-	-NA-
	Hooters' Location	-NA-	-NA-	-NA-
8.	MOEFA	-NA-	-NA-	-NA-
9.	Public Address System			NIA -
10.	Automatic Sprinkler System Basement	-NA-	-NA-	-NA-
	Ground & Upper Floors	-NA-	-NA-	-NA-
	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11.	Internal Hydrants			I NA
11.	Size of riser/down-comer	-NA-	100mm	-NA-
	Number of hydrants per floor	-NA-	01at GF & FF, 02 at SF & TF	
	Hose Box	-NA-	01	-NA-
12.	Yard Hydrants			1
12.	Total number of hydrants	-NA-	-NA-	-NA-
	Hose Box	-NA-	-NA-	-NA-
13.	Pumping Arrangements			r ———
10.	Ground Level			NIA
	➤ Discharge of main Pump	-NA-	-NA-	-NA-
	> Head of Main pump	-NA-	-NA-	-NA-
	> Number of main pumps	-NA-	-NA-	-NA-
	> Jockey Pump out put	-NA-	-NA-	-NA-
*	25 72 71	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	> Standby Pump out put	-NA-	-NA-	-NA-
	> Standby Pump Head	-NA-	-NA-	··-NA-
191	➤ Auto Starting/Manual Stopping	-NA-	-NA-	NA-
	> Pump House Access	-NA-	1112	1
	Terrace level	4501mm	450lpm	MR
	> Discharge of pump	450lpm 40m	40m	MR
	Head of the pumpPower Supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
2.3	Captive Water Storage for fire fighting	require		
14.		-NA-	-NA-	-NA-
	Underground tank capacity	-NA-	-NA-	-NA-
	 Draw-off connection Fire service inlet 	-NA-	-NA-	-NA-
	The state of the s	-NA-	-NA-	-NA
	0 1 1 0 1	E 0.04000	10,000ltr	MR
	130 Wester	10,000ltr	Provided	MR
5.	Exit Signage.	Required	Tiovided	IVIIC
6.	Provision of Lifts.			W. S. W.
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-
	Pressurization of Lift lobby	-NA-	-NA-	-NA-
	Communication In lift Car	-NA-	-NA-	-NA-
	Fireman's Grounding Switch	-NA-	-NA-	-NA-
	Lift Signage	-NA-	-NA-	-NA-
7	Standby power supply	-NA-	-NA-	-NA-
7.	Refuge Area.	contraggery m		
8.	, e	-NA-	-NA-	-NA-
	> Total Area	-NA-	-NA-	-NA-
	> Location	-INVA-	-1477-	-1 VM -
	Fire Control Room	NTA	NI A	NT.
	Detector System Panel	-NA-	-NA-	-NA-
	Flow Switch Panel	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-

F .	PA System Panel	-NA-	-NA-	-NA-
	Battery backup Building Floor Plans	-NA-	-NA-	-NA-
	ial Fire Protection System for ection of special Risks, if any:	-NA-	-NA-	-NA-

Accordingly, the fire protection systems provided in the building were tested/ checked

randomly and found in working condition at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures required stipulated in Director of Education Circular, the FSC issued vide letter no. F.6/DFS/MS/2022/School/WZ/619 dated 07.06.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Designation ADO(Rohini)

;

DCFO/ 162-NC

Dated 2 G o G 25 CFo

Dinector

Fi lette is fort up for Kind Permal and Sup Pos