



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/5
आज़ादी का
अमृत महोत्सव

019

No. F6/DFS/MS/School/2025/NDZ/ 707

Dated: 09/09/2025

To,

The Principal,
Sagar Public School,
H.No.101, Block Harijan Basti,
Gharoli Vistar,
Delhi - 110096.

Subject: - Regarding issuance of Fire Safety Certificate in r/o Sagar Public School located at H.No.101, Block Harijan Basti, Gharoli Vistar, Delhi - 110096.


Sir,

Please refer to your outdoor dairy No.4481 dated 04/08/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 19/08/2025 in the presence of Mr. Kamal Singh (Owner) and observed that **the shortcoming has still not complied** with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2025/263 dated 22/04/2025 (copy overleaf).

In view of above, **the application for issuance of Fire Safety Certificate is rejected.** The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclose as above


6/9/2025
VIRENDRA SINGH
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
o/c
W

Copy to: -

1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, New Delhi-110002.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

575
आजादी का
अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2025/263

Dated: 22/04/2025

To,

The Principal,
Sagar Public School,
H. No. 101, C - Block,
Harijan Basti, Gharoli Vistar,
Delhi - 110096.

Subject: - Regarding grant of Fire Safety Certificate in r/o Sagar Public School located at H. No. 101, C - Block, Harijan Basti, Gharoli Vistar, Delhi - 110096.

Sir,

This has a reference to your Outdoor Diary No. 120 dated 02/04/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 12/04/2025 in the presence of Mrs. Hemlata (Principal) and observed that building comprised of ground plus one upper floor.

Following shortcomings were observed during time of inspection:

1. Single staircase of width 0.85 meter is provided second fire exit of width 0.95 mtr. found removed.
2. All fire extinguishers found empty.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

1. The Director of Education, East Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi - 110092.