

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/School/SZ/2025/1333

Dated: 20/11/2025

FIRE SAFETY CERTIFICATE

Certified that Sanatan Shishu Gyan Mandir located at T-137, Baljeet Nagar, New Delhi- 110008, running at ground plus one upper floor in a building comprised of ground plus two upper floors (2nd floor used for Temple storage), was granted Fire Safety Certificate vide letter No. F.6/DFS/MS/School/SZ/2022/1246 dated 17.11.2022. The school building was reinspected by the officer concerned of this department on dated 06.11.2025 in the presence of Mrs. Poonam Bassi, principal of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Directorate of Education circular No. F.16/Estate/CC/FireSafety/2011/3298 to 3398 dated 01.03.2011 and that the building/premises (ground & first floor only) is fit for occupancy class "Educational Building" w.e.f. 20 11 2025 for a period of three years, subject to compliance of the under mentioned conditions.

Issued on 20 11 2025 at New Delhi by.

(A. K. Malik) Dy. Chief Fire Officer

Copy to: -

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi- 54.

2. The Principal, Sanatan Shishu Gyan Mandir at T-137, Baljeet Nagar, New Delhi- 110008

Conditions for the Validity of Fire Safety Certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. Any loss of life or property due to non-functional of fire safety measures shall be at the risk & responsibility of the management.

3. The trained firefighting staffs should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building

5. This fire safety certificate may not be treated in any case for regularization of

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form "J" [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry. The form is available on www.dfs.delhigovt.nic.in.

8. All the means of escapes /exits shall not be locked/blocked at any time for safe evacuation of the occupants in case of emergency.

INSPECTION REPORT

1. Name & address of the building

Sanatan Shishu Gyan Mandir at T-137, Baljeet Nagar, New

Delhi- 110008

2. Type of Occupancy

Educational

3. Building Composition

The said school building comprised of ground plus two upper floors but the school running at ground and first floor only.

Renewal

4. Type of Case 5. Details of previous NOC

6. Fire Safety directives letter No

F.6/DFS/MS/School/SZ/2022/1246 dated 17.11.2022 Education circular No. 3298 to 3398 dated 01-03-2011

7. Date of inspection

06.11.2025

8. Name of the Inspecting Officers

R.K. Yadav, Asstt. Div. Officer (SRD)

9. Name and designation of officers

from the building side

Mrs. Poonam Bassi, principal

9. Year of Construction

Sr. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement as per FSC dt. 17.11.2022	Provided at site	Remarks MR/NMR
1	Access to building			
	Road width	06 mts	Provided	MR
	Gate width	05 mts	Provided	MR
	Width of internal road	N/A	N/A	N/A
2	Number, Width, Type & Arrangement	of Exits	- Falls 1 1- 1- 1-	r Frau Y
	a. Number of staircases		T	Control of the Contro
	Upper Floors	02	02	MR
	Basements	N/A	N/A	N/A
	b. Width of staircases		The part of the pa	1071
	Upper Floors	1.50 m & 0.75 mt	1.10 mts & 0.90 mt.	MR, old case
	Basements	N/A	N/A	N/A
	c. Protection of exits		Alexand Lagrania	
	Fire check door	N/A	N/A	N/A
	Pressurization	N/A	N/A	. N/A
	e. No. of continuous staircases to terrace	N/A	N/A	N/A
×	g. Width of Corridor	N/A	N/A	N/A
	h. Door \$ize	Old Case	Provided (0.87 mt)	MR, old case
3	Compartmentation.	A S DOS	And the same of	2
	Fire check door Sealing of electrical shafts	N/A	N/A	N/A
		N/A	N/A	N/A
	 Fire Rating of shaft door 	N/A	N/A	N/A
	Water Curtain	N/A	N/A	N/A
	Fire Dampers	N/A	N/A	N/A
4	Smoke Management System.		V	
	Basements	30 a/c per hour(NA)	N/A	N/A
	Upper floors	12 a/c per hour	Natural ventilation	MR
5	Fire Extinguishers	e e		
	Total numbers	09 nos. ABC type	Provided	MR
	• Types		Provided	MR
	IS marking	ISI marked	Provided	MR

ΩŔ		١	1
,	1		

	Total numbers on each floor	N/A	N/A	N/A
	Length of hose reel hose	30 m (MA)	N/A	N/A
	Nozzle diameter	5-mm (NA)	N/A	N/A
7	Automatic fire detection and alarmin		ot required	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	Type of detectors	N/A	N/A	N/A
	Location of Main Panel	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A N/A	N/A
	Hooters' Location	N/A	N/A	N/A
0	MOEFA	N/A	N/A	N/A
8	Public Address System.	N/A	N/A	N/A
10	Automatic Sprinkler System	IVA	IN/A	N/A
10	Basement	N/A	N/A	DIVA
	Upper Floor	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants	- 11.4.M	IV/D	N/A
3.8	Size of riser/down-comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	
	Hose Box	N/A	N/A N/A	N/A N/A
2	Yard Hydrants.	976- AU 1 -	IVA	IN/A
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3	Pumping Arrangements	Med Tuleson	Same of A. S. S.	NASS COME &
	Ground Level	7		
	Discharge of main Pump	N/A	N/A	N/A
	➤ Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	➤ Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	➤ Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	➤ Auto Starting/ Manual stopping	N/A	N/A	N/A N/A
	➤ Pump House Access	N/A	N/A	
	Terrace level	IN/A	IN/A	N/A
	 Discharge of pump 	N/A	TOTAL CONTROL OF THE PARTY OF T	N/A
	➤ Head of the pump	N/A	N/A	N/A
	➤ Power Supply		N/A	N/A
	➤ Auto Starting of pump	N/A	N/A	N/A
		N/A	N/A	N/A
	Captive Water Storage for fire fighting Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	N/A	N/A	N/A
	Exit Signage.	Required	Provided	MR
	Provision of Lifts.		Not App	
	Pressurization of Lift Shaft	N/A	N/A	N/A N/A
	Pressurization of Lift lobby	N/A	N/A N/A	N/A
	Communication In lift Car Signature 2 Grounding Switch	N/A N/A	N/A N/A	N/A
	Fireman's Grounding SwitchLift Signage	N/A	N/A	N/A
	Standby power supply	N/A	N/A	N/A

-	> Total Area	N/A	N/A	N/A
	➤ Location	N/A	N/A	N/A
	Fire Control Room		1	
19	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System PanelBatter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 ABC type fire extinguish is provided near elect. Pane	ner MR

The fire protection systems provided in the building were test checked at random and found satisfactory at the time of inspection.

Note: - As per undertaking submitted by school management (placed at C- 24) that the school building comprised of ground plus two upper floors but the school is running at ground and first floor only and the rooms on the second floor are not being used for school purpose. It is used as Temple storage.

In view the deemed compliance of the minimum standards on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter No. F. F.6/DFS/MS/School/SZ/2022/1246 dated 17.11.2022, is recommended to be renewed under the Directorate of Education circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011.

Signature of the Inspecting Office!

Name: - R.K. Yadav Designation: - ADO (SRD)

DO (SW) [18]11]25
RAJINDER ATWAL

DY (SO (SZ)

WALIK

Zincital Director

my.

11/11/25

M. Ofo CER

A.K. MALIK

Am (skd)

6