

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/EH/2025/SZ/ 315

Dated: 02/09/2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Sarvana Bhawan (A unit of Thanigai Murgan Restaurant Pvt. Ltd.) at P- 13/90, Connaught Palace, New Delhi, running at Ground & mezzanine floor only in a building comprised of ground, mezzanine plus two upper floors, was issued FSC by this department vide letter No. F.6/DFS/MS/EH/2022/NDZ/195 dated 05.07.2022. The restaurant building was re-inspected by the officer concerned of this department on dated 25.08.2025 in the presence of Sh. Shakti Singh, and found that the restaurant have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the restaurant building/premises (Ground & mezzanine floor only) is fit for occupancy class Group "D" Assembly Building" w.e.f. 02 09 2025 for a period of three years, accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Issued on 02 09 2025 at New Delhi.

Virendra Singh

Chief Fire Officer

Copy to: -

1. The Commissioner, MCD, Delhi: with a request to ensure the occupancy as detailed above and deviation

2. Online application Id 2025072911984 dated 30.07.2025.

Conditions for the validity of fire safety certificate: -

- 1. The FSC issued only for ground & mezzanine floor only.
- 2. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 3. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 5. The trained staff should be available round the clock.
- 6. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 7. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

INSPECTION REPORT

M/s Sarvana Bhawan (A unit of Thanigai Murgan Restaurant Pvt. 1. Name & address of the building

Ltd.) at P- 13/90, Connaught Palace, New Delhi.

Ground floor, Mezzanine plus two upper floors.

Group D (Assembly) Restaurant running at Gr. & Mezzanine floor only 2. Building is comprised of

3. Type of Occupancy

F.6/DFS/MS/EH/2022/NDZ/195 dated 05.07.2022 4. Type of Case

5. Details of Previous NOC Nil 6. Fire Safety directives letter No 25.08.2025

A.D.O. R.K.Yadav (JKP) 7. Date of inspection

8. Name of Inspecting Officers

9. Name and designation of officers Sh. Shakti Singh

1947 (Old Heritage Building) From the building side MHA Portal ID 2025072911984 dated 30.07.2025

	11. Applicant s letter 1	Applicant's letter No.		Provided at site	Remarks MR/NMR		
	1 100	fire	Requirements		MIKINIM		
	Minimum Standards or	ty 11/R 33					
0.	prevention and fire salety C/RCo						
	Access to building		0(==	Provided	N/A		
•	Road width		06 m	N/A	N/A		
	Road width Gate width		N/A	N/A	1,471		
	C:-torna	l road	N/A				
	Number, Width, Type	& Arrangement	of Exits	A	T		
•	Number, Width, 1) Po	MR					
	a. Number of staircases			03 no's	N/A		
	Number of Standards Upper Floors		02 no's	N/A	N/A		
			N/A				
	Basements			1.58 m, 1.20 m & 0.80 m	MR		
	b. Width of staircases		1.50 m	1.36 III, 1.26 III	N/A		
	Upper Floor		N/A	27/2	I Section 1		
	Basements Soviets			N/A	N/A		
	c. Protection of exits		N/A	N/A	N/A		
	• Fire check door		N/A	N/A			
	Pressurization	iranses to		01	MR		
	d. No. of continuous staircases to terrace		01	01	N/A		
			N/A	N/A	MR		
	e. Width of Corridor		1.50 m	1.20 m & 2.0 m			
	f. Door Size						
3.	Compartmentation			N/A	N/A		
<i>.</i>	Tr. Leak door		N/A	N/A	N/A		
	a 1' - of electr	ical shafts	N/A		N/A		
	n: Dating of ch	aft door	N/A	N/A	N/A		
	arr Curtain		N/A	N/A	N/A		
			N/A	N/A	IN/A		
		etom					
4.	Smoke Management Sy	Journal	N/A	N/A	N/A		
	Basements		Required	Provided	MR		
	 Upper floors 	*	Managemen				
5.	Fire Extinguishers						
٠.	m Iborg is	n restaurant	10 no.'s	Provided	M/R		
	(17) (T-20)(18)		ABC/CO₂	ABC- 04 & Co2- 04	M/R		
	Types IS marking		ISI marked	Provided	M/R		
					1		
6.	First-Aid Hose Reels						
	Total numbers at each floor		1 Nos.	Provided	M/R		
	Length of hose r		30 mtrs	Provided	M/R		
	Nozzle diameter		5 mm	Provided	M/R		

7.	Automatic fire detection and alarming system in restaurant						
	Type of detectors Smoke/Heat	N/A	N/A	N/A			
	Location of Main Panel	N/A	N/A	N/A			
	Location of Repeater Panel	N/A	N/A	N/A			
	Alternate source of power	N/A	N/A	N/A			
	Hooters' Location	N/A	N/A	N/A			
3.	MOEFA	Required	Provided	M/R			
9.	Public Address System	N/A	N/A	N/A			
10.	Automatic Sprinkler System		5/47/E-9/	IVA			
	Basement	N/A	N/A	N/A			
	Upper floors/Restaurant	Required	Provided	MR			
	Sprinkler above false ceiling	N/A	N/A	N/A			
11.	Internal Hydrants						
	Size of riser/down-comer	N/A	N/A	N/A			
	Number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A N/A			
12.	Yard Hydrants						
	Total number of hydrants	N/A	N/A	NIA			
	Hose Box	N/A	N/A	N/A N/A			
13.	Pumping Arrangements		IVA	N/A			
	Ground Level		2 % 1				
	> Discharge of main Pump	N/A	NIA	37/4			
	> Head of Main pump	N/A	N/A	N/A			
	> Number of main pumps	N/A	N/A	N/A			
	> Jockey Pump out put	N/A N/A	N/A	N/A			
	> Jockey pump head	N/A N/A	N/A	N/A			
	➤ Standby Pump out put	N/A	N/A	N/A			
	➤ Standby Pump Head	N/A	N/A	N/A			
	Auto Starting/Manual Stopping	N/A	N/A N/A	N/A			
	➤ Pump House Access	N/A	N/A N/A	N/A N/A			
	Terrace level	Dissipari U					
	➤ Discharge of pump	450 LPM	Provided	M/R			
	> Head of the pump	40 m	Provided	M/R			
	> Power Supply	Required	Provided	M/R			
	➤ Auto Starting of pump	Required	Provided	M/R			
14.	Captive Water Storage for fire-fighting						
	> Underground tank capacity	N/A	N/A	N/A			
	Draw-off connection	N/A	N/A	N/A			
	> Fire service inlet	N/A	N/A	N/A			
	> Access to tank	N/A	N/A	N/A			
	Overhead Tank capacity	10,000 ltrs	Provided	MR			
5.	Exit Signage.	Required	Provided	M/R			
6.	Provision of Lifts						
10.	D winstion of Lift Shaft	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Pressurization of Lift lobby Output Description In lift Car.	N/A	N/A	N/A			
	Communication In lift Car Communication In lift Car	N/A	N/A	N/A			
	Fireman's Grounding Switch	N/A	N/A	N/A			

The shortcomings issued vide letter no F6/DFS/MS/EH/2025/316 dated 28.07.2025 have been rectified. The fire protection systems provided in the building were tested, checked and found functional at the time of inspection...

In view of the deemed compliance of the minimum standards of fire prevention and fire measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/EH/2022/NDZ/195 dated 05.07.2022, is recommended to be renewed under rule 37, of the Delhi Fire Service Rules, 2010.

> Signature of the Inspecting Name: - R.K. Yadav

Designation: - ADO (JKP)

Protection of special Risks, if any:

ADO (FRP)