## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No. F.6/DFS/MS/School/2025/SZ/733

Dated: 17 / 09 / 2025

The Principal,

Sardar Patel Vidya Niketan, Mandi Village, New Delhi 110047

Sub: Regarding issuance of Fire Safety Certificate in r/o Sardar Patel Vidya Niketan, at Mandi Village, New Delhi 110047.

Sir,

This has reference with your letter no nil dated 14/08/2025, received through outdoor diary no 5031 dated 20/08/2025 on the subject cited above. In this connection, this is to inform you that this department has already been visited the premise on 25/08/2025 and issued certain observations / shortcomings vide letter of even no 607 dated 31.07.2025, letter of even no 372 dated 13.05.2025 & letter of even no 150 dated 12.03.2025. (Copy enclosed overleaf for ready ref.)

Further, your application for issuance of FSC can only be considered after getting compliance of the observation in toto.

This is for your information and action at your end.

yours faithfully

(VIRENDRA SINGH) CHIEF FIRE OFFICER

**DELHI FIRE SERVICE** 

Copy to: -

1. The Directorate of Education, Govt. of NCT of Delhi, old Secretariat, New Delhi 110054

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/School/2025/SZ/607

Dated: 31.../2025

The Principal, Sardar Patel Vidya Niketan, Mandi Village, New Delhi 110047

Sub: Regarding issuance of FSC in r/o M/s Sardar Patel Vidya Niketan, located at Mandi Village, New Delhi 110047

Sir,

This has reference to your letter no nil dated 20/05/2025 received through DFS Outdoor diary no 1872 dated 20/05/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 15.07.2025 in the presence of Mrs. Sangeeta Sharma (HOS) to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

- 1. There is addition of First Floor in 4th block, only one staircase is provided having width of 1.50 mtr against the requirement of two staircase having width of 1.50 mtr each.
- Service staircase to access of terrace tank is needed to be provided for verification of terrace tank & terrace pumps.
- 3. Hose reel hose not working.
- 4. Fire fighing pumps are not working.
- 5. Exit signage found removed at some places.

The same observations has already been issued and communicated earlier by this department vide letter of even no 372 dated 13/05/2025 & letter of even no 150 dated 12/03/2025.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

(VIRENDRA SINGH) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 54.

## GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI- 110001

No. F.6/DFS/MS/School/2025/SZ/ | 50

Dated: 12/03../2025

To

The Principal, Sardar Patel Vidya Niketan, Mandi Village, New Delhi 110047

Sub: Regarding issuance of FSC in r/o M/s Sardar Patel Vidya Niketan, located at Mandi Village, New Delhi 110047

Sir,

This has reference to your letter no nil dated 17/02/2025 received through outdoor diary no 12598 dated 18/02/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officer concerned of this department on 07.03.2025 in the presence of Mrs. Sangeeta Sharma (HOS) to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

- 1. There is addition of First Floor in 4th block, only one staircase is provided having width of 1.50 mtr against the requirement of two staircase having width of 1.50 mtr each.
- 2. Service staircase to access of terrace tank is needed to be provided for verification of terrace tank & terrace pumps.
- Hose reel hose not working.
- Fire fighing pumps are not working.
- 5. Exit signage found removed at some places.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier.

Yours faithfully,

DELHI FIRE SERVICE

Copy to:-

1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi 110054.