

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



No.F6/DFS/MS/School/2025/NDZ/194

Dated: 07 / 04 /2025

To,

The Principal, Sharon Public School (Govt. Recognized), D-264, Street No. 11, Laxmi Nagar, Delhi -110092.

Sub.: - Inspection Report in r/o Sharon Public School (Govt. Recongnised), located at D-264, Street No. 11, Laxmi Nagar, Delhi-110092.

Sir,

Please refer to your Outdoor Diary no. 14985 dated 25/03/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 01/04/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/2021/208 dated 13/04/2021 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Enclosed: as above

DELHI FIRE SERVICE

Yours faithfull

Copy to:
1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, New Delhi - 110002.

old seat

959

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No.F6/DFS/MS/School/2021/208

Dated:-13/04/2021

To

The Principal,
 Sharon Public School,
 D-264, Gali no. 11, Laxmi Nagar East, Delhi-92.

Sub: Regarding Renewal of FSC in r/o Sharon Public School, D-264, Gali no. 11, Laxmi Nagar East, Delhi-92.

Sir,

This has reference to email dated 26/03/2021 on the subject cited above. In this regard, it is to inform you that the site was inspected by the officer concerned of this department on 01/04/2021 in the presence of Mrs. Sheetal (Principal) and observed that earlier school was Ground + 02 upper floors but now the school building is comprised of Ground + 02 upper floors and 3rd floor/additional floor also found constructed. Therefore this is a case of additional/alteration and needs to route your application through bldg. deptt. of East MCD. During the inspection following shortcomings were observed:-

- 1. One additional staircase found removed from Ground to 1st floor.
- 2. Hose reel found not functional.
- 3. Fire pump found not functional.

Hence, renewal of Fire Safety Certificate can not be considered at this stage.

Yours faithfully

(Dr. S.K. Tomar) Dy. Chief Fire Officer Delhi Fire Service

مر ا

Copy to:The Director (Education),
Govt. of NCT, Old Sectt.
Delhi - 54.