ERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

C74

5/6/25, 10:57 AM

No F 6/DFS/MS/GH/2025/NDZ/ 366

Dated: 21/05/2025

FIRE SAFETY CERTIFICATE

Issued on 2.1).0.5. 20.25. at New Delhi, by

Aful Garg) Director

elhi Fire Service

Copy to: -

1. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as detailed above.

M/s Shezan Guest House located at 1331, Chitli Qabar Chowk, Jama Masjid, Delhi-110006.

3. MCD Portal, ID No. 2025050507874.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD
portal (https://www.mcdonline.nic.in) along with a copy of this Certificate, six months
prior to its expiry.

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. This FSC is only for total 12 guest rooms at 1st, 2nd & 3rd floor only.

INSPECTION REPORT

Delhi- 110006.

Desidertial (A.)

of Occupancy ding Comprised of

Residential (A-1) (Total 12 Guest Rooms)

: Ground Floor (Commercial use, Mercantile), 1st floor (04 Guest Rooms + Reception), 2nd floor to 3rd floor (04 Guest rooms at each floor), 4th floor (owner residence, not in use as per affidavit dated 19.05.2022)

Renewal for 1st, 2nd and 3rd floor.

type of Case Details of Previous NOC

Fire Safety directives letter No

F6/DFS/MS/GH/NDZ/2022/339 Dated 12/07/2022

Date of inspection

14/05/2025

Name of Inspecting Officer

R.K.Sinha, ADO (BW)

9. Name and designation of officers 10. From the building side

Mr. Faizal Zamal

11. Year of Construction

1983 as per MCD P

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Inspection report	No. 2025050507874 dated 0 Provided at site	5/05/2025	
1.	Access to building	dated 05.07.2022	1 lovided at site	Remarks MR/NMR	
	Road width	Accessible		MOTOR	
	Gate width	NA	5 m	MR	
	Width of internal road		NA	NA	
2.	Number, Width, Type & Arrangeme	nt of Evita	NA	NA	
	Number of staircases				
	Upper Floors	-	,		
	Basements	01	01	MR	
	Width of staircases	NA	NA	NA	
	Upper Floor				
	Basements	0.80 m	0.81 to 0.87 m	MR	
		NA	NA	NA	
	Protection of exits				
	Fire check door	NA	NA	NA	
	Pressurization	NA	NA	NA	
	No. of continuous staircases to terrace	01	01	MR	
	Width of Corridor	NA	NA	NA	
	Door Size	1 m	Provided	MR	
3.	Compartmentation				
	Fire check door	NA	NA	NA	
	Sealing of electrical shafts	NA	NA	NA NA	
	Fire Rating of shaft door	NA	NA	NA	
	Water Curtain	NA	NA	NA NA	
	Fire Dampers	NA	NA	NA	
4.	Smoke Management System				
	Basements	NA	NA	NA	
	Upper floors	Required	Provided	MR	
5.	Fire Extinguishers				
	Total numbers	06 Nos.	Provided	MR	
	Types	ABC/Co2 Type	Provided	MR	
	IS marking	Required	Provided	MR	
6.	First-Aid Hose Reels				
	Total numbers on each floor	01	Provided	MR	
	Length of hose reel hose	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7.	Automatic fire detection and alarming system				
	Type of detectors	СО	Provided	MR	
	Location of Main Panel	Required	Provided at F.F.	MR	
	Location of Repeater Panel	NA	NA	NA	
	Alternate source of power	Required	Provided	MR	

N.29

		70 (Strategic locations	MR	
		Required		NA	
	Hooters' Location	NA	NA	MR	
8.	MOEFA	Required	Provided		
9.	Public Address System Public System		NA	NA	
10.	Automatic Sprinkler System	NA	NA NA	NA	
	Basement	NA	NA NA	NA	
	Upper Floor	NA	NA ·	- 19	
	Sprinkler above false ceiling		27.	NA	
11.	Internal Hydrants	NA	NA NA	NA	
	Size of riser/down-comer	NA	NA NA	NA	
	Number of hydrants per floor	NA	NA	1	
	Hose Box		NA.	NA	
12.	Yard Hydrants Total number of hydrants	NA	NA NA	NA	
	Hose Box	NA	NA		
	Pumping Arrangements				
13.	Ground Level		N/A	NA .	
	Discharge of main Pump	NA	NA NA	NA .	
		NA NA	NA		
	Head of Main pump	274	NA	NA	
	Number of main pumps	NA	NA NA	NA	
	Jockey Pump out put	NA	NA NA	NA	
	Jockey pump head	NA	NA NA	NA	
	Standby Pump out put	NA	NA NA	NA	
	Standby Pump Head	NA	NA NA	NA	
	Auto Starting/Manual Stopping	NA		NA	
	Pump House Access	NA	NA		
	Terrace level				
	Discharge of pump	225 lpm	Provided	MR	
	Head of the pump	40 m	Provided	MR	
	Power Supply	Required	Provided	MR	
	Auto Starting of pump	Required	Provided	MR	
14.	Captive Water Storage for fire fight				
	Underground tank capacity	NA	NA	NA	
		NA .	NA	NA	
	Draw-off connection	NA NA	NA NA	NA	
	Fire service inlet				
	Access to tank	Required '	Provided	MR	
	Overhead Tank capacity	25,00 ltrs	Provided	MR	
15.	Exit Signage.	Required	Provided	MR	
16.	Provision of Lifts.				
	Pressurization of Lift Shaft	NA	. NA	NA	
	Pressurization of Lift lobby	NA NA			
	Communication In lift Car	NA NA	NA NA	NA NA	
			NA	NA	
	Fireman's Grounding Switch	NA	NA	NA	
	Lift Signage	NA	NA	NA	
17.	Standby power supply	Required	Provided	MR	
18.	Refuge Area.				
	Total Area	NA	NI A		
	Location	NA	NA NA	NA	
19.	Fire Control Room	1 2722	NA.	NA	
	Detector System Panel	NA			
	Flow Switch Panel		NA	NA	
	PA System Panel	NA NA	NA	NA	
		NA	NA	NA	
	Battery backup	NA	NA		
			- 14 A	NI	

Protection System for NA Non of special Risks, if any:	NA NA
The fire protection	NA
The fire protection systems provided in the b	Dildin

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the fire safety certificate issued vide letter no. F6/DFS/MS/GH/NDZ/2022/339 dated 12/07/2022 under rule 37 of the Delhi Fire Service Rules, 2010 if agreed. Accordingly DFA is placed on file, please.

Signature of Inspecting Officer

Name: Rajeev Kumar Sinha Designation: ADO/B.W.