



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001**



429

ΔFA+FT

No. F6/DFS/MS/2025/School/NDZ/ 436

Dated: 22/05/2025

To,

Shiv Shakti Public School
90, Lok Vihar Phase – IV,
Delhi - 110094.

Subject: - Reg. Fire Safety Certificate in r/o Shiv Shakti Public School located at 90, Lok Vihar Phase – IV, Delhi - 110094.

Sir,

Please refer to your letter outdoor diary No.1449 dated 07/05/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on 16/05/2025 in the presence of Principal and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/School/NDZ/2025/176 dated 26/03/2025 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,

Enclosed: As above

Copy to: -

1. The Dy. Director of Education, MCD, Civic Centre, Jawahar Lal Nehru Marg, New Delhi - 110002.

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

7/5
गणपति नमो
अमृत मातेस्तु

No. 16/DFS/MS/School/NDZ/2025/116

Dated: 26/03/2025

To,

The Principal,
Shiv Shakti Public School,
90, Lok Vihar Phase - IV,
Shiv Vihar,
Delhi - 110094.

Subject: - Regarding grant of Fire Safety Certificate in r/o Shiv Shakti Public School located at 90, Lok Vihar Phase - IV, Shiv Vihar, Delhi - 110094.

Sir,

This has a reference to your outdoor dairy no.12871 dated 24/02/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 07/03/2025 in the presence of Mr. Ram Mehar (Head Master) and observed that building comprised of ground plus two upper floors.

Following shortcomings were observed during time of inspection:

1. Two staircase of width 1.08 meter & 0.93 meter are provided against requirements of 1.50 meter.
2. All fire extinguishers found empty.
3. First-Aid-Hose Reel provided but found not functional.
4. MOEFA not provided.
5. Fire pump capacity of 220 LPM provided against requirement of 450 LPM.
6. Over head water storage tank of capacity 5,000 ltr. provided against requirement of 10,000 ltr.
7. Exit & floors Signage's not provided at strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR

O/C DELHI FIRE SERVICE

Copy to:-

1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, ...