

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F6/DFS/MS/2025/School/ 336

Dated: 02 /04/2025

FIRE SAFETY CERTIFICATE

Certified that the Shree Ram DAV International School located at Khasra No- 3/2/1, Gali No-9, Block-D, Nathu, Colony, Nathupura, Delhi-110084 comprised of Ground & first floor owned/ occupied by the Shree Ram DAV International School have complied with the fire prevention and safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by the officer concerned of Fire Service on 19.03.2025 in the presence of Sh. Manoj Kumar (Manager) and that the building/premises is fit for occupancy Class "Group B Educational (School)" with effect from02.54 2025 for a period of three years, in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on ... 02 04 2025... at New Delhi

(Atul Garg) Director

Ph:-011-23414000

Copy to: -

1. The Deputy Director of Education, GNCT of Delhi, Zone-VII, District North Lucknow Road, Timarpur, Delhi – 110054.

2. The Manager, Shree Ram DAV International School located at Khasra No- 3/2/1, Gali No- 9, Block-D, Nathu, Colony, Nathupura, Delhi-110084.

Conditions for the validity of Fire Safety Certificate:

1 All the means of escape/entry/exit shall be kept free from any obstruction.

2 All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

3 All the staff members must know the correct method of operation of firefighting system.

4 The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in./wps/wcm/connect/doit fire/FIRE/Home/Forms.

This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-

2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

6 "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building

: Shree Ram Dav International School at Kh. No- 3/2/1, Gali No-9, Block-D,

Nathu Colony, Nathupura, Burari, Delhi-110084.

Type of Occupancy 2.

: Educational

3. Type of Case

: New Case

Composition of building

: Ground & First floor only

Details of previous NOC

: Nil

Fire Safety directives letter No

: NBC Part-4

Date of inspection

: 19.03.2025

Name of the Inspecting Officers 8.

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Manoj Kumar (Maanger)

10. Year of Construction

: 2022

	Minimum Standards on fire prevention and fire safety U/R 33	NBC Part-IV Requirements	Provided at site	Remarks MR/NMR		
	Access to building					
	Road width	06m	06m	MR		
	Gate width	4.50m	4.50m	MR		
	Width of internal road	NA	NA	. NA		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases		THE TOP OF			
	Upper Floors	02	02	MR		
	Basements	NA	NA	NA		
	b. Width of staircases	24.4	and the second second			
	• Upper Floors	1.50m	1.50m	MR		
	Basements	NA	, NA	NA		
	c. Protection of exits	TOTAL	ATT TO A STATE OF			
	Fire check door	NA	NA	NA		
	Pressurization	NA .	NA	NA		
	d. No. of continuous staircases to terrace	02	02	MR		
	e. Width of Corridor	1.50m	1.50m	MR		
	f. Door Size	1.20m	1.20m	MR		
3	Compartmentation.					
	Fire check door	NA	NA	NA		
	Sealing of electrical shafts	NA	NA	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA	NA	NA		
	Fire Dampers	NA	NA	NA		
4	Smoke Management System.					
	Basements	NA	NA	NA		
	• Upper floors	Required	Natural Ventilated	MR		
5	Fire Extinguishers.					
	Total numbers	06nos	08nos	MR		
	• Types	ABC/Co2	ABC-06	MR		
	ISI marking	ISI Marked	Provided	MR		
5	First-Aid Hose Reels.			let a la l		

	The state of the s	14/6		
	Total numbers on each floor	01	Provided	M
	Length of hose reel hose	30m	Provided	М
	Nozzle diameter	5mm	Provided	
7	Automatic fire detection and alarming system.		Tovided	M
	Type of detectors	NA	NA	N.
	Location of Main Panel	NA	NA	N.
	Location of Repeater Panel	NA	NA	N.
	Alternate source of power	NA	NA	
	Hooters' Location	NA	VELINI SI	N/
8	MOEFA	NA NA	NA NA	N/
9	Public Address System.	NA NA	NA NA	N/
10	Automatic Sprinkler System.	1111	INA	N/
	Basement	NA	NA NA	
		NA NA	NA NA	N/
	Upper Floor	NA	NA NA	N/
	Sprinkler above false ceiling			18/
11	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	N/
	Number of hydrants per floor	N/A	N/A	N/.
	Hose Box	N/A	N/A	N/
2	Yard Hydrants.			
	Total number of hydrants	NA	NA	N/
	Hose Box	NA	NA	N/
part.				
3	Pumping Arrangements.			
	Ground Level			
	> Discharge of main Pump	·N/A	N/A	N/A
	> Head of Main pump	N/A	N/A	N/A
	> Number of main pumps	***************************************	ENG/PACA	
	> Jockey Pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A	N/A	N/A
	> Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual stopping	N/A	N/A	N/A
	> Pump House Access	N/A	N/A	N/A
	Terrace level			
	Discharge of pump	450 LPM	Provided	MR
	Head of the pump	40m	Provided	MR
	> Power Supply	Required	Provided	MR MR
	➤ Auto Starting of pump	Required	Provided	MK
1	Captive Water Storage for fire fighting.			
	Underground tank capacity	N/A	N/A	N/A
	> Draw-off connection	N/A	N/A	N/A
	➤ Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity			2571000
F	xit Signage	10,000 LTR	Provided	MR
		Required	Provided	MR

	Provision of Lifts.						
ď	 Pressurization of Lift Shaft 	N/A	N/A	N/A			
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch 	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
	Lift Signage	N/A	N/A	N/A			
17	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	> Total Area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	Flow Switch Panel	N/A	N/A	N/A			
	PA System Panel Batter backup	N/A	N/A	N/A			
		N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A			

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition at the time of inspection. The management has complied all the shortcomings issued and communicated by this department vide letter of even no. F6/DFS/MS/2024/School/616 dated 10.09.2024.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as under rule, it is recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer
Name:-C.L. Meena

Designation:- Asst. Div. Officer (RN)

DO (1W)

21/03/202

Dy che (w2)

DCFO/1090-1/10 Dated 27/03/25

22/2/ms

Dineette fr

April RAV

CON ... P.T. O.