



## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No.F.6/DFS/MS/2025/NDZ/1016

Dated: 19 /08 /2025

## FIRE SAFETY CERTIFICATE

Certified that the Shri Ram Bal Bharti School located at Sewa Dham Marg Mandoli, Shahdara, Delhi-110093, building comprised of Ground floor only owned / occupied by Shri Ram Bal Bharti School, was issued FSC vide letter No. F6/DFS/MS/2022/NDZ/1001 Dated 13/09/2022. The school building was re-inspected by the officer concerned of this department on 25/07/2025 in presence of Sh. Dheeraj Ahuja and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with Circular No. F16/Estate/CC/Fire Safety/2011/3298-3398 Dated 01/03/2011 issued by Director of Education and the building is fit for occupancy class "Educational" (Group-B) with effect from 19/08/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010.

Issued on 1908 2025 at New Delhi by.

(VIRENDRA SINGH) CHIEF FIRE OFFICER.

olca

Copy to :-

- 1. The Principal, Shri Ram Bal Bharti School, Sewa Dham Margm Mandoli, Shahdara, Delhi-110093.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi-110054.

## Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided their in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non-functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. "The owner / Occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The from is available on <a href="https://www.dfs.Delhigovt.nic.in"><u>WWW.dfs.Delhigovt.nic.in</u></a>.



## INSPECTION REPORT

1. Name & address of the building: Shri Ram Bal Bharti School, Sewa Dham Marg,

2. Building is comprised of Mandoli, Shahdara, Delhi-110093.

3. Type of Occupancy : Ground Floor only

4. Type of Case : Educational : Renewal

5. Details of previous NOC 6. Fire Safety directives Letter No.: Circular No. 3298-3398 Dated 01/03/2011 : F6/DFS/MS/2022/NDZ/1001 Dated 13/09/2022

7. Date of inspection

8. Name of the Inspecting Officer: A.K. Jaiswal, D.O. (E.D.)

9. Name and designation of Officer

from the building side

S	Applicant's letter No. : Nil da	ated 14/07/2025	and the second			
No	prevention and fire safety U/R 33	D.O.E. Circ. 01/03/2011 Requirements	Provided at Site	Remarks MR/NMR		
1.	Access of building	Requirements				
	Road width	6 mtr	9 mtr	I.m		
	Gate width	N/A	N/A	MR		
	Width of internal road	N/A		N/A		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	Upper floors	N/A	N/A			
0.4	Basements	N/A	N/A	N/A		
A	b. Width of staircases	parantinini	IN/A	N/A		
1	<ul> <li>Upper floors</li> </ul>	N/A	I NIZA	Marsain.		
	Basements	N/A	N/A	N/A		
100	c. Protection of exits	1778	N/A	N/A		
-	• Fire check door					
- 1	Pressurization	N/A	N/A	N/A		
- 13	d. No of continuous staircase to	N/A	N/A	N/A		
-	terrace to	N/A	N/A	N/A		
	e. Width Of Corridor	N/A	Eds			
13	f. Door Size	N/A 1.0 m	N/A	N/A		
3.	Compartmentation	1.0 m	Provided	MR		
		1955	Tale con-			
-	THE CHECK GOOF	N/A	N/A	N/A		
-	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A		
-	Fire Rating of shaft door	N/A	12.00	The state of the s		
-	Water Curtain	N/A		N/A N/A		
	Fire Dampers	- 25	20000	N/A		
	Smoke managements System					
-	Basements	N/A	N/A	NI/A		
	Upper floors  Fire Fire Fire	N/A	NI/A	N/A		
-	Fire Extinguishers		.775	N/A		
	Total numbers	04 nos.	06 nos.	MR		
	• Types	ISI marked ABC/CO <sub>2</sub>	D	MR		
	IS marking	Required	Provided 1	MR		
	of the same		- 2	d,		

MI	V

	First – Aid Hose Reels	. The state of	-	
	Total numbers on each floor	N/A	N/A	N/A
	Length of hose reel hose	N/A	N/A	N/A
	Nozzle diameter	N/A	N/A	N/A
	Automatic fire detection and alarming	g system		
	Type of detector	N/A	N/A	101/0
	Location of Main Panel	N/A	N/A	N/A N/A
	Location of Repeater     Panel	N/A	N/A	N/A
	Alternate source of power	N/A	N/A	N/A
	Hooters' Location	N/A	N/A	N/A
	MOEFA	N/A		
	Public Address System	N/A	N/A N/A	N/A
•	Automatic Sprinkler System		IN/A	N/A
	Basements	N/A	N/A	11/2
	Upper Floor	N/A	N/A	N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
	Internal Hydrants	Level d	172	N/A
	Size of riser/down- comer	Transport	Jan edi	
	Number of hydrants	N/A	N/A	N/A
	per floor	N/A	N/A	N/A
•	Hose Box	N/A	N/A	N/A
•	Yard Hydrants		7,500	IN/A
	Total number of hydrants	N/A	N/A	N/A
	• Hose Box	N/A	N/A	N/A
_	Pumping Arrangements Ground Level		The facility of	IVA
1	<ul><li>Discharge of main pump</li><li>Head of main pump</li></ul>	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	➤ Jockey pump out put	N/A	N/A	N/A
1	Jockey pump head	N/A	N/A	N/A
1	Standby Pump out put	N/A N/A	N/A	N/A
_	Standby Pump Head	N/A	N/A	N/A
_	Auto Staring/Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A N/A	N/A
_	Terrace level		II/A	N/A
1	Discharge of pump	N/A	N/A	N/A
-	Head of the pump	N/A	N/A	N/A
_	> Power supply	N/A	N/A	N/A N/A
_	Auto starting of pump	N/A	N/A	N/A
	Captive water Storage for fire fighting			IV/A
	<ul> <li>Underground tank capacity</li> </ul>	N/A	N/A	N/A
	> Draw of connection	N/A	N/A	N/A
	Fire service inlet Access to tank	N/A	N/A	N/A
	- THE TO THE TO	N/A	N/A	N/A
	overnead Talik capacity	N/A	N/A	N/A
•	Exit Signage.	N/A	N/A	N/A

i

-	-		
	at a	_	-
•	10	_	-
Δ:	radi		
	-	No.	

16.	Provision of Lifts.			Azadi <sub>Ka</sub> Amrit Mahotsav	
	D. D.				
	> Pressurization of Lift Shaft	N/A	N/A	N/A	
	11cssurization of lift lobby	N/A	N/A	N/A	
	Collinionication in 1:4 C	N/A	N/A	N/A	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
17.	Standby power supply	N/A	N/A	N/A	
18.	Refuge Area		1.47.	1.47.	
	➤ Total area	N/A	N/A	N/A	
10	Location	N/A	N/A	N/A	
19.	Fire control room				
	Detector system panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Battery backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, The Fire Safety Certificate issued vide letter no. F6/DFS/MS/2022/NDZ/1001 Dated 13/09/2022 has grant under circular No. 3298-3398 Dated 01/03/2011 is recommended.

y cfo/MS21

Ling of Below

C.FO}

0/8/2025

Principal Directal

Q Fo to Been.

Signature of the Inspecting Officer Name: Ashok Kumar Jaiswal Designation: D.O. (East Division)

F.T. is educal-fil.

Do (20) 18.8.2015

CFO Mug 18/8/1/205

MS