OVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE **CONNAUGHT PLACE: NEW DELHI-110001**

F.6/DFS/MS/CGHS/2025/SZ/ 1050

Dated: 13,06 /2025

To

Sh. Vinod Kumar Gahlot, President, Shriniketan CGHS Ltd, Plot No. 01, Sector-07, Dwarka, New Delhi-110075

Sub: Renewal of Fire Safety Certificate in r/o "Shriniketan CGHS Ltd" situated at Plot No. 01, Sector-07, Dwarka, New Delhi-110075

Sir,

Please refer to your letter received through outdoor diary No. 1835 dated 15.05.2025, on the subject cited above. In this connection, the premise was visited by the officer concerned of this department on 03/06/2025 in the presence of Sh. Raja Ram (Security Guard) to verify the compliance of shortcomings issued vide this office letter No. F.6/DFS/MS/CGHS/2025/SZ/197 dated 29/04/2025 and observed that the shortcomings are not yet complied.

In view of above, application for renewal of fire safety certificate cannot be considered at this stage. You are advised to rectify the shortcomings under intimation to this department for further action.

Yours faithfully





GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

F.6/DFS/MS/CGHS/2025/SZ/ 197 No.

Dated: 29/64 /2025

To

Sh. Vinod Kumar Gahlot, President, Shriniketan CGHS Ltd, Plot No. 01, Sector-07, Dwarka, New Delhi-110075

Renewal of Fire Safety Certificate in r/o "Shriniketan CGHS Ltd" situated at Plot No. 01, Sector-07, Dwarka, New Delhi-110075

Please refer to your letter No. Nil dated 05/04/2025 received through outdoor diary No. Sir, 582 dated 15/04/2025, on the subject cited above. In this connection, the said residential complex was visited by the officer concerned of this department on 23/04/2025 in the presence of Sh. Sanjay Malhotra (Secretary) to verify the compliance of shortcomings issued vide this office letter No. F.6/DFS/MS/CGHS/2025/SZ/24 dated 13/01/2025 and the status of shortcomings observed is as below.

		Present Status
S. No.	Shortcomings issued	Not Complied
1.	Six-meter-wide internal road around the building found encroached.	
2.	The trimming of trees is required for free movement of fire vehicle	Complied
	in case of fire emergency.	Complied
3.	Hose Reels & Hydrant system found non-functional.	Complied
4.	All the pumps at ground level found non-functional.	Complied
5.	Exit signage's & lift signage's found removed.	Compare

In view of above, application for renewal of fire safety certificate cannot be considered at this stage. You are advised to rectify the left-over shortcomings under intimation to this department for further action.

Yours faithfully

1-23414000