



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001**



No.F6/DFS/MS/EH/2025/SZ/ 64/75

Dated: 11/02/2025

To,  
The Joint. Commissioner (Lic.)  
1<sup>st</sup> floor Police Station Defence Colony,  
New Delhi

**Sub:- Regarding Issuance Fire Safety Certificate r/o M/s Shyam Guest House located at 4234,  
Tel Mandi, Pahar Ganj, New Delhi.**

Sir,

With reference to MHA application ID No. 2025011600626 dated 17/01/2025 on the subject cited above. In this connection, this is to inform you that the site was inspected by the officer concerned of this department on dated 06/02/2025 in presence of Mr. Sunil Kumar Behl it was observed that the shortcomings as communicated earlier vide letter no. F.6/DFS/MS/GH/NDZ/2024/751 dated 31/12/2024 have not been complied yet.

In view of above the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire Safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully

Encl. As above

  
(ATUL GARG)  
DIRECTOR  
DELHI FIRE SERVICE

Copy to:-

Mr. Sunil Kumar Behl  
Shyam Guest House located at 4234, Tel Mandi, Pahar Ganj, New Delhi.



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

आग्निदीप  
अग्नि महोत्सव

No. F6/DFS/MS/GH/NDZ/2024/ 751

Dated: 31/12/2024

To

The Joint Commissioner of Police (Licensing),  
1<sup>st</sup> Floor, Police Station Defence Colony,  
New Delhi.

Ref: elt.mcdonline application no. 2024101215589

Sub: Regarding renewal of Fire Safety Certificate in respect of M/s Shyam Guest House  
located at 4234, Tel Mandi, Pahar Ganj, New Delhi.

Sir,

With reference to the elt.mcdonline application no. 2024101215589 on the subject cited above, it is informed that the said guest house was inspected by the officer concerned of this department on. 23.12.2024 in the presence of Mr. Ameer (Manager) and following shortcoming were observed at the time of inspection.

1. Hose reel found non functional.
2. CO detector found non functional.
3. Manual Operated Electrical Fire Alarm (MOEFA) system found non functional.
4. Fire pump found non functional.
5. Guest house was also found running at 4<sup>th</sup> & 5<sup>th</sup> floor though owner has submitted an affidavit dated 05.12.2019 not to use any floor above 3<sup>rd</sup> floor. Closure/sealing of the same shall be ensured by the local authority/licensing authority.

In view of above shortcomings, the application for renewal of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit

Yours faithfully,

(Atul Garg)

Director

Delhi Fire Service

Copy to :-

1. The Executive Engineer (Bldg.), MCD, 9<sup>th</sup> Floor, Dr. SPM Civic Centre, Minto Road, New Delhi-110002. To verify the height of the building under intimation to this department.