



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आज़ादी का
अमृत महोत्सव No.

F6/DFS/MS/2025/School/NDZ/727

Dated: 15/09/2025

To,

The Principal,
Silverline Public School,
S-623, School Block Shakarpur,
Delhi - 110092.

Subject: - Reg. Fire Safety Certificate in r/o Silverline Public School located at S-623, School Block Shakarpur, Delhi - 110092.

Sir,

With reference to your outdoor diary no. 4984 dated 19/08/2025, on the subject cited above, in this connection, it is to inform you that the reply letter has already been issued by this department vide letter no. F6/DFS/MS/School/2012/1220 dated 04/04/2012 (Copy overleaf).

This is to your kind information please.

Yours faithfully,

Encl: As above

[Signature]
13/9/2025

VIRENDRA SINGH
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

ok @

Copy to:-

1. The Principal, Silverline Public School located at S-623, School Block Shakarpur, Delhi - 110092.
2. The Director (Education) 24th floor, Dr. S.P.M. Civic Center, Minto Road, New Delhi-110002.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

Dated 04/04/12

No. F6/DFS/MS/School/2012/1220

To

The Principal,
Silverline Public School
S-623, School Block Shakarpur,
Delhi - 92

Sub: - Regarding issue of NOC from fire safety point of view in r/o Silverline Public School
S-623, School Block Shakarpur, Delhi - 92


Sir,

Please refer to letter dated 29.2.12 on the subject cited above. In this connection this is to inform you that officer concerned of this department has visited the School to ensure the fire safety arrangement in accordance with the rule 33 of the Delhi Fire Service Rules, 2010. At the time of inspection Manager of the school was present and observed that the school building is comprised of ground plus three upper floors only. During the course of inspection, the following points / shortcomings were noticed:-

1. Two Co2 type 2.5 kg capacity or two ABC type fire extinguisher with ISI mark were not found provided for every 300 square meters of covered area or part there of each floor level.
2. Hose reel is not found provided at each floor level.
3. Fire pump having 450 liters per minute out put at 40 meters head is not found provided at terrace.
4. Over head water storage tank 10,000 ltrs capacity is not found provided at terrace.
5. Exit signs are not found provided.

In view of above, the fire safety certificate can not be issued at this stage.

Yours faithfully


Dy. Chief Fire Officer
Delhi Fire Service

etc Shugh



Copy to:-

The Joint Director of Education
(Land & Estate)
Directorate of Education,
Lucknow Road, Delhi -54.