



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No.

F.6/DFS/MS/School/2025/SZ 487

Dated: 06 / 06 /2025

To

Ms. Jyotsna Jain (Principal), South Delhi Public School. D- Block, Defence Colony, New Delhi-110024

Renewal of Fire Safety Certificate in r/o South Delhi Public School located at D-Block, Defence Colony, New Delhi-110024

Sir,

Please refer to your letter No. SDPS/FSC/2024(04) dated 25/04/2025 received through outdoor diary No. 1085 dated 28/04/2025, on the subject cited above. In this connection, it is to inform you that the above said premise was visited by the officer concerned of this department on 23/05/2025 in your presence to see the compliance of the shortcomings issued vide this office letter No. F6/DFS/MS/School/SZ/2022/719 dated 25/11/2022 and found that the shortcomings are still not fully complied.

In view of above, application for renewal of fire safety certificate is rejected. You are requested to rectify the shortcomings under intimation to this department for further action.

Yours faithfully,

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to: -

1. The Dy. Director of Education, Govt. of NCT of Delhi, Distt. South, Block-C, Defence Colony, New Delhi-110024

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

र्गा पुष्

No.F6/DFS/MS/School/SZ/2022/ 719

Dated:

25/11/2022

To

The Principal,
South Delhi Public School,
D- Block, Defence Colony, New Delhi-24.

Sub:- Regarding renewal of Fire Safety Certificate in respect of South Delhi Public School located at D- Block, Defence Colony, New Delhi-24.

Sir,

This has reference to outdoor diary no. 5776 dated 16.09.2022 on the subject cited above. it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 14.11.2022 in the presence of Mr. B.S. Rana (Admin Officer) and it was observed that the building is comprised of ground + 2 upper floors. During the inspection following shortcomings were observed:-

- 1. An additional staircase is required of width 1.50 mtrs.
- 2. First aid hose reels found non function.
- 3. Fire pump found non function.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(Sunil Chawdhary)

Dy. Chief Fire Officer Delhi Fire Service

Copy to:-.

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.