Dated: 03/09/2025



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



No. F.6/DFS/MS/School/2025/SZ/ 1094

FIRE SAFETY CERTIFICATE

Certified that the building of **St. Joan's Convent School** Opp, JLN Stadium, Behind Mehar Chand Market, Lodhi Road Complex, New Delhi–110003 (School ID: 1719133), comprised of **Basement, Ground + 01 upper floor only**, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2022/SZ/915 dated 29/08/2022. The premise was re-inspected by the officer concerned of this department on 19/08/2025 in the presence of Mr. Rajan Sharma (Administrator) and found that said premises have complied with the fire prevention and fire safety requirements in accordance with Director of Education Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 and that the school building is fit for occupancy class "Educational Group B" with effect from 63/09/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>63/69/2025</u> at New Delhi by

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to: -

- 1. Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054
- 2. Principal, St. Joan's Convent School, Opp. JLN Stadium, Behind Mehar Chand Market, Lodhi Road Complex, New Delhi-110003

Conditions for the validity of Fire Safety Certificate: -

- 1. The basement shall be used strictly in accordance with BBL and not for school activities.
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire-fighting system.
- 5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this certificate, prior to its expiry.
- 7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

N-18

1.	Name & address of the building	ON REPORT	nvon4 C 1			
		St. Joan's Convent School, Opp. JLN Stadium, Behind Mehar Chand Market, Lod Road Complex, New Delhi-110003 (School ID: 1719133)				
2	The state of the s					
2.	Type of Occupancy	Educational (Group B)				
3.	Building Comprised of	Basement, Ground & 1st floor only				
4.	Type of Case	Renewal				
5.	Details of previous NOC No.	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5				
6.	Fire Safety directives Letter No.	F.6/DFS/MS/School/2022/SZ/915 Dt. 29/08/202				
7.	Date of inspection	As per DOE Circular dated 01/03/2011 19/08/2025				
8.	Name of the Inspecting Officer					
9.	Name and designation of Officer	ADO (SJ)				
	from the building side	Mr. Rajan Sharma (Administrator)				
10.	Year of Construction	2004				
11.	Applicant's letter No.	No. Nil dated 07/08/2025 received through				
	PP-round & lotter 140.					
S.	Minimum standards on fire	outdoor diary No. 4681 dated 08/08/2025 Old NOC Provided at site Remark				
No.	prevention and fire safety U/R 33	Requirements	Provided at site	Remark MR/NM		
1.	Access of building	_ additioned	A V	IVIIVINIV		
	Road width	Accessible	06 mtr	MR		
	Gate width	N/A	N/A			
	 Width of internal road 	N/A	N/A	N/A		
2.	Number, width, Type & Arrangement		IN/A	N/A		
	a. Number of staircases					
	Upper floors	02.11				
	Basements	02 Nos 02 Nos	02 Nos	MR		
	b. Width of staircases	02 NOS	02 Nos	MR		
	Upper floors	1.5m / 0.75m	1.52 0.1.40			
	Basements	1.5m / 0.75m	1.53m & 1.40m	MR		
	c. Protection of exits	1.3III / 0.73III	1.05m & 1.35m	MR		
	Fire check door	NI/A				
	Pressurization	N/A N/A	N/A	N/A		
	d. No of continuous staircase to terrace	N/A N/A	N/A	N/A		
	e. Width of Corridor		N/A	N/A		
	f. Door Size	N/A	N/A	N/A		
3.	Compartmentation	1.0 mtr	1.0 mtr	MR		
٦.	5 St. 14 ST. 15 SHIP OF STREET AND ADDRESS OF STREET	****** T	*			
	Fire check door Seeling of electrical chafts	N/A	N/A	N/A		
	Sealing of electrical shaftsFire Rating of shaft door	N/A N/A	N/A	N/A		
	Water Curtain	N/A N/A	N/A · N/A	N/A		
	Water Curtain Fire Dampers	N/A	N/A N/A	N/A		
4.	Smoke Managements System	- 114	IVA	N/A		
70	Basements	30 ACPH	Exhaust Fans	1		
	Upper floors	N/A	N/A	MR N/A		
5.	Fire Extinguishers		11/17	IN/A		
٥.	Total numbers	08 Nos	10 Nos	MD		
		ABC & CO ₂	ABC & CO ₂	MR MR		
	Iypes ISI marking	ISI Marked	ISI Marked	MR		
	First-Aid Hose Reels		*	IVIK		
6.	Total numbers on each floor	N/A	One	N/A		
		N/A	30m	N/A N/A		
	 Length of hose reel hose 	N/A	5mm	19500.5000		
	Nozzle diameter	TWEE	Juni	N/A		



N-19

7.	Automatic fire detection and also					
	Automatic fire detection and alarming system • Type of detector					
	- JPC OI delector	N/A	N/A	N/A		
	Location of Main Panel Location of Panel	N/A	N/A	N/A		
	Location of Repeater Panel Alternate seements.	N/A	N/A	N/A		
	Alternate source of power Hooters' Location	N/A	N/A	N/A		
8.	MOEFA Location	N/A	N/A			
9.	Public Address System	N/A	Provided	N/A		
10.	Automatic Section	N/A	N/A	N/A		
	Automatic Sprinkler System		IN/A	N/A		
	Basements	Required	Dec. 11.1	_		
	• Upper Floor	N/A	Provided	MR		
11.	Sprinkler above false ceiling Internal Living	N/A	N/A	N/A		
11.	internal Hydrants	IWA	N/A	N/A		
	Size of riser/down- comer	N. V. Ph.				
	Number of hydrants per floor	N/A	N/A	N/A		
	TOSE BOY	N/A	N/A	N/A		
12.	Yard Hydrants	N/A	N/A	N/A		
	Total number of hydrants		11	INA		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements	N/A	N/A	N/A		
	Ground Level			1,771		
	Discharge of :					
	Discharge of main pumpHead of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A N/A		
	Jockey pump out put	N/A	N/A	N/A		
	> Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A N/A	N/A	N/A		
	Auto Staring/Manual stopping	N/A N/A	N/A	N/A		
	Pump House Access	N/A	N/A N/A	N/A		
	Terrace level		N/A	N/A		
	Discharge of pump	450 LPM	Provided) m		
	Head of the pump	40 mtr	Provided	MR		
	Power supply	Required	Provided	MR		
	Auto starting of pump	Required	Provided	MR		
14.	Captive water storage for firefighting	rioquirou	Tiovided	MR		
	Underground tank capacity	N/A	N/A	77/4		
	> Draw of connection	N/A		N/A		
	Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity		N/A	N/A		
15.	Exit Signage	10,000 ltr	10,000 ltr	MR		
M124 00	Provision of Lifts	Required	Provided	MR		
16.		× 774		1		
	> Pressurization of Lift Shaft	N/A	N/A	N/A		
	Pressurization of lift lobby	N/A	N/A	. N/A		
	Communication in lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	Lift Signage	N/A	N/A	N/A		
	Standby Power Supply	N/A	N/A	· N/A		
17.						
17.						
17. 18.	Refuge Area > Total area	N/A	N/A	N/A		

19.	Fire Control Room		9	
k. '	Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection. The shortcomings communicated by this department vide letter No. F.6/DFS/MS/School/2025/SZ/468 dated 30/05/2025 have been complied, from fire safety point of view and the basement floor was found vacant at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under DOE circular dated 01/03/2011, the fire safety certificate issued vide letter No. F.6/DFS/MS/School/2022/SZ/915 dated 29/08/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

DO (\$D)

27 81 3025

Principal Director

CFO L

er 8/28/23

29181 200

Men. 8. W

P.T.0