

C/367

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001**

No.F6/DFS/MS/NDZ/2025/ 150

Dated: 07/04/2025

To

Authorized Signatory,
Statesman House at 148, Barakhamba Road,
New Delhi.

Sub: Regarding issuance of Fire Safety Certificate (FSC) in r/o Statesman House at 148, Barakhamba Road, New Delhi.


Sir,

This has a reference to your letter no. FM/AA/SH/923 dated 10.03.2025, on the subject cited above. In this regard, this is to inform you that the site was inspected by the officers concerned of this department on 25/03/2025 in the presence of Sh. Alam (Estate Manager) from building side and following shortcomings were observed:

1. Fire check door found removed in basement near lift.
2. Sealing of electrical shafts/opening not done properly.
3. MCP found nonfunctional.
4. Pressurization or naturally ventilation is required in main staircase as open window has been sealed by glass.

In view of above, the case is rejected with a request to rectify the above shortcomings immediately. Further, the occupancy of building /premises in absence requisite fire & life safety arrangements shall be at the risk and liability of the owner/occupier. The statutory/licensing authority may take suitable action as deemed fit.

Yours faithfully



(Virendra Singh)
Chief Fire Officer
01123414333



Copy to :

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.