



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110 001



No. F.6/DFS/MS/WZ/EH/2025/335

Dated: 11/08/2025

To,

Mr. Sandeep Joshi,
House No.A-24 Shyam Vihar,
Phase-2 Najafgarg, Dindapur,
New Delhi-110043.

Sub: Renewal of FSC in r/o M/s Tata Starbucks Pvt. Ltd. located at upper ground floor, Plot No.25, North West Avenue Club Road, Punjabi Bagh, New Delhi-110026.

Sir,

This is refer to online application no. 2025071311312 dated 13.07.2025, received in this department on the subject cited above. The premise was inspected by the concern nominated authority of this department on **26.07.2025**, in presence of **Mrs. Deepika (Store Manager)** to ascertain the availability and operability of the fire prevention and fire safety measures. Your request for **renewal of FSC is rejected** under sub rule (3) of Rule 37 of DFS Rules-2010 due to following reason:

1. Smoke management system is not provided.
2. Hoses & branch found missing from hose box.
3. Pump house/pumps are now common with Juri Restaurant instead of standalone fire protection system for restaurant in last renewal. Therefore, clarification is required on control of fire protection system.
4. 5000 ltrs Over Head water captive tank provided against the required capacity of 10,000 ltrs.

In this regard as stipulated in sub Rule 37 of DFS Rules, 2010 you may apply with a fresh application for renewal of fire safety certificate under sub-rule (2) on Form "J" /MCD Portal with compliance of above shortcomings. The web links for DFS Act-2007/ Rules 2010 & Form "J" are as under:

http://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/htt
p://www.delhi.gov.in/wps/wcm/connect/doi_fire/FIRE/Home/Forms

Yours faithfully


(Virendra Singh)
Chief Fire Officer


Copy To:-

1. MCD Portal Id- 2025071311312 dated 13.07.2025.