

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

No.F.6/DFS/MS/School/2025/SZ/ 249

Dated: 18 03 2025

FIRE SAFETY CERTIFICATE

Certified that the Tiara International Public School running at ground, first & second floor in a building comprised of ground plus three upper floors (3rd floor used for owner residence) located at D-5, Bhagwati Vihar, Uttam Nagar, New Delhi-110059, owned/occupied by Tiara International Public School, was issued FSC by this department vide letter No. F.6/DFS/MS/School/2022/SZ/126 dated 08.02.2022. The School building was re-inspected by the officer concerned of this department on 07.03.2025 in the presence of Sh. Pritam Singh (Manager), and found that School building have deemed complied the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises (ground plus two upper floors) is fit for occupancy class "Educational" w.e.f. 18 03 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed as below.

Issued on 18 03 2025 at New Delhi by.

Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

2. The Principal, Tiara International Public School at D-5, Bhagwati Vihar, Uttam Nagar, New Delhi-110059

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

15

INSPECTION REPORT

1. Name & address of the building

Tiara International Public School, D-5, Bhagwati Vihar,

Uttam Nagar, New Delhi-110059.

2. Building is comprised of

: G+3 upper floors but school is running at ground plus two upper floors & 3rd floor is being used for residence of owner.

: Educational

4. Type of Case

: Renewal

5. Details of Previous FSC letter

F.6/DFS/MS/School/2022/SZ/126 dated 08.02.2022

6. Fire Safety direction letter No

N/A

7. Date of Inspection

3. Type of Occupancy

07.03.2025

8. Name of the Inspecting officers

ADO R.K. Yadav

9. Name and designation of Officer:

From the building side

Sh. Pritam Singh (Manager)

10. Year of Construction

Before 2009

11. Applicant's letter No

TIPS/F-Safety/New2025 dated 08.02.2025

o.	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR		
	Access to building					
	Road width	06 m.	Provided	MR		
	Gate width	N/A	N/A	N/A		
	Width of internal road	N/A	N/A	N/A		
_	Number, Width, Type and Arrangement of Exits					
	a. Number of Staircases					
	Upper Floor	02 Nos.	02 Nos.	MR		
	Basement	N/A	N/A	N/A		
	B. Width of Staircases		1 (0 8 1 25)/	MR		
	Upper Floor	1.50 & .75 m	1.60 & 1.25 M	N/A		
	Basement	N/A	N/A	IVA		
	c. Protection of exits		N/A	N/A		
	Fire check door	N/A	N/A	N/A		
	Pressurization	N/A	N/A			
	d. No. of continuous staircases to	Required	Provided	MR		
	terrace	1.5 m.	4.30 m.	MR		
	e. Width of Corridor f. Door Size	1 m	.90 m	MR old existing bld		
3	Compartmentation.					
761 1000-		N/A	N/A	N/A		
	Fire check door Falsetrical shafts	N/A	N/A	N/A		
	 Sealing of electrical shafts Fire rating of shaft door 	N/A	N/A	N/A		
	• Water curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4	Smoke Management System.					
91	nment	N/A	N/A	N/A		
5.	Basement Upper floor	Required	Natural Ventilation	MR		
	To disquishers					
_	Total numbers	08 nos.	Provided	MR		
	• Types	ABC /CO ₂	ABC /CO ₂	MR		
	IS marking	IS I marked	ISI marked	MR		

1/6

6	First-aid-Hose Reels.				
	* Total numbers of each floor	01 Nos.	Provided	MR	
	 Length of hose reel hose 	30 mtr.	Provided	MR	
	Nozzle diameter	05 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	Type of detectors	N/A	N/A	N/A	
	 Location of main panel 	N/A	N/A	N/A	
	 Location of repeater panel 	N/A	N/A	N/A	
	 Alternate source of power 	N/A	N/A	N/A	
	Hooter's location	N/A	N/A	N/A	
8	MOEFA	N/A	N/A	N/A	
9	Public address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.				
	Basement	N/A	N/A	N/A	
	upper floor	N/A	N/A	N/A	
	 sprinkler above false ceiling 	N/A	N/A	N/A	
11	Internal Hydrants				
	size of riser/down-comer	N/A	N/A	N/A	
	 Number of hydrants per floor 	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
2	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
3	Pumping Arrangements.				
	Ground Level				
	Discharge of main Pump	N/A	N/A	27/4	
	➤ Head of Main Pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	> Jockey pump out put	N/A	75 NO. 200 NO.	N/A	
	> Jockey pump head	N/A	N/A	N/A	
	> Standby pump out put	N/A	N/A	N/A	
	Standby pump Head	N/A	N/A	N/A	
	➤ Auto Starting /Manual stopping	N/A N/A	N/A	N/A	
	> Pump House Access		N/A	N/A	
	Terrace Level	N/A	N/A	N/A	
	> Discharge of pump	450 Y D) 4			
	> Head of the Pump	450 LPM	Provided	MR	
	> Power supply	40 M	Provided	MR	
	> Auto Starting of pump	Required	Provided	MR	
4		Required	Provided	MR	
	Captive Water Storage for Fire Fighting.				
	Underground tank capacity	N/A	N/A	N/A	
	> Draw-off connection > Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	Overhead Tonk	100-			
5	Overhead Tank capacity Exit Signage.	10,000 Ltr.	10,000 Ltrs	MR	

NZ

1					
	Provision of Lifts.	1. 4	11.	'	
16	Pressurization of Lift Shaft	N/A	N/A	N/A	
	D 'tion of I ift lobby	N/A	N/A	N/A	
	Pressurization of Lift loopy Communication in lift car	N/A	· N/A	N/A	
-	Firemen's grounding switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
7	Standby power supply	N/A	N/A	N/A	
18	Refuge Area.				
	Total area	N/A	N/A	N/A	
	Location	N/A	N/A	1,77	
9	Fire Control Room				
	The second	N/A	N/A	N/A	
	Detector system panel	N/A	N/A	N/A	
	Flow switch panel	N/A	N/A	N/A	
	PA system panel	N/A	N/A	N/A	
	Battery backup	N/A N/A	N/A	N/A	
	Building Floor Plans	IN/A		N/A	
20	Special Fire Protection systems for protection of special Risks, if any:	N/A	N/A	IN/A	

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - As per undertaking submitted by Manager of school (placed at C-22) the school building comprised of ground plus three upper floors but school running at ground plus two upper floors only.

3rd floor used for owner residence and school building constructed before year 2009.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/School/2022/SZ/126 dated 08.02.2022, renewal under rule 37, of the Delhi Fire Service Rules 2010 is recommended.

Signature of the Inspecting Officer Name- R.K. Yadav

Designation- A.D.O (JKP)

DO (SW)

[] ग्रिअक

Cfo | Wung 2025

Deneiter My

Anymy