



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

No. F.6/DFS/MS/Hotel/2025/SZ/ 21

Dated: 03/07/2025

FIRE SAFETY CERTIFICATE

Certified that M/s Tirupati Buildings & Offices Pvt. Ltd (Including ITC Welcom Hotel) located at Plot No. 3, Sector-10, Dwarka, New Delhi-110075, comprised of 03 Basements, Ground + 12 upper floors, was issued FSC by this department vide letter No. F6/DFS/MS/2022/Hotel/52 Dt. 21/07/2022. The premise was re-inspected by the officers concerned of this department on 25/06/2025 in the presence of Sh. Sunil Kumar Tiwari (Chief Er.) & Sh. Nishant Negi (G.M) and found that the said building/premises is fit for occupancy class "Group A-5" (Hotel Building) with effect from __03 / 67 /2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

1-23414000

Copy to: -

1. The Joint Director Delhi Development Authority, Vikash Sadan, INA, New Delhi-110023

2. The Joint Commissioner of Police, Licensing Unit, First Floor, Police Station Defence

3. Authorized Signatory, M/s Tirupati Buildings & Offices Pvt. Ltd (ITC Welcom Hotel) located at Plot No. 3, Sector-10, Dwarka, New Delhi-110075

Conditions for the validity of Fire Safety Certificate:

- 1. The Addition/alteration work has not been undertaken as of now. However, same shall not be occupied without getting clearance from this department else, the FSC issued shall be withdrawn/cancelled
- 2. All the means of escape/entry/exit shall be kept free from any obstruction.
- 3. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 4. All the staff members must know the correct method of operation of fire-fighting system.
- 5. Basement shall be used strictly in accordance with the BBL.
- 6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in
- Form 'J' [sub rule (1) of rule37] along with a copy of this certificate, prior to its expiry.

N-87

1.	Name & address of the building		dings & Offices Pvt. Ltd	(ITC		
1.	Traine so address of the building	Welcom Hotel) at Plot No. 3, Sector–10, Dwarka, New Delhi–110075				
2.	Type of Occupancy	Residential, Gro	up A- 5			
_	Building Comprised of		round + 12 upper floo	rs,		
3.	Type of Case	Renewal				
4.	Details of previous NOC No.	F6/DFS/MS/2022/Hotel/52 Dt. 21/07/2022				
5.	Fire Safety directives letter No.	F6/DFS/MS/BP/Hotel/2010/919 Dt. 26/03/2010 F6/DFS/MS/BP/Hotel/2016/150 Dt. 30/06/2016 F6/DFS/MS/BP/Hotel/2018/193 Dt. 15/06/2018				
6.	Fire Salety directives retter 1 to					
	= -					
	Date of inspection 25/06/2025					
7.	Name of the Inspecting Officer	DO (SW) & ADO (DWK)				
8.	Name and designation of Officer	Sh. Sunil Kumar Tiwari (Chief Er) &				
9.	Name and designation of Officer	Sh. Nishant Negi (G.M)				
	from the building side Year of Construction	2010, 2018				
10.		No. Nil dated 16/05/2025 received through				
11.	Applicant's letter No.	outdoor diary No. 1849 dated 20/05/2025				
	a di la una atandarda an fire	Old NOC	Provided at site 1	<i>lemark</i>		
S.	Minimum standards on fire prevention and fire safety U/R 33	Requirement	N	IR/NM		
No.	A seem of building					
1.	Access of building • Road width	45 mtr	Provided	MR		
	Gate width	06 mtr	Provided	MR		
	Width of internal road	06 mtr	Provided	MR		
	Number, width, Type & Arrangement	s of exits				
2.	a. Number of staircases	11 =		T . m		
	Upper floors	13 Nos	13 Nos	MR		
	Basements	17 Nos	17nos + Ramp & Escalator	MR		
	b. Width of staircases		12 14 8-1 45m	MR		
	Upper floors	1.25m, 1.5m	1.2m, 1.4m &1.45m	(Old Ca		
	Basements	1.25m, 1.5m	1.2m, 1.4m, 1.45m + Ramps	MR (Old Ca		
	c. Protection of exits					
	Fire check door	Required	Provided	MR		
	Pressurization	Required	Provided	MR		
	d. No of continuous staircase to terrace	08 Nos	Provided	MR		
	e. Width of Corridor	1.80m, 3.0m	Provided	MR		
	f. Door Size (Final Exit)	0.90m x 2.24m	0.90m x 2.24m	MR		
3.	Compartmentation		B 11 1	MD		
	 Fire check door 	Required	Provided	MR MR		
	 Sealing of electrical shafts 	Required	Provided Provided	MR		
	 Fire Rating of shaft door 	2 Hrs.	N/A	N/A		
	Water Curtain	N/A	Provided	MR		
4.	• Fire Dampers	Required	Tiovided	MIC		
, ·	Smoke Managements System	Required	Provided	MR		
	• Basements	Required	Provided	MR		
5.	• Upper floors	Required	and 3000 300 30			
	Fire Extinguishers	10 per floor	Provided	MR		
	• Total numbers	ABC / CO ₂	ABC & CO ₂	MR		
	TypesISI marking	ISI marked	Provided	MR		
	151 marking					
6.	First-Aid Llogo Bools					
6.	First-Aid Hose Reels	03 Nos	Provided	MR		
6.	Total numbers on each floor Length of hose reel hose	03 Nos 30m	Provided 30m 5mm	MR MR		

N-88

1	Type of detector	Heat & Smoke	Provided	100
1	 Location of Main Panel 	Basement	Basement	MR
	Location of Repeater Panel	Required		MR
	Alternate source of power	Required	Basement	MR
	Hooters' Location		Provided	MR
8.	MOEFA	Corridors	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	Required	Provided	MR
		- 5-275		
	Duscincins	Required	Provided	MR
	Upper Floor	Required	Provided	V 100 P-100 P
11.	Sprinkler above false ceiling Internal Hydronia	Required	Provided	MR
11.		roquired	Provided	MR
	 Size of riser/down-comer 	150 mm	D	
	Number of hydrants per floor		Provided	MR
10	11026 BOX	Three	Provided	MR
12.	Yard Hydrants	Required	Provided	MR
	Total number of hydrants			
	Hose Box	8 Nos	Provided	MR
13.	Pumping Arrangements	Required	Provided	
	Ground Level	41		MR
	Discharge of			
	 Discharge of main pump Head of main pump 	2850 LPM	D	
	Trullber of main	90 mtr	Provided	MR
	DOCKEY DIIMP OUT	2 Nos	Provided	MR
	I SOUNCY DIIMN has I	2 x 180	Provided Provided	MR
	Stalldby Pump and	LPM	riovided	MR
	Juliuny Pilme II	90 mtr	Provided	
	Auto Staring/Manual stopping Pump House Access	2850 LPM	Provided	MR
	Trouse Access	90 mtr	Provided	MR
	Terrace level	Required Required	Provided	MR MR
	Discharge of pump	required	Provided	MR
	Head of the pump	950 LPM		IVIIV
	Power supply	30 mtr	Provided	MR
	Auto starting	Required	Provided	MR
14.	Captive water St	Required	Provided	MR
	Captive water Storage for fire fightin Underground	g	Provided	MR
	i Sioulia tank	2,00,000 Lts		MIK
	Draw of connection Fire service inlet	Required	Provided	MD
	Access to tople	Required	Provided	MR MR
15	Uverhead T.	Required	Provided	MR
16.		20 000 ltm	Provided	MR
10.	Provision of Lifts (Used by	Required	Provided	MR
			Provided	MR
	Pressurization of lift lobby	Required	Provid	
	Communication .	Required	Provided Provided in basement	MR
	Communication in lift Car Fireman's Grounding Switch Lift Signage	Pagu!	only	MR
	► Lift Signage	Required	Provided	(Old cas
17.	Standby Power Supply	Required	Provided	MR MR
18.	Refuge Area	Required Required	Provided	MR
	P Total	required	Provided (DG Set)	MR
	Total area	Required		
	> Location	Required Required	Provided	MR
		2000	Provided	

m Le

N-89

19.	Fire Control Room			
	 Detector system panel Flow Switch Panel PA System Panel Battery backup Building Floor Plans 	Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
		Required	Provided	MR
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	CO ₂ Fire Extinguishers provided near electric panels		MR

Note: Addn./Alternation approved vide letter No. F.6/DFS/MS/BP/2021/292 dated 25/06/2021 has not yet been carried out. However, we may consider renewal of FSC issued, if agreed please.

The fire protection systems provided in the premises were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/2022/Hotel/52 dated 21/07/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA letter is put up for approval and signature please.

Signature of the Inspecting Officer

Name:

Rajinder Atwal

Designation: DO (SW)

Signature of the Inspecting Officer

Name:

Santosh Kumar

Designation: ADO (DWK)

CFO (HQ)

30 Bl 201

Director

Sir, F.T, letter is putup for your ging. pl

Disuport My